User Guide


3D SCANNER

January 2017

Contents


| 1 | Home Screen Window | 3 |
|---|--|---|
| | To View Recent Projects: | 3 |
| | To Start New Project: | 3 |
| 2 | Calibration Frame Window | |
| | | 4 |
| | To Set Pass through Filter Parameters | 5 |
| | To Start Recording the Frames | 5 |
| | To Go back to Previous Window | 5 |
| | To Proceed with ICP, 3D Reconstruction & Filtering | 5 |
| 3 | Registration and Filtering Window | 6 |
| | To initialize ICP/Registration | 6 |
| | For Filtering and Surface Reconstruction | 6 |
| | To Go back to Previous Window | 6 |
| 4 | Previously Scanned Files | 7 |
| | To Open Mesh File | 7 |
| | To Go back to Previous Window | 7 |

1 Home Screen Window



- To View Recent Projects:
 - 1. Click 'Recent Projects'
 - 2. This will take you to the Recent project window
- To Start New Project:
 - 1. Click 'Start New Project'
 - 2. This will take you to the Calibration Window
 - 3. Visualizer will appear

2 Calibration Frame Window





To Set Pass through Filter Parameters

- 1. To adjust **X** minimum value, move slider from left to right or vice versa
- 2. To adjust X maximum value, move slider from left to right or vice versa
- 3. To adjust Y minimum value, move slider from left to right or vice versa
- 4. To adjust Y maximum value, move slider from left to right or vice versa
- 5. To adjust **Z** minimum value, move slider from left to right or vice versa
- 6. To adjust **Z** maximum value, move slider from left to right or vice versa

• To Start Recording the Frames

- 1. Enter the Name of person in Enter Name field
- 2. Click **RECORD** button
- 3. After clicking Record button, STATUS will change to SCANNING


To Go back to Previous Window

- 1. Click **Home** button on the top left
- 2. This will display Home Screen Window

To Proceed with ICP, 3D Reconstruction & Filtering

- 1. Click **Next** button
- 2. This will display Registration and Filtering Window


3 Registration and Filtering Window



To initialize ICP/Registration

- 1. Enter Name in Name of File field
 - a. *Note: This name should match the name entered in the Calibration Frame Window
- 2. Click Registration to start ICP
 - a. Status at bottom of the window changes to Waiting
 - b. Once the Registration is completed, Status changes to Registration completed
 - c. Results are displayed on the Viewer, located on left
- For Filtering and Surface Reconstruction
 - 1. Select either Grid Projection or Greedy Projection Triangulation
 - 2. Set the Parameter of Statistical Outlier Removal
 - a. Set the Value of Mean (By default this value is set at 50)
 - b. Set the Value of Standard Deviation STD (By default this value is set to 1.50)
 - 3. Click 3D Reconstruction and Filter to start 3D Reconstruction and filtering
 - 4. Status will change to Filtering Started
- To Go back to Previous Window
 - 1. Click **Home** button on the top left
 - 2. This will display Home Screen Window

4 Previously Scanned Files



• To Open Mesh File

- 1. Click **Open Mesh File** to select/view the previously saved mesh file from the pop up dialog
 - a. Result will be displayed on the viewer on left
- 2. Click Open PCD File to select/view the previously saved PCD file from the pop up dialog
 - a. Result will be displayed on the viewer on left

To Go back to Previous Window

- 1. Click **Home** button on the top left
- 2. This will display Home Screen Window