	index	Group	Name EN Reportelement	AIDA IP RG	Standort RG	Standort Bemerkung	Standort Name
0	6	HMI	ADAS ASIA	5-6	5	[Additional information] #1 #2 #3 #4	JAP
2	15	HMI	Listen to AM/FM Radio (Legacy < IDC Android)	5-6	5	[Top5 defects] 904258 [JP][MGU22] no audio after a bus sleep BI5/spor | KW08 > Duplicate to 906683 > 08-In Verification #5 Function not available in Japan #6 #7	JAP
5	34	HMI	Display and operation of PaDi BMW widgets	5-6	4	[MLI] 918697 [jp][mgu22] FireTV stuck on language`s settings BI4/rep | CW09 (SS candidate) > 04-In Progress [Top5 defects] 907516 [JP][MGU22] PaDi does not respond correctly to touch command BI5/hint | CW08 (SS candidate) > 04-In Progress	JAP
6	39	HMI	Display of Legal Disclaimer	5-6	5	[Additional information] #1 #2 #3	JAP

8	51	HMI	Change Audio Sound Settings	5-6	5	[Additional information] #1 #2 #3 #4 #5 #6 #7 #8 #9 no clear explanation which function should be tested. #10 no clear explanation which function should be tested. #11	JAP
11	74	HMI	Play audio via USB	5-6	5	[Top5 defects] 917865 [jp][mgu22] Fast/backward function is not working with USB iAP BI6/repr| CW09 > Duplicate to 896143 > 04-In Progress #5	JAP
12	83	HMI	Augmented Reality Video CID	5-6	5	[Additional information] #1 #2 #3 #4	JAP
17	109	HMI	Display of User Manual	5-6	5	[Top5 defects] 877090　wrong translation "Notes" BI6/rep 　| 　CW04 -> Master 749236 [Additional information] #1 #2 #3	JAP

20	132	HMI	CarPlay	5-6	5	[Top5 defects] 861140 [XMAS][jp][mgu22][CarPlay] Intermediate destination cannot be deleted (google map) BI6/rep | CW02 > 04- In Progress 811558 [JP][MGU22][CarPlay] Fast forward/backward is not possible BI5/rep | CW46 (No SS) > 04-In Progress [Device used for testing] iPhone 11 | SW.: iOS 15.3.1 [Additional information] #1 #2 #3	JAP
21	139	HMI	Charge CE Device Wireless	5-6	5	[Device used for testing] [Additional information]	JAP
22	142	HMI	Charge CE Device via USB	5-6	5	[Device used for testing] [Additional information]	JAP
24	159	HMI	Manage CE Devices (WIFI AP)	5-6	5	[Device used for testing] [Additional information]	JAP
25	166	HMI	Display Check- Control- Message and telltales	5-6	5	[Additional information] #1 #2 #3 #4 #5	JAP
28	185	HMI	E-Call	5-6	5	Takano [Top5 defects] [Additional information]	JAP
32	209	HMI	Date and Time Settings	5-6	5	[Top5 defects] 894957 Weather app date format changes when selected a day. BI6/rep | CW07 #5 #6	JAP

38	243	HMI	Transfer Data from Vehicle to Backend (Last State Call)	5-6	5	Takano [Additional information]	JAP
39	253	HMI	PaDi Remote Control via BMT	5-6	5	[Device used for testing] [Additional information]	JAP
40	257	HMI	FireTV download of content	5	4	[MLI] 947163 [id8][jp][padi]amazon fire tv: login failure and cyclic login loop processes BI5/rep | CW12 [Top5 defects] 858350 [jp][mgu22][PaDi] Keyboard input is not working correctly BI5/rep | CW03 (SS confirmed) > 08-In Verification [Device used for testing]	JAP
41	262	HMI	FireTV Full App Support and Automotive Feature Set	5-6	4	[MLI] 947163 [id8][jp][padi]amazon fire tv: login failure and cyclic login loop processes BI5/rep | CW12 [Top5 defects] 858350 [jp][mgu22][PaDi] Keyboard input is not working correctly BI5/rep | CW03 (SS confirmed) > 08-In Verification [Additional information]	JAP

42	266	HMI	FireTV VoD App and Audio Output	5-6	4	[MLI] 947163 [id8][jp][padi]amazon fire tv: login failure and cyclic login loop processes BI5/rep | CW12 [Top5 defects] 907516 [JP][MGU22] PaDi does not respond correctly to touch command BI5/hint | CW08 (SS candidate) > 04-In Progress 858350 [jp][mgu22][PaDi] Keyboard input is not working correctly BI5/rep | CW03 (SS confirmed) > 08-In Verification[Device used for testing]	JAP
43	272	HMI	Handsfree Telephony in the rear seats	5-6	5	[Top5 defects] 917696 Copy of [jp][mgu22][bmt] Index letter is not shown when scrolling through the same contacts BI6/rep | CW08 (No SS) > 04 In Progress [Device used for testing]	JAP
45	287	HMI	Internet Access via Hotspot	5-6	5	Nagai [Device used for testing] [Additional information]	JAP
46	291	NAV	Map and Navigation Data update ASIA	5-6	5	[Additional information] #1 #2	JAP
47	293	HMI	Display Contacts	5-6	5	[Top5 defects] 907284 [jp][mgu22][bmt] Index letter is not shown when scrolling through the same contacts BI6/rep | CW08 (Master ticket 917696 Copy of [jp][mgu22][bmt] Index letter is not shown when scrolling through the same contacts) > 04-In Progress	JAP
48	301	HMI	Search Contacts	5-6	5	[Device used for testing] [Additional information]	JAP

50						[MLI] 938087[JP][MGU22] not possible to set navigation destination from telephone number search results BI5/repr | KW11 -> 906016 > 04 In Progress > Reproduced 934969 [JP][MGU22] not possible to set navigation destination from contacts BI5/repr | KW11 -> 922817 >08-In Progress (CW14) > Reproduced [Additional information] #1 #2 #3 #4 #5 #6	
	309	NAV	Navigation Destination Input ASIA	5-6	4		JAP
51						[Top5 defects] 740208 [JP][MGU22] corrupted graphic appears when setting a destination BI5/repr | KW35 > 04 In progress > Not reproduced [Additional information] #1 #2 #3	
	322	ENT	Display map ASIA	5-6	5		JAP
52						Takano [Top5 defects] 944124 [MGU22] All ConnectedDrive OAP Apps missing on G70 rack BI4/Repr CW12 883557 [JP][Alexa] Paying media is not switched by speech command with Alexa BI5/Repr CW6 925104 [JP][Weather] Weather app is not selectable BI5/HIgh CW11 941410 [JP] YouTube app is frequently not available BI5/High CW12 (ticket will be created) [JP] Cannot proceed Alexa setup in the page of sign in process BI5/High CW13 ------------------------------------ ------------------------------------ [Additional information]	
	329	HMI	OAP App platform Vehicle-App-Interface Setup	5-6	5		JAP

53	337	HMI	PaDi View and Audio Settings	5-6	5	[Top5 defects] 907516 [JP][MGU22] PaDi does not respond correctly to touch command BI5/hint | CW08 (SS candidate) > 04-In Progress	JAP
54	344	HMI	PaDi RoW CE area (FireTV) bring-up	5-6	4	[MLI] 947163 [id8][jp][padi]amazon fire tv: login failure and cyclic login loop processes BI5/rep | CW12 [Top5 defects] 907516 [JP][MGU22] PaDi does not respond correctly to touch command BI5/hint | CW08 (SS candidate) > 04-In Progress 858350 [jp][mgu22][PaDi] Keyboard input is not working correctly BI5/rep | CW03 (SS confirmed) > 08-In Progress [Device used for testing]	JAP
56	349	NAV	POI Functions ASIA	5-6	5	[Top5 defects] 922665 [JP][MGU22][PU2307] Charge stations search shows no result when online POI is active BI5/repr | KW10 > 04 In Progress > Reproduced 894712 [MAP][JP][CW07] Preview map of POI results not working BI5/spor | KW07 -> 892693 > 08-In Verification > Not reproduced 740208 [JP][MGU22] corrupted graphic appears when setting a destination BI5/repr | KW34 > 04 In Progress > Not reproduced [Additional information] #1 #2	JAP

57	357	NAV	Positioning ASIA	5-6	5	[Top5 defects] 894744 [CW07][JP][POS] CCP drifts in Aqua tunnel (Chiba to Tokyo) BI5/sing｜KW07 > 04 In Progress (Target week CW15) [Additional information] #1 #2 #3	JAP
58	362	HMI	Remote Services	5-6	5	Takano [Additional information]	JAP
59	372	NAV	Manage and Plan Routes ASIA	5-6	5	[Top5 defects] 916693 [JP][MGU22] sort destinations does not work BI5/repr｜KW09 > 08 In verification > not reproduced and ticket will be closed. [Additional information] #1 #2->not available in Japan #3 #4->not available in Japan #5 #6->not available in Japan #7 -> in clarification with FO what	JAP
60	376	HMI	Report service issues via Teleservice	5-6	5	Takano [Additional information] TSBG test currently not available	JAP
61	381	HMI	Manage SMS Messages	5-6	5	[Device used for testing] Galaxy S21 5G iPhone SE iOS 15.3.1 [Additional information] #1 #2 Function not implemented #3 #4 #5	JAP

63			Telephony via customer SIM	5-6	5	[Device used for testing] [Additional information] #1	JAP
	392	HMI					
64			Telephony via customer device	5-6	5	[Top5 defects] 894988 [CW07][JP]outgoing call by voice dial number not possible BI5/spor | CW06 > 04 In Progress 804843 [JP][MGU22] Conference call status is not updated on CID BI6/rep | CW46 > 03 In Analysis [Device used for test]	JAP
	397	HMI					
65			Telephony via second customer device	5-6	5	[Device used for testing] [Additional information] #1	JAP
	405	HMI					
66			Watch TV (Japan)	5-6	5	[Top5 defects] 877250 [MGU22][JP][tv] Focus bar jumps on wrong entry BI6/rep | CW04 > 04-In Progress 878239 [MGU22][JP][tv] Station title`s overlay continues popping up BI6/rep | CW04 > 04-In Progress [Additional information]	JAP
	410	HMI					
67			Traffic Info ASIA	5-6	5	[Top5 defects] 896121 [CW07][JP][TI] No CHM displayed in Traffic widget BI5/high | KW07 > 04 In Progress (Target week CW15) > Reproduced [Additional information] #1 #2 -> function not available in Japan #3-> function not available in Japan #4 #5	JAP
	416	NAV					

68						[Top5 defects] 938980 [JP][speech]voice command "Theatre Screen" not recognized BI6/rep | CW11 878470 1-shot address/ poi search: No search started even dictated search token displayed on top of CID for a moment. BI5/spo | CW04 806111 [CW45][JP][MGU22][Speech] TV station is not recognized via speech BI5/rep | CW45 #5 #6 #7	
	428	HMI	Voice Interface	5-6	5	#8	JAP
69						[Top5 defects] 945208 [JP][MGU22] no route line in Kombi map widget although route guidance is active BI6/spor | KW12 > 04 In Progress 894747 [CW07][JP][GUIDA] Wrong utterance in Japanese at all motorway Junction BI5/repr | KW07 > 04 In Progress [Additional information] #1 HUD not available in KSP	
	443	NAV	Guiding ASIA	5-6	5	#2	JAP