

Matrix orientation:
COL2ROW.
The diodes are soldered with the cathode (stripe) to the row wires (green lines).
In the KMK, specify: diode_orientation = DiodeOrientation.COL2ROW

