

Policy 1: Will dispose of waste in the standardized method. This includes storing it in a cooling pool for a duration of 5 years, mitigating its radiation output. Then place it into a steel lined dry concrete cask for a short period. Finally for a prolonged time it will be deposited into a deep stable underground facility.

Policy 2: Will clean up nuclear waste using standard hazmat suits approved by local and federal government.

Policy 3: Will wear safety goggles approved by local and federal government to reduce eye damage.

Policy 4: Will conduct monthly reports regarding potential hazards and injuries.