

Regulation 1: You must wear eye protection equipment such as goggles

Regulation 2: You are required to use the nuclear standard equipment such as hazmat suits

Regulation 3: Nuclear waste must be properly disposed of into cooling pools for 5-10 years to mitigate radiation. Then move the waste to steel lined concrete dry casks for the interim. Long term it must be stored in a stable deep underground facility.

Regulation 4: You must submit weekly reports regarding all potential facility hazards as well as any incidents that do occur which cause injury and or death to your employees