

Note, the sequence will turn the DAQ back ON and adjust the acquisition time after you Exit the Moller configuration. This is intentional and for monitoring of beam-charge asymmetry during normal running.