One-hot values have a single bit that is a 1 with all other bits being 0. Output a 1 if the input (din) is a one-hot value, and output a 0 otherwise.

Input and Output Signals

- din Input value
- onehot 1 if the input is a one-hot value and 0 otherwise