

TOP VIEW

BOTTOM VIEW





JP1 SOLDERING JUMPER FOR ENABLING OUTPUT1 RESISTOR

JP2 SOLDERING JUMPER FOR ENABLING OUTPUT2 RESISTOR

JP3 SOLDERING JUMPER FOR 2nd OUTPUT PIN. IO1 or IO3

OUT1 IO2

OUT2 IO1 or IO3

FLASH CARD PINS

1012 - DATO

1013 - CMD

1014 - CLK

1015 - DAT3/CD

DALLAS SENSOR

104

RELAY

1016