

We found out that our kernel7.img file is not the right format for our microSD. We decided to change our focus from implementing our system to finding a reliable, consistent bare-metal C compiler, because it is clear that no such service is widely available.

We'll likely need to study the system's hardware architecture in order to see how it boots off of its microSD.