

P 6

M_A

M_0V

M_B

HSI_5V

S_A

S_0V

S_B

HSI_24V

HSI_0V

HSI_0V

A_N

A_P

B_N

B_P

Z_N

Z_P