


1. Read points from .out file




2. Bring the blade origin to the global origin




3. Align blade axis to the global z-axis



4. Rotate around the z-axis to eliminate the current blade pitch



5. Return the blade axis to its original orientation



6. Return the blade origin to its original position

