

Deviation Report

Site: Plant 1

Date of Occurrence: 27 September 2026

During routine monitoring at Plant 1, the storage temperature for Product A, Batch B2409-15, increased above the approved range for approximately 40 minutes.

The excursion was detected by the monitoring system and the temperature was restored to the approved range.

No visible product damage was observed.

Affected Process Parameter: Storage Temperature

Related Product: Product A

Batch Number: B2409-15