

Appendix B - 40 Sitreps of CNS Alpha for duration of 20 days

CNS ALPHA — DAY 1 (01 Mar 26)

--- SITREP 01 | AM | 0800 IST (EF) ---

1. Basic Details

- Name of Ship: CNS Alpha
 - Sitrep No / PCS / Eqpt No: 01/AM/ALPHA/OPS
 - PCS: 082° / 96 NM from Fujairah | Course 110° | Speed 14 kts
-

2. Intelligence Report

ESM

- Emitter 001: S-band long-range air search radar, bearing 192°, strength 8/10 → probable correlation (0.83 confidence). Arleigh Burke Class Destroyer; OSINT indicates USS Mustin (DDG89)
- Emitter 002: AEGIS SPY-1D type emission, bearing 198°, strength 7/10 → probable correlation (0.71). Arleigh Burke Class Destroyer; OSINT indicates USS Rafael Peralta (DDG115)
- Emitter 003: Medium-power navigation radar, bearing 210°, strength 5/10 → possible DDG escort. Arleigh Burke Class Destroyer, unable to identify specifically
- Emitter 004: Intermittent low-power emission, bearing 178°, strength 3/10 → possible littoral combatant. OSINT indicates USS Savannah (LCS28)
- Emitter 005: Civilian radar cluster, bearings 095°–120°, strength 4/10
- Emitter 006: Weak coastal radar pulse, bearing 015°, strength 2/10

Radar

- Total tracks detected: 15
- Merchant vessels: 12
 - VLCC: 5
 - Container: 4
 - Bulk cargo: 3
- Naval contacts:

- 2 large contacts (95–110 km) (likely USS Mustin (DDG89) and USS Savannah (LCS28)
 - 1 medium escort-type track (likely USS Rafael Peralta (DDG115))
- 1 intermittent low-RCS surface contact detected north-west sector

Visual

- Nil significant due haze
 - Distant tanker mast silhouettes visible west bearing
-

3. Fuel Status

- Available – 936 T / 78%
 - Required to make 95% – 204 T / 17%
-

4. A/C State

- Frame No: ALH-01
 - State / Rate: Fully serviceable / 2.2 hrs flown
 - Cleared for: Day/Night Operations
 - Next Insp: 05 Mar 26
 - Any flaws in book log: Nil
-

5. Weather

- Wind: NE 11 kts
 - Swell: 1.2 m
 - Sea State: 3
 - Visibility: 7 km
 - Barometric Pressure: 1012 mb
-

6. Extra Info

- Civil aircraft in ASR: 18
- 2 civilian aircraft observed holding south-west airway junction

- MV density approximately 20% above expected baseline
 - Tanker spacing inconsistent (3–5 NM)
 - No replenishment activity sighted
 - Jet engine noise detected twice bearing 195°–205°
 - No fishing dhow activity north sector
 - Merchant VHF advisory referenced “increased military aviation south sector”
 - Weak AIS lag (~4 min) observed in one VLCC
 - No UAV/drone activity reported
-