
Navigating NETRA for Monitoring Dashboard

STEP 2

PRELIMINARY STEPS FOR GRAPH TO BE VISIBLE


- 1. Create the sensor in Maintenance Allocation / Create Maintenance Plan
- 2. Add Sensor Data For respective sensors in View Or Update Data / Add Sensor Data
- 3. Follow the guide

STEP 3
Click on MONITORING DASHBOARD




STEP 4

Fill The Rquired Options




STEP 5 Select The Required parameters ex. Temprature, Pressure



STEP 6

Click on SUBMIT



STEP 7

Blinking of the graph in red color indicates the crossing of a threshold, i.e., the maximum value assigned.

