1. Description


1.1. Project

Project Name	Nucleo_L4_I2S_AudioDac_v1
Board Name	NUCLEO-L476RG
Generated with:	STM32CubeMX 5.4.0
Date	12/21/2019

1.2. MCU

MCU Series	STM32L4
MCU Line	STM32L4x6
MCU name	STM32L476RGTx
MCU Package	LQFP64
MCU Pin number	64

2. Pinout Configuration




3. Pins Configuration

Pin Number LQFP64	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
1	VBAT	Power		
2	PC13	I/O	GPIO_EXTI13	B1 [Blue PushButton]
3	PC14-OSC32_IN (PC14)	I/O	RCC_OSC32_IN	
4	PC15-OSC32_OUT (PC15)	I/O	RCC_OSC32_OUT	
5	PH0-OSC_IN (PH0) *	I/O	RCC_OSC_IN	
6	PH1-OSC_OUT (PH1) *	I/O	RCC_OSC_OUT	
7	NRST	Reset		
11	PC3	I/O	SAI1_SD_A	
12	VSSA/VREF-	Power		
13	VDDA/VREF+	Power		
16	PA2	I/O	USART2_TX	USART_TX
17	PA3	I/O	USART2_RX	USART_RX
18	VSS	Power		
19	VDD	Power		
21	PA5 **	I/O	GPIO_Output	LD2 [green Led]
29	PB10	I/O	SAI1_SCK_A	
31	VSS	Power		
32	VDD	Power		
46	PA13 (JTMS-SWDIO)	I/O	SYS_JTMS-SWDIO	TMS
47	VSS	Power		
48	VDDUSB	Power		
49	PA14 (JTCK-SWCLK)	I/O	SYS_JTCK-SWCLK	TCK
55	PB3 (JTDO-TRACESWO) *	I/O	SYS_JTDO-SWO	SWO
60	воото	Boot		
61	PB8	I/O	SAI1_MCLK_A	
62	PB9	I/O	SAI1_FS_A	
63	VSS	Power		
64	VDD	Power		

^{**} The pin is affected with an I/O function

^{*} The pin is affected with a peripheral function but no peripheral mode is activated

4. Clock Tree Configuration



Page 4

5. Software Project

5.1. Project Settings

Name	Value	
Project Name	Nucleo_L4_I2S_AudioDac_v1	
Project Folder	C:\Users\toussaij\Documents\STM32dev\Nucleo_L4_I2S_AudioDac_v1	
Toolchain / IDE	STM32CubeIDE	
Firmware Package Name and Version	STM32Cube FW_L4 V1.14.0	

5.2. Code Generation Settings

Name	Value
STM32Cube MCU packages and embedded software	Copy only the necessary library files
Generate peripheral initialization as a pair of '.c/.h' files	No
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	Yes
Set all free pins as analog (to optimize the power	No
consumption)	

6. Power Consumption Calculator report

6.1. Microcontroller Selection

Series	STM32L4
Line	STM32L4x6
мси	STM32L476RGTx
Datasheet	025976_Rev4

6.2. Parameter Selection

Temperature	25
Vdd	3.0

7. IPs and Middleware Configuration 7.1. GPIO

7.2. RCC

Low Speed Clock (LSE): Crystal/Ceramic Resonator

7.2.1. Parameter Settings:

System Parameters:

VDD voltage (V)

Instruction Cache

Prefetch Buffer

Enabled *

Data Cache

Enabled *

Flash Latency(WS) 4 WS (5 CPU cycle)

RCC Parameters:

HSI Calibration Value 16

MSI Calibration Value 0

MSI Auto Calibration Disabled

HSE Startup Timout Value (ms) 100

LSE Startup Timout Value (ms) 5000

Power Parameters:

Power Regulator Voltage Scale Power Regulator Voltage Scale 1

7.3. SAI1

Mode: Master with Master Clock Out

mode: I2S/PCM Protocol 7.3.1. Parameter Settings:

SAI A:

Synchronization Inputs Asynchronous

Basic Parameters

Audio Mode Master Transmit

Output Mode Stereo

Companding Mode No companding mode

SAI SD Line Output Mode Driven

Protocol Parameters

Protocol I2S Standard
Data Size 16 Bits

Number of Slots (only Even Values)

Clock Parameters

Master Clock Divider Enabled
Audio Frequency 192 KHz

Real Audio Frequency 71.428 KHz *
Error between Selected -62.79 % *

2

Advanced Parameters

Fifo Threshold Empty
Output Drive Disabled

7.4. SYS

Debug: Serial Wire

Timebase Source: SysTick

7.5. USART2

Mode: Asynchronous

7.5.1. Parameter Settings:

Basic Parameters:

Baud Rate 115200

Word Length 8 Bits (including Parity)

Parity None Stop Bits 1

Advanced Parameters:

Data Direction Receive and Transmit

Over Sampling 16 Samples
Single Sample Disable

Advanced Features:

Auto Baudrate Disable TX Pin Active Level Inversion Disable Disable **RX Pin Active Level Inversion** Disable Data Inversion TX and RX Pins Swapping Disable Overrun Enable DMA on RX Error Enable MSB First Disable

Nucleo_L4_I2S_A	.udioDac_v1	Project
(Configuration	Report

* User modified value		

8. System Configuration

8.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
RCC	PC14- OSC32_IN (PC14)	RCC_OSC32_IN	n/a	n/a	n/a	
	PC15- OSC32_OU T (PC15)	RCC_OSC32_O UT	n/a	n/a	n/a	
SAI1	PC3	SAI1_SD_A	Alternate Function Push Pull	No pull-up and no pull-down	Low	
	PB10	SAI1_SCK_A	Alternate Function Push Pull	No pull-up and no pull-down	Low	
	PB8	SAI1_MCLK_A	Alternate Function Push Pull	No pull-up and no pull-down	Low	
	PB9	SAI1_FS_A	Alternate Function Push Pull	No pull-up and no pull-down	Low	
SYS	PA13 (JTMS- SWDIO)	SYS_JTMS- SWDIO	n/a	n/a	n/a	TMS
	PA14 (JTCK- SWCLK)	SYS_JTCK- SWCLK	n/a	n/a	n/a	TCK
USART2	PA2	USART2_TX	Alternate Function Push Pull	No pull-up and no pull-down	Very High *	USART_TX
	PA3	USART2_RX	Alternate Function Push Pull	No pull-up and no pull-down	Very High *	USART_RX
Single Mapped Signals	PH0- OSC_IN (PH0)	RCC_OSC_IN	n/a	n/a	n/a	
	PH1- OSC_OUT (PH1)	RCC_OSC_OUT	n/a	n/a	n/a	
	PB3 (JTDO- TRACESWO)	SYS_JTDO- SWO	n/a	n/a	n/a	SWO
GPIO	PC13	GPIO_EXTI13	External Interrupt Mode with Falling edge trigger detection	No pull-up and no pull-down	n/a	B1 [Blue PushButton]
	PA5	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Low	LD2 [green Led]

8.2. DMA configuration

nothing configured in DMA service

8.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority	
Non maskable interrupt	true	0	0	
Hard fault interrupt	true	0	0	
Memory management fault	true	0	0	
Prefetch fault, memory access fault	true	0	0	
Undefined instruction or illegal state	true	0	0	
System service call via SWI instruction	true	0	0	
Debug monitor	true	0	0	
Pendable request for system service	true	0	0	
System tick timer	true 0		0	
PVD/PVM1/PVM2/PVM3/PVM4 interrupts through EXTI lines 16/35/36/37/38	unused			
Flash global interrupt	unused			
RCC global interrupt	unused			
USART2 global interrupt	unused			
EXTI line[15:10] interrupts	unused			
SAI1 global interrupt	unused			
FPU global interrupt	unused			

^{*} User modified value

9. Software Pack Report