DENVER RTD EAGLE P3
COMMUNICATION SYSTEM

FIELD MODIFICATION INSTRUCTIONS
FMI #12: SOFTWARE UPDATE

CONTRACT NO.	P110701149
CDRL NO.	N/A
WIS DOC. NO.	42A-2016-0033
REVISION:	1.0
DESIGNED:	J. S. JEONG
REVIEWED:	J. Y. LEE
APPROVED:	B. J. JONE
DATE:	8/30/2016

WOOJIN
Industrial Systems Co., Ltd.

Record of Revisions

Rev.	Date	Description	Entered By
1.0	8/30/2016	Initial release	J. S. Jeong

© Copyright Woojin Industrial Systems Co., Ltd.

Table of Contents

1. INTRODUCTION 4

2. SUMMARY 4

3. INSTRUCTIONS 4

3.1 LOCATION OF EQUIPMENT 4
3.2 SOFTWARE UPDATE 7
3.2.1 UPDATING CRA-MAIN, CRA-FTP AND CRA-CDT 7
3.2.2 UPDATING CCP 7
3.3 TEST AND VERIFICATION 7
3.4 VERSION CHECK 8

4. TRACKING 8

© Copyright Woojin Industrial Systems Co., Ltd.

1. INTRODUCTION

This FMI provides instructions to install the Communication System software update to the vehicles.

2. SUMMARY

This FMI applies to following software configuration item:

- CRA-MAIN, version 1.0.06
- CRA-FTP, version 1.0.03
- CRA-CDT, version 1.0.03
- CCP, version 1.0.04

Please refer to software version summary sheet and software revision history for more details.

3. INSTRUCTIONS

3.1 LOCATION OF EQUIPMENT

Following figures show the location of equipment to be updated.



Figure 1 – CNCS Board Location

© Copyright Woojin Industrial Systems Co., Ltd.



Figure 2 – CRA Location





Section A-A



Detail B

Figure 3 – CCP Location

© Copyright Woojin Industrial Systems Co., Ltd.

3.2 SOFTWARE UPDATE

3.2.1 Updating CRA-MAIN, CRA-FTP and CRA-CDT

1) Plug in a USB flash drive and a wireless keyboard to the USB ports on the CNCS front panel.
2) Terminate all running applications
3) Copy the updated files to CNCS directory: D:\Woojin\CNCS\
4) Recycle COMCB to apply the update.

3.2.2 Updating CCP

1) Connect the CCP and a PTU laptop with a USB cable.
2) Copy the updated 'AnCCP_MFC.exe' to CCP directory: Root\NandFlash\
3) Recycle COMCB to apply the update.

3.3 TEST AND VERIFICATION

After updating the VoIP software, follow the procedure below to verify the functionality:

1) Key-on the cab
2) Using the CCP touchscreen, enter route number 10 or 11
3) Run the route simulation
4) Verify the simulated announcements and displays function appropriately.

© Copyright Woojin Industrial Systems Co., Ltd.

3.4 VERSION CHECK

Use the MDS Software Version menu to verify the updated software versions.

- CRA-MAIN: 1.0.06
- CRA-FTP: 1.0.03
- CRA-CDT: 1.0.03
- CCP: 1.0.04

4.TRACKING

Status of the field modification activities will be tracked and managed for car number and items completed. The progress will be reported to DTP/H-Rotem in daily basis as the modification proceeds.

© Copyright Woojin Industrial Systems Co., Ltd.