M.C.R.Kumara

B.Sc.(Eng.) Hons, C.Eng, MIE (SL.),MSSE(SL),Green(SL)AP Structural Engineer

107/8A, Kirulapone Avenue, Colombo 05.

E-mail: kumaramer@yahoo.com

Mobile: 0718582835

0772699396

16th June 2020

TO WHOM IT MAY CONCERN


ASIRI HOSPITAL HOLDINGS PLC, KIRULA ROAD, COLOMBO 05.

STRUCTURAL ENGINEER'S REPORT FOR THE EXISTING BUILDING

As per the request made by the Management of the Hospital, I have done the visual inspection of the building to evaluate the existing situation.

- · There is no structural cracks visually seen on beams/slabs and columns.
- · There is no noticeable settlement occurred in the building at ground floor level.

Further as per the information received, the building was constructed over 30 years ago as per the practicing standards and methods in Sri Lanka. Also, it has been fully occupied for the past years and it is functioning without any structural failures. Therefore, the building is structurally stable and safe for human habitation.



Eng M.C.R.Kumara

BSc(Eng)Hons, C.Eng, MIE(SL), MSSE(SL), Green(SL)AP