
Micro:bit Project Sheet 6

Success Criteria

- Screen blank on start
- If wire touched X displayed
- Have three lives
- Lose life if wire touched
- Display dead when 0 lives left

μPython

```
# Add your Python code here. E.g.
from microbit import *
import music
lives =3
while lives>0:
    if pin1.is_touched():
        display.show("X")
        sleep(250)
        display.clear()
        lives=lives-1
display.show("DEAD")
```



Testing

- Does x display on touch
- Does screen clear
- Does dead display on third lost life

Notes

- Connect pin 1 to handle
- Connect Ground to wire rail

