Micro:bit Project Sheet 5

Design


Success Criteria

- Read X,Y,Z axis from accelerometer
- Log the data to a microSD card in a CSV format
- Read/Graph the data

μ Python

Please download from

http://microbitsandbobs.co.uk/downloads/MicroPi-Logger.py



Testing Does Micro:bit display not logging on start up On button A press does X display On button B press does not logging return Press button A rotate in X,Y,Z axis for 5 seconds - Press button B Is data recorded on SD Card Can data be imported into a spreadsheet tool Is data being recorded from all three axis Notes