

ISOMETRIC DRAWING AUTO-EDIT

PDS Isometric Auto-Edit

Dimension / item-no / weld-no / elbow editing of Intergraph PDS isometric DXF, plus ISO BOM Excel export.

Key Purpose

Why this program

1. One-click clean-up of PDS isometric DXF

- Runs the full pipeline — PLT single-lining, dimension edit, item-no, weld-no and elbow-arc edit — in one pass
- **Effect:** Hours of manual redrawing per isometric are replaced by a single button, with no missed edits

2. Batch many drawings at once


- Select any number of DXF files; each is processed and saved as <name>_PDS.dxf
- **Effect:** A whole isometric package is reformatted unattended instead of file-by-file

3. Consistent, standardised output every time

- The same rules run silently in the background, no console, no per-file settings to get wrong
- **Effect:** Every drawing comes out to the same house style, removing rework and reviewer corrections

Required inputs : One or more Intergraph PDS isometric DXF files

Main Window – Item Guide



1. Title – PDS ISO Drawing Auto Editing Tool
2. General tab
3. Select Dxf Dwg from PDS ISO (heading)
4. Selected DXF file list
5. Status – file count / No file selected
6. Select DXF files
7. Remove Selected from list
8. Clear All files
9. Open highlighted DXF
10. Auto Edit – run the editing pipeline
11. Cancel – close the tool

Processing Steps

What 'Auto Edit' runs, in order

1. Read the source DXF into memory once
2. Convert PLT multi-lines into clean single lines
3. Reformat and tidy the dimensions
4. Edit the item / component (TEM) numbers
5. Edit the weld numbers
6. Redraw the elbow arcs
7. Save the result as a new _PDS.dxf

Overview

What it does

1. Dimension
2. Item-no
3. Weld-no
4. Elbow editing of Intergraph PDS isometric DXF
5. ISO BOM Excel export

Category: Isometric Drawing Auto-Edit

Folder: ISO_AUTO_EDIT/ISO_AUTO_EDIT_FOR_PDS

Main scripts: PDS_RUNTEST.PY

Scripts / Status: 14 scripts · Operational

Tags: PDS · DXF · Excel

Notes & Information

- Part of the in-house Plant Engineering automation suite — category: Isometric Drawing Auto-Edit.
- Runs offline as a pure-Python / Tkinter tool; portable across PCs via OneDrive sync (needs Python + packages).
- Launch from the PC launcher (런처.bat) or run the main script: PDS_RUNTEST.PY.
- Output samples and the program window above reflect the current build.

Thank You

PDS Isometric Auto-Edit · Plant Engineering Total Service System