Aluminium 2011T3

Pos.	Tool Type	Depth (Peck)		Feed Rate		Spindle Speed	
		Rough	Finish	Rough	Finish	Rough	Finish
2	Center Drill		3		156		3819.719
6	Drill		5		105.300		1909.859
4	Drill		5		105.300		3819.719
7	Left Hand Turning	0.700	0.200	100	100	2800	2800
8	Right Hand Boring Bar	0.500	0.200	120	60	2200	2400
5	Right Hand External Threa		0.200				400
3	Right Hand Groove/Parting	j0.700	0.200	84	70	2800	2800
1	Right Hand Turning	0.700	0.200	100	100	2800	2800