Suggested Moai Exposure Settings for UV Resins These are recommended values based on our experience or user feed but are not absolute Individual factors such as temperature, leveling and others affects how resin cures, please adjust values as needed for your situation To learn about to find optimal exposure please use this guide: Brand Color Layer Height (um) Moai Laser Sett Moai 200 Laser Setting Print Speed Initial layer height (um) Initial layer print spee initial slower laye Contributer Notes Peopoly Moai Resin Grav Blue Rec 57-58 58 85 Pennoly Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6. please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Moai Resin Gray Blue Red 57-58 130 100 Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6. please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Peopoly Peopoly Moai Resin Gray Blue Red 57-58 58 170 100 Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6, please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Moai Resin Peopoly Black White Peopoly Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6. please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Moai Resin Black White 59 130 Peopoly Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6, please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&sfl=firmware Peopoly Moai Resin Black White 59 100 Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6, please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware 58-59 170 Peopoly Peopoly Peopoly Moai Resin Clear, Neon Green 50 57 57 130 100 Peopoly Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6, please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&sfl=firmware Peopoly Moai Resin Clear Neon Green 100 57 85 100 Peopoly Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6. please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Peopoly Moai Resin Clear Neon Green 25 57 57 170 100 Recommend update to new firmware setting of pm motor speed 20 and z motor speed 6. please refer http://wiki.peopoly.net/doku.php?id=moai:firmware&s[]=firmware Peopoly Next (HiTemp) Flesh/Skin/Grey 100 51 85 100 some users print at 50, it is best to use a sharp object to remove print due to high hardness Peopoly Next (HiTemp) Flesh/Skin/Grey 51 130 100 some users print at 50, it is best to use a sharp object to remove print due to high hardness Next (HiTemp) Flesh/Skin/Grey 170 100 some users print at 50, it is best to use a sharp object to remove print due to high hardness Peopoly Peopoly Next (HiTemp) Clear Nex Clear is slightly softer than other Nex 100 Peopoly Next (HiTemp) Clear Nex Clear is slightly softer than other Nex Next (HiTemp) Clear Peopoly 25 170 100 Nex Clear is slightly softer than other Nex Clear 100 51-52 85 100 pm motor speed 15, z motor speed, it is print to the left side to reduce peel force, use thicker support/tips Peopoly Tough Peopoly Tough Clear 50 51-52 130 100 pm motor speed 15, z motor speed, it is print to the left side to reduce peel force, use thicker support/tips Peopoly Tough Clear 25 51-52 170 100 pm motor speed 15, z motor speed, it is print to the left side to reduce peel force. use thicker support/tips Peopoly Deft Grey, White 100 85 100 use same slicing profiles as regular Moai model resin, just dial down the power 100 85 100 use same slicing profiles as regular Moai model resin, just dial down the power Cr & Br 100 100 Nextden 85 Nextdent Cr & Br 130 Nextdent Cr & Br 25 170 100 D. Lee 85 100 Nextdent SG 100 D. Lee 130 100 Nextdent SG 50 D. Lee Nextdent SG 25 170 100 D Lee Nevtdent Ortho Clear 100 75 100 chadfroe Nextdent Ortho Clear 50 130 100 chadfroe Nevtdent Ortho Clear 25 170 100 chadfroe Nextdent C&B MEH 100 90 100 chadfroe C&B MFH Nextdent 130 chadfroe C&B MFH 170 100 Nextdent chadfroe Moonray SG Transparen 100 85 100 David WH Moonray SG Transparent 50 50 130 100 David WH Moonray SG Transparent 50 170 100 David WH Maker, Juice Waxcat Orange 100 85 100 Bobby A Not as easy to cast cleanly Maker, Juice Waxcat Orange 50 130 100 Bobby A Not as easy to cast cleanly MakerJuice Waxcat Orange 25 170 100 Bobby A Not as easy to cast cleanly MakerJuice G+ Blue 100 85 100 PaulY 130 100 MakerJuice very high shrinkage MakerJuice Blue 170 100 PaulY very high shrinkage MakerJuice 85 100 CCox hard to fully cured, user reported random tiny holes may appear, very thin and suspect to pigment settling and bubbles Red 100 Maker Juice Red 50 53 130 100 CCox hard to fully cured, user reported random tiny holes may appear, very thin and suspect to pigment settling and bubbles MakerJuice SF Red 25 53 170 100 CCox hard to fully cured, user reported random tiny holes may appear, very thin and suspect to pigment settling and bubbles Funtodo Snow White White 100 85 100 David WH Funtodo Snow White White 50 130 100 David WH Snow White 170 100 David WH Funtodo White Castable 100 100 quick damages to resin Funtodo Bobby A quick damages to resin Castable Funtodo FotoDent Model White David WH Dreve Dreve FotoDent Model White 50 130 100 David WH 100 Dreve FotoDent Model White 170 David WH Dreve FotoDent SG Transparent 100 52 85 100 David WH Dreve FotoDent SG Transparent 50 52 130 100 David WH Dreve FotoDent SG Transparent 170 100 David WH Spot-A Yellow 100 85 100 Spot-A Yellow Spot-A нт Yellow 170 William L 100 Siraya Tech Fast Grey, White, Black, G 100 85 85 100 Sirava Tech Simple all colors 100 *warning photocentric tough doesn't print well and have problem stay on the plate Printing Guide: Nex HiTemp Resin http://wiki.peopoly.net/doku.php?id=moai:nexresin Tough V2 Resin http://wiki.peopoly.net/doku.php?id=moai:toughresin