







Not sure if you want this here: GP LEDS PushButton or 2 for testing USB Connector Testing Connector Jumpers for debugging and inserting signals @Authors: Ryan Jones, Alex Cargill & Devlin Trafford @Checked By: Group 7 UCT Sheet: /Outputs/ File: outputs.kicad_sch Title: Size: A4 Date: 2022-04-08 KiCad E.D.A. kicad (6.0.2) Rev: v1.0 ld: 5/5