

OBS / Windows Diagnostic Report

Generated: 07/05/2026 17:05:31

Computer: DESKTOP-VJT2BR2

User: Sound Room

Windows Version

Caption : Microsoft Windows 10 Pro

Version : 10.0.19045

BuildNumber : 19045

OSArchitecture : 64-bit

LastBootUpTime : 6/24/2026 7:30:27 PM

Computer / CPU / RAM

Manufacturer : Micro-Star International Co., Ltd.

Model : MS-7C37

TotalPhysicalMemory : 51456405504

Name : AMD Ryzen 9 5950X 16-Core Processor

NumberOfCores : 16

NumberOfLogicalProcessors : 32

MaxClockSpeed : 3975

GPU / Display Driver Info

Name : AMD Radeon RX 5700 XT

DriverVersion : 32.0.12019.1028

DriverDate : 10/10/2024 8:00:00 PM

VideoProcessor : AMD Radeon Graphics Processor (0x731F)

AdapterRAM : 4293918720

Audio Devices

Name : PreSonus FireStudio Audio

Manufacturer : PreSonus Audio Electronics

Status : Error

Name : AMD Streaming Audio Device

Manufacturer : AMD

Status : OK (x15)

Name : High Definition Audio Device

Manufacturer : Microsoft (x12)

Name : AMD High Definition Audio Device

Manufacturer : Advanced Micro Devices

Name : Nahimic mirroring device

Manufacturer : Nahimic

Name : Kinoni Audio Source

Manufacturer : Kinoni

Name : Dante Virtual Soundcard

Manufacturer : Audinate Pty Ltd

Name : VB-Audio Virtual Cable

Manufacturer : VB-Audio Software (x2)

Name : SteelSeries Sonar Virtual Audio Device

Manufacturer : SteelSeries ApS

Name : NDI Webcam Audio

Manufacturer : NewTek Partners LLP

Name : VB-Audio Voicemeeter VAO

Name : Sony Camera 1 (Virtual Webcam)

Manufacturer : Sony Corporation (x5)

Name : Sony Camera 2 (Virtual Webcam)

Name : Sony Camera 3 (Virtual Webcam)

Name : Sony Camera 4 (Virtual Webcam)

Name : Sony Camera 5 (Virtual Webcam)

Network Adapters

Name	InterfaceDescription	Status	LinkSpeed	MacAddress	ifIndex
------	----------------------	--------	-----------	------------	---------

Sony Camera(s)	Realtek PCIe GbE Family Controller #2	Up	1 Gbps	2C-F0-5D-09-E7-A5	18
----------------	---------------------------------------	----	--------	-------------------	----

Wi-Fi 6	Intel(R) Dual Band Wireless-AC 3168 #3	Disconnected	6 Mbps	0C-7A-15-92-0A-95	9
---------	--	--------------	--------	-------------------	---

Network Adapter Driver Info

DeviceName : Intel(R) Dual Band Wireless-AC 3168

Manufacturer : Intel Corporation

DriverProviderName : Intel

DriverVersion : 19.51.31.1

DriverDate : 9/14/2020 8:00:00 PM

DeviceName : Microsoft Kernel Debug Network Adapter

DriverProviderName : Microsoft (x11)

DriverVersion : 10.0.19041.1 (x11)

DriverDate : 6/20/2006 8:00:00 PM (x11)

DeviceName : Microsoft Wi-Fi Direct Virtual Adapter (x2)

DeviceName : Realtek PCIe GbE Family Controller

Manufacturer : Realtek

DriverProviderName : Realtek

DriverVersion : 10.54.1111.2021

DriverDate : 11/10/2021 7:00:00 PM

DeviceName : WAN Miniport (IKEv2)

DeviceName : WAN Miniport (IP)

DeviceName : WAN Miniport (IPv6)

DeviceName : WAN Miniport (L2TP)

DeviceName : WAN Miniport (Network Monitor)

DeviceName : WAN Miniport (PPPOE)

DeviceName : WAN Miniport (PPTP)
DeviceName : WAN Miniport (SSTP)
Network Adapter Advanced Properties
Name DisplayName DisplayValue
RegistryKeyword

Sony Camera(s) Advanced EEE Disabled
AdvancedEEE
Sony Camera(s) ARP Offload Enabled
*PMARPOffload (x2)
Sony Camera(s) Auto Disable Gigabit Disabled
AutoDisableGigabit
Sony Camera(s) Energy-Efficient Ethernet Enabled
*EEE
Sony Camera(s) Flow Control Rx & Tx Enabled
*FlowControl
Sony Camera(s) Gigabit Lite Enabled
GigaLite
Sony Camera(s) Green Ethernet Enabled
EnableGreenEthernet
Sony Camera(s) Interrupt Moderation Enabled
*InterruptModera...
Sony Camera(s) IPv4 Checksum Offload Rx & Tx Enabled
*IPChecksumOfflo...
Sony Camera(s) Jumbo Frame Disabled
*JumboPacket
Sony Camera(s) Large Send Offload v2 (IPv4) Enabled
*LsoV2IPv4
Sony Camera(s) Large Send Offload v2 (IPv6) Enabled
*LsoV2IPv6
Sony Camera(s) Maximum Number of RSS Queues 4 Queues
*NumRssQueues
Sony Camera(s) Network Address
NetworkAddress
Sony Camera(s) NS Offload Enabled
*PMNSOffload (x2)
Sony Camera(s) Power Saving Mode Enabled
PowerSavingMode
Sony Camera(s) Priority & VLAN Priority & VLAN Enabled
*PriorityVLANTag
Sony Camera(s) Receive Buffers 512
*ReceiveBuffers
Sony Camera(s) Receive Side Scaling Enabled
*RSS
Sony Camera(s) Shutdown Wake-On-Lan Enabled
S5WakeOnLan
Sony Camera(s) Speed & Duplex 1.0 Gbps Full Duplex
*SpeedDuplex
Sony Camera(s) TCP Checksum Offload (IPv4) Rx & Tx Enabled
*TCPChecksumOffl... (x2)
Sony Camera(s) TCP Checksum Offload (IPv6) Rx & Tx Enabled
Sony Camera(s) Transmit Buffers 128
*TransmitBuffers
Sony Camera(s) UDP Checksum Offload (IPv4) Rx & Tx Enabled
*UDPChecksumOffl... (x2)
Sony Camera(s) UDP Checksum Offload (IPv6) Rx & Tx Enabled
Sony Camera(s) VLAN ID 0
RegVlanid
Sony Camera(s) Wake on Magic Packet Enabled
*WakeOnMagicPacket (x2)
Sony Camera(s) Wake on magic packet when system is in the S0ix power state Disabled
*ModernStandbyWo...
Sony Camera(s) Wake on pattern match Enabled
*WakeOnPattern (x2)
Sony Camera(s) WOL & Shutdown Link Speed 10 Mbps First
WolShutdownLinkS...
Wi-Fi 6 802.11a/b/g Wireless Mode 6. Dual Band 802.11a/b/g
WirelessMode
Wi-Fi 6 802.11n/ac Wireless Mode 802.11ac
IEEE11nMode
Wi-Fi 6 ARP offload for WoWLAN Enabled
Wi-Fi 6 Channel Width for 2.4GHz Auto
ChannelWidth24
Wi-Fi 6 Channel Width for 5GHz Auto
ChannelWidth52
Wi-Fi 6 Fat Channel Intolerant Disabled
FatChannelIntole...
Wi-Fi 6 GTK rekeying for WoWLAN Enabled
*PMWi-FiRekeyOffload
Wi-Fi 6 MIMO Power Save Mode Auto SMPS
MIMOPowerSaveMode

Wi-Fi 6 Mixed Mode Protection RTS/CTS Enabled
CtsToItself
Wi-Fi 6 NS offload for WoWLAN Enabled
Wi-Fi 6 Packet Coalescing Enabled
*PacketCoalescing
Wi-Fi 6 Preferred Band 1. No Preference
RoamingPreferred...
Wi-Fi 6 Roaming Aggressiveness 3. Medium
RoamAggressiveness
Wi-Fi 6 Sleep on WoWLAN Disconnect Disabled
*DeviceSleepOnDi...
Wi-Fi 6 Throughput Booster Disabled
ThroughputBooste...
Wi-Fi 6 Transmit Power 5. Highest
IbssTxPower
Wi-Fi 6 U-APSD support Disabled
uAPSDSupport
Wi-Fi 6 Wake on Magic Packet Enabled
Wi-Fi 6 Wake on Pattern Match Enabled
Network Adapter Power Management
InterfaceDescription : Realtek PCIe GbE Family Controller #2 (x2)
Name : Sony Camera(s)
ArpOffload : Enabled (x2)
NSOffload : Enabled (x2)
RsnRekeyOffload : Unsupported
D0PacketCoalescing : Unsupported
SelectiveSuspend : Unsupported (x2)
DeviceSleepOnDisconnect : Unsupported
WakeOnMagicPacket : Enabled (x2)
WakeOnPattern : Enabled (x2)
InterfaceDescription : Intel(R) Dual Band Wireless-AC 3168 #3 (x2)
Name : Wi-Fi 6
RsnRekeyOffload : Enabled
D0PacketCoalescing : Enabled
DeviceSleepOnDisconnect : Disabled
IP Configuration
Windows IP Configuration
Host Name : DESKTOP-VJT2BR2
Primary Dns Suffix :
Node Type : Hybrid
IP Routing Enabled. : No
WINS Proxy Enabled. : No
Ethernet adapter Sony Camera(s):
Connection-specific DNS Suffix . : (x4)
Description : Realtek PCIe GbE Family Controller #2
Physical Address. : 2C-F0-5D-09-E7-A5
DHCP Enabled. : Yes (x2)
Autoconfiguration Enabled : Yes (x4)
Link-local IPv6 Address : fe80::985c:e800:772e:4b20%18(Preferred)
IPv4 Address. : 192.168.1.229(Preferred)
Subnet Mask : 255.255.255.0
Lease Obtained. : Wednesday, June 24, 2026 7:30:41 PM
Lease Expires : Sunday, July 5, 2026 6:39:35 PM
Default Gateway : 192.168.1.1
DHCP Server : 192.168.1.1
DHCPv6 IAID : 372043869
DHCPv6 Client DUID. : 00-01-00-01-26-0B-FA-9C-2C-F0-5D-09-E7-A5
DNS Servers : 192.168.1.1
NetBIOS over Tcpip. : Enabled
Wireless LAN adapter Local Area Connection* 1:
Media State : Media disconnected (x3)
Description : Microsoft Wi-Fi Direct Virtual Adapter
Physical Address. : 0C-7A-15-92-0A-96
Wireless LAN adapter Local Area Connection* 10:
Description : Microsoft Wi-Fi Direct Virtual Adapter #2
Physical Address. : 0E-7A-15-92-0A-95
DHCP Enabled. : No (x2)
Wireless LAN adapter Wi-Fi 6:
Description : Intel(R) Dual Band Wireless-AC 3168 #3
Physical Address. : 0C-7A-15-92-0A-95
Net IP Configuration
InterfaceAlias : Sony Camera(s)
InterfaceIndex : 18
NetProfile.Name : Rapp Family {Backup WiFi}
IPv4Address : 192.168.1.229
IPv6DefaultGateway :
IPv4DefaultGateway : 192.168.1.1
DNSServer : 192.168.1.1
InterfaceAlias : Wi-Fi 6
InterfaceIndex : 9
NetAdapter.Status : Disconnected

DNS Servers

InterfaceAlias InterfaceIndex AddressFamily ServerAddresses

Sony Camera(s) 18 IPv4 {192.168.1.1}
Sony Camera(s) 18 IPv6 {}
Local Area Connection* 1 24 IPv4 {}
Local Area Connection* 1 24 IPv6 {fec0:0:0:ffff::1, fec0:0:0:ffff::2,
fec0:0:0:ffff::3} (x4)
Local Area Connection* 10 3 IPv4 {}
Local Area Connection* 10 3 IPv6 {fec0:0:0:ffff::1, fec0:0:0:ffff::2,
Wi-Fi 6 9 IPv4 {}
Wi-Fi 6 9 IPv6 {fec0:0:0:ffff::1, fec0:0:0:ffff::2,
Loopback Pseudo-Interface 1 1 IPv4 {}
Loopback Pseudo-Interface 1 1 IPv6 {fec0:0:0:ffff::1, fec0:0:0:ffff::2,
Default Gateway Ping Test
Default Gateway: 192.168.1.1
Source Destination IPV4Address IPV6Address Bytes (x2)
Time(ms) (x2)
----- (x2)

--- (x2)

DESKTOP-VJ... 192.168.1.1 32 0 (x47)

DESKTOP-VJ... 192.168.1.1 32 1 (x3)

Internet Ping Test

Pinging 1.1.1.1...

DESKTOP-VJ... 1.1.1.1 1.0.0.1 32 12 (x6)

DESKTOP-VJ... 1.1.1.1 1.0.0.1 32 11 (x44)

Installed OBS / NDI / Audio / AMD / Realtek Related Programs

DisplayName DisplayVersion Publisher

InstallDate

AMD DVR64 1.0.2 Advanced Micro Devices, Inc.

20241108 (x5)

AMD Ryzen Master 2.2.0.1543 Advanced Micro Devices, Inc. (x2)

20200524

AMD Settings 2024.1011.1706.2043 Advanced Micro Devices, Inc.

AMD Software 24.10.1 Advanced Micro Devices, Inc.

AMD User Experience Program Installer 2420.19.01.1011 Advanced Micro Devices, Inc.

AMD WVR64 1.0.2 Advanced Micro Devices, Inc.

Branding64 1.00.0009 Advanced Micro Devices, Inc.

Dante Control and Monitoring 4.0.4.1 Audinate Pty Ltd

20200420 (x3)

Dante Discovery 1.3.1.2 Audinate Pty. Ltd.

Dante Virtual Soundcard 4.1.0.4 Audinate Pty Ltd (x2)

NDI 4 Runtime NewTek, inc.

20220227 (x2)

NDI 6 Tools 6.0.1.0 NDI

20240901

NewTek SpeedHQ Video Codec (x64) (Remove Only)

NewTek SpeedHQ Video Codec (x86) (Remove Only)

OBS Studio 31.0.2 OBS Project

obs-ndi version 4.13.0 4.13.0 StÃ©phane Lepin

20240202 (x2)

obs-ndi version 4.9.0 4.9.0 Stephane Lepin

obs-ptz version 0.15.4 0.15.4 Grant Likely

obs-websocket version 5.0.1 5.0.1 OBS Project

20240406

Voicemeeter, The Virtual Mixing Console VB-Audio Software

vs_filehandler_amd64 17.14.36024 Microsoft Corporation

20250721

Recent System Errors / Warnings - Last 24 Hours

CONDENSED EVENT LOG REPEATS

Warning (x5) - Microsoft-Windows-DistributedCOM (x5) Event 10016 (x1)

First/last seen: 7/5/2026 5:04:29 PM -> 7/5/2026 5:04:29 PM

Message: The application-specific permission settings do not grant Local Activation (x3) permission for the COM (x3) Server application with CLSID (x3) and APPID (x5) to the user DESKTOP-VJT2BR2\Sound Room SID (S-1-5-21-4085534441-4294284424- (x5) 2636835831-1001) from (x5) address LocalHost (Using LRPC) running in the application container Unavailable SID (x3) (Unavailable). (x3) This security permission can be modified using the Component Services (x3) administrative tool. (x3)

Unknown Level - Unknown Provider Event Unknown ID (x1)

First/last seen: 7/5/2026 11:25:12 AM -> 7/5/2026 11:25:12 AM

Message: The machine-default permission settings do not grant Local Activation permission (x2) for the COM Server (x2) application with CLSID (x2) address LocalHost (Using LRPC) running in the application container (x2)

Microsoft.Windows.ShellExperienceHost_10.0.19041.4957_neutral_neutral_cw5n1h2txyewy (x2)

(S-1-15-2-155514346-2573954481-755741238-1654018636-1233331829-3075935687- (x2) 2861478708). This (x2) security permission can be modified using the Component Services administrative (x2) tool. (x2)

Unknown Level - Unknown Provider Event Unknown ID (x22)

First/last seen: 7/4/2026 11:36:22 PM -> 7/5/2026 10:25:00 AM

Message: TimeCreated : 7/4/2026 11:36:22 PM

Error (x30) - Microsoft-Windows-Bits-Client (x24) Event 16398 (x1)
First/last seen: 7/5/2026 9:10:49 AM (x4) -> 7/5/2026 9:10:49 AM (x4)
Message: A new BITS job could not be created. The current job count for the user DESKTOP- (x24) VJT2BR2\Sound Room (x24) (60) is equal to or greater than the job limit (60) specified through group policy. (x24) To correct the (x24) problem, complete or cancel the BITS jobs that haven't made progress by looking at (x24) the error, and (x24) restart the BITS service. If this error recurs, contact your system administrator (x24) and increase the (x24) per-user and per-computer Group Policy job limits. (x24)

Unknown Level - Unknown Provider Event Unknown ID (x1)
First/last seen: 7/4/2026 11:36:12 PM -> 7/4/2026 11:36:12 PM
Message: TimeCreated : 7/4/2026 11:36:12 PM Recent Application Errors / Warnings - Last 24 Hours

Unknown Level - Bonjour Service (x6) Event 100 (x1)
First/last seen: 7/5/2026 1:00:22 PM (x2) -> 7/5/2026 1:00:22 PM (x2)
Message: mDNSCoreReceiveResponse: Unexpected conflict discarding 23 1.0.0.127.in- addr.arpa. PTR DESKTOP-VJT2BR2.local. Message : mDNSCoreReceiveResponse: Received from 127.0.0.1:5353 25 1.0.0.127.in-addr.arpa. PTR DESKTOP-VJT2BR2-2.local.

Unknown Level - Unknown Provider Event Unknown ID (x1)
First/last seen: 7/5/2026 1:00:18 PM -> 7/5/2026 1:00:18 PM
Message: Client application bug: DNSServiceResolve(mobile._epoccam._tcp.local.) active for over two minutes. This places considerable burden on the network.

Unknown Level - Unknown Provider Event Unknown ID (x1)
First/last seen: 7/5/2026 12:38:17 PM (x3) -> 7/5/2026 12:38:17 PM (x3)
Message: Task Scheduling Error: m->NextScheduledSPRetry 1047 Message : Task Scheduling Error: m->NextScheduledEvent 1047 Message : Task Scheduling Error: Continuously busy for more than a second OBS Log Folder OBS log path: C:\Users\Sound Room\AppData\Roaming\obs-studio\logs Copied latest OBS logs to: C:\Users\Sound Room\Desktop\OBS_Diagnostics_20260705_170531\OBS_Logs Recent OBS logs: Name LastWriteTime Length ----

2026-07-05 09-09-49.txt 7/5/2026 12:36:28 PM 107807 2026-07-05 09-09-21.txt 7/5/2026 9:09:45 AM 50122 2026-07-03 19-31-22.txt 7/3/2026 8:20:28 PM 77479 2026-07-03 19-04-12.txt 7/3/2026 7:50:24 PM 31749 2026-07-03 18-55-22.txt 7/3/2026 7:04:01 PM 52974 2026-07-03 18-54...