## MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE

# UNITED STATES POSTAL SERVICETM

## Maintenance Management Order

**SUBJECT:** Network Distribution Center (NDC)

Operational and Preventive Maintenance Guidelines for Sack Sorting Machine

Over/Under

**NO:** MMO-145-12

DATE: December 4, 2012

TO: Manager Maintenance, All NDCs FILE CODE: Y10

mcol:mm12047ae

This Maintenance Management Order (MMO) provides Network Distribution Center (NDC) Operational and Preventive Maintenance Guidelines for the Sack Sorting Machine (SSM) Over/Under. This MMO supersedes MMO-033-98. The acronym is SSM. The class code is OA.

The workhours indicated in the workload estimate (Attachment 1) are based on a 20-hour operations window and reflect the maximum annual workhours required to maintain each system. Actual workhour requirements and the frequency of tasks are dependent on run time and pieces processed. Therefore, PM workhour requirements will vary day-to-day based on site specific machine utilization. Management may modify task frequencies to address local conditions.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher level employees from performing any of this work.

Preventive Maintenance (PM) guidelines provide maintenance employees with the recommended task based maintenance activities. The Electronic Conditioned Based Maintenance (eCBM) is an abbreviated task list that represents a portion of the PM checklist. The complete master PM checklist must be accessible to all maintenance employees when performing PM and eCBM task based maintenance activities.

#### WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

Web Access: http://mtsc.usps.gov

#### WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

#### WARNING

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Manager

Maintenance Technical Support Center

**HQ** Maintenance Operations

- Attachments 1. Summary Workload Estimate for SSM
  - 2. Master Checklist: 03-SSM-\*\*-001-M
  - 3. Master Checklist: 09-SSM-\*\*-001-M

#### **ATTACHMENT 1**

SUMMARY
WORKLOAD ESTIMATE
FOR SSM

#### SUMMARY WORKLOAD ESTIMATE FOR SSM

#### **NOTE**

Since this equipment contains multiple units of unknown quantity, the workload estimate can not be provided in a traditional roll-up table. For this guideline, the annual work hours are derived from local site specific entries made in an electronic Work Hour Estimator Program (eWHEP) worksheet. Refer to eWHEP for further guidance.

#### **ATTACHMENT 2**

#### **SSM MASTER CHECKLIST**

03-SSM-OA-001-M

Time Total: 297.66 minutes per year

Maintenance Technical Support Center

ИМО-145-12					Mai	intenance	e Tec	hnic	al Sup	port C	enter
U.S. Postal	Service	WORK		FOLI	PMENT	IDENTIFICAT		ASS	I NII	IMBER	TYPE
Maintenance	Checklist	CODE			ONYM			ODE	INC	INDER	TTPE
		0 3	SSN	/			0	Α	0	0 1	М
Equipment Nomenclature Sack Sorting		Equipmer	nt Model			Bulletin File	ename 2047a	е	Occurre	ence	
Part or	Item		Statement an				Est.	Min.		Threshold	ls
Component	No	(Comply wit	h all current s	afety p	recautio	ns)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.
SAFETY STATEMENT:	Disconne required local	lect power lect power lect power less than the leaner less than the	LL SAFET er and apprintruction cedures to machine. I ditions. Cl debris. If a nd notify s any furthe  MPRESSE s required, such as a or a dample sed or blo ay be used when othe Report safe immediate EWP/PPE: in this bull Protective ent Electri riate PPE r and solven al procedu mbustion. nutious wh when pow maintenan nothis PM g bedure is te ments (i.e. b) low speed er listen to " inufacturer ic Detector	ly local. Reformed in Reformed	kouts er to coperly s equip for susual visor p on on  BLOV Iternate A filte nust b ir. A li poptical ning r eficier on det  way re pment fork PI rement ked ma o preve orking as bee  dM) te ngs, rol ng equ check ers mar	when current shutdown ment and spicious orior to the WN AIR IS ive red e used in nt-free methods accies to tection.  equire the (PPE). an (EWP) is. aterials ent ground in applied. Chniques e Ultrasonic condition ders and ipment) in for noise unal and	3	All			W

2 Attachment 2

**NOTE:** Return loose mail found while performing this checklist to locally designated locations.

U.S. Postal Service							IDE	NTIF	ICATI	ION					
Maintenance Checklist	CO	RK DE				 MENT NYM				CLA CO	ASS DE	N	UMBI	ĒR	TYPE
	0	3	S	S	М					0	Α	0	0	1	М
Equipment Nomenclature Sack Sorting Machine	Equ	ipmer	nt Mo	del			В			name 047ae		Occur	rence		

3								
Part or	Item	Task Statement and Instruction	,	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions	5)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.
MAIL SEARCH:	2.	WARNING: Be cautious when working a or on equipment when power has been CHECK FOR MAIL. Look for loose mail with the control of the control o	applied.	3	07			W
		performing these activities.						
SYSTEM:	3.	START EQUIPMENT. Start equipment and warning indicators for proper operation.	d check	3	07			W
DRIVE:	4.	CHECK MOTOR AND GEAR HOUSING. motor and gear housing as follows:	Check	6	09			Q
		Use the ultrasonic detector with stethoronome to check motor and gear housing detect for excessive vibration and nois	gs to					
		<ol> <li>Use the noncontact infrared thermome check for excessive heat on the motor reducer.</li> </ol>						
DRIVE: BRAKE	5.	CHECK BRAKE. Check brake as follows:		8	09			Q
DIV II L		Observe effectiveness of brake.						
		Check braking action on motor.						
		Listen for noisy brake operation.						
DRIVE: COUPLING	6.	CHECK OUTPUT COUPLING. Observe o coupling for any misalignment of shafts.	utput	2	09			Q
CARRIAGE: CHAIN	7.	CHECK CHAIN / CARRIAGE ASSEMBLY the equipment operating, check chain/carriassembly as follows:		0.12*	07			W
		Look for proper chain lubrication.						
		<ol><li>Check for cracked trays, missing bump and damaged wheels.</li></ol>	pers,					
		3. Look for mail caught in chain.						
TRAY STRAIGHTENER:	8.	CHECK TRAY STRAIGHTENER. Check t straightener as follows:	ray	2	07			W
		<ol> <li>Observe carriages at the tray straighte smooth operation and proper latching.</li> </ol>						
		<ol><li>Check that clearance between tray and straightener should be 1/2".</li></ol>	d					

Maintenance Technical Support Center

U.S. Postal Service							IDE	NTIF	ICAT	ION					
Maintenance Checklist		RK DE				 MEN ONYN					ASS DE	1	IUMB	ER	TYPE
	0	3	S	S	М					0	Α	0	0	1	M
Equipment Nomenclature Sack Sorting Machine	Equ	Equipment I		del			В			name 047ae		Occu	rence	!	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	INO	(Comply with all current salety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.
CARRIAGE:	9.	CHECK CARRIAGE ASSEMBLY. Check carriage assembly as follows:	3*	07			Q
		Remove latch pins and lower removable track.					
		Check trays for cracks and rough edges.					
		<ol><li>Clean all dirt and build-up from carriage assembly and wheels.</li></ol>					
		<ol> <li>Check all wheels and guide rollers and Index plates for wear and damage.</li> </ol>					
		5. Check carriage for cracks and warpage.					
		6. Check for damaged bumpers.					
CARRIAGE: CHAIN	10.	CHECK CHAIN. Observe chain (one complete revolution at slow speed) around one sprocket for indications of frozen or worn rollers and missing cotter pins.	0.04*	07			Q
UNICO:	11.	CHECK UNICO DRIVE CABINET. Check cabinet	4	09			Q
		as follows:  1. Clean or replace filter as needed.					
		Review fault history.					
		3. Review fault mask.					
SYSTEM:	12.	POWER DOWN AND LOCK OUT POWER. Power down the machine and lock out its electrical power as prescribed by the current local lockout instructions providing lockout/restore procedures.	3	All			W
OILER:	13.	CHECK OILER OIL LEVEL. Check automatic oiler level. Add oil (OL-3) if required.	5	07			W
WIPER: DRAIN PAN	14.	SERVICE WIPER AND DRIP PAN. Service wiper and drip pan as follows:	15	07			М
		Check chain oil wipers.					
		2. Drain and clean oil drip pan.					
CHAIN:	15.	CHECK CHAIN TENSION. Check the sorter chain tension using the approved method. Tension chain as necessary.	60	09			Q

U.S. Postal Service							IDE	NTIF	ICATI	ON					
Maintenance Checklist	_	RK DE				 MEN NYM				CLA CO	ASS DE	N	UMBI	ĒR	TYPE
	0	3	S	S	М					0	Α	0	0	1	М
Equipment Nomenclature Sack Sorting Machine	Equ	ipmer	nt Mo	del			В		n Filer m12	name 047ae		Occuri	rence		

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	s
Component	No	(Comply with all current safety precautions)	Time	Skill	Run	Pieces	Freq.
			Req (min)	Lev	Hours	Fed (000)	r req.
DRIVE: REDUCER		CHECK AND CLEAN MOTOR AND REDUCER HOUSINGS. Check that the motor and reducer housings are free from dirt accumulation. Clean if necessary.	30	07			S
DRIVE: REDUCER		<b>LUBRICATE REDUCER</b> . Take oil sample for lab test. If change is indicated, drain and refill reducer to the appropriate level. Use lubricant GL-5-EP.	15	07			А
DRIVE: REDUCER		LUBRICATE OUTPUT COUPLING. Lubricate output coupling with GR-2-EP lubricant.	5	07			А
DRIVE: REDUCER		WRENCH TEST BOLTS. Wrench test mounting bolts on output coupling.	5	07			A
DRIVE: REDUCER		CLEAN AND LUBRICATE DRIVE SHAFT BEARING. Clean and lubricate drive shaft bearing as follows:  1. Wipe clean and lubricate the drive shaft bearing with (GR-2-EP) lubricant.  2. Lube until fresh lubricant appears at relief vent.  3. Clean excess lubricant from bearing.	6	07			А
ENCODER		CHECK ENCODER MODULE. Check encoder module as follows:  1. Remove cover on encoder module.	10	07			A
		<ol> <li>Clean the chain.</li> <li>Look for damage and wear to chain and sprockets.</li> <li>Lube the chain (GL-5) and reinstall the cover.</li> <li>Check motor encoder for secure mounting.</li> </ol>					
DRIVE: SPROCKET		<ul> <li>CHECK AND CLEAN SPROCKET TEETH. Check and clean sprocket teeth as follows:</li> <li>1. Check sprocket teeth for wear.</li> <li>2. Remove build-up of foreign material.</li> <li>3. Check sprocket teeth mounting bolts.</li> <li>4. Tighten, if required, SAE-8 bolts and lock nuts to 15 ft/lb. torque.</li> </ul>	30	07			S

Maintenance Technical Support Center

U.S. Postal Service							IDE	NTIF	ICAT	ION						
Maintenance Checklist	_	RK DE				 MEN NYM				_	ASS DE		Νl	JMBE	₽R	TYPE
	0	3	S	S	М					0	Α		0	0	1	М
Equipment Nomenclature Sack Sorting Machine	Equ	ipmer	nt Mo	del			В	ulletir <b>m</b> ı		name 047ae		Occ	curr	ence		
											· ·					

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.
DISCHARGE: TRIPPER ASSEMBLY		CLEAN AND CHECK TRIPPER ASSEMBLY. Clean and check tripper assembly as follows:  1. Remove foreign material from tripper assembly, power cables, solenoids, and air hoses.  2. Check air hose connectors and look for damaged air hoses.  3. Listen for air leaks.  4. Look for damage to electrical cable, solenoid valves, and connector.  5. Check trippers for proper position.  6. Wrench test all mounting bolts. Check for excess wear.  7. Check bumpers for wear or damage. Rotate tripper roller to check for ease of rotation.  8. Look for damaged or worn linkage.	4*	07		(000)	Q
STRUCTURE:		Check pivot points for ease of operation.  CHECK CONDUIT AND WIRING. Check conduit	10	07			S
		<ol> <li>Check for damage to conduit and wiring between control panel and motor panels, limit switches, photocells, and other control devices associated with this group panel.</li> <li>Look for conduit being used for handhold or steps.</li> </ol>					
STRUCTURE:		<ol> <li>CLEAN AND CHECK LIMIT SWITCH. Clean and check limit switch as follows:</li> <li>Remove dust from housing and tripper arm of removable track switch.</li> <li>Look for damaged or worn linkage.</li> <li>Check pivot points for ease of operation.</li> <li>Wrench test switch mounting bolts for tightness.</li> <li>Look for damage to conduit and wiring.</li> </ol>	3	07			Q

U.S. Postal Service							IDE	NTIF	ICAT	ION					
Maintenance Checklist	WC	RK DE				 MENT MYMC					ASS DE	N	UMBI	ER	TYPE
	0	3	S	S	М					0	Α	0	0	1	M
Equipment Nomenclature Sack Sorting Machine	Equ	ipmer	nt Mo	del			Е	Bulletir m		name 047ae		Occur	rence		

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	c
Component	No	(Comply with all current safety precautions)	Time	Skill	Dun		
			Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.
STATIC DEVICE:	26.	CHECK STATIC DISCHARGE DEVICE. Check	5	07			Q
		condition and contact of static discharge device.					
STRUCTURE:	27.	CHECK STRUCTURE. Check structure as follows:	40	07			S
		Look for damage to supporting and structural members of equipment, misalignment at joints between equipment sections, and loose connecting bolts.					
		<ol><li>Look and feel for loose anchor bolts, hanger rods, and tie rods.</li></ol>					
		Look for cracked or broken welds.					
SYSTEM:		WARNING: Be cautious when working around or on equipment when power has been applied.	3	All			W
		RESTORE EQUIPMENT TO SERVICE. Restore equipment to service as prescribed by the current local procedure providing lockout/restore procedures.					
START UP:		START UP. Perform normal start-up procedures as follows:	5	All			W
		Start or preset equipment.					
		Check for proper operation.					
SENSOR: TRACKING (DVS, IVS, LVS)		RUN FMPCS MAINTENANCE SENSOR TESTS. Check tracking sensor alignment, run test for each sorter tracking sensor (observe test results on message log). Verify condition of tray stabilizer and wear strip for tray load sensors.	5*	10			Q
DISCHARGE:		RUN FMPCS MAINTENANCE DISCHARGE TESTS. Run discharge unit test for each discharge (observe each discharge unit tipping tray).	0.5*	10			Q
DISCHARGE: CHUTE /CONTAINER	32.	TEST CHUTE SENSORS. Verify operation of chute sensor and reporting circuits:	1*	10			Q
LOADER		For chutes that only have one sensor (these sensors are located near the top of each chute).					
		Block the sensor and check to see if the chute full light illuminates.					
		b. While the sensor is blocked, check the					

CLEAN UP:

Maintenance Technical Support Center

3

ΑII

W

U.S. Posta	I Service									IDE	ENTIF	<b>ICAT</b>	ION					
Maintenance	e Chec	klist		ORK ODE			_	QUIP 4CRC		-				ASS ODE	N	UME	BER	TYPE
			0	3	S	S	М						0	Α	. 0	0	1	М
Equipment Nomenclatu Sack Sortino	Sack Sorting Machine				nt Mo	del	•			В	Bulletir m		name 047a	е	Occuri	ence	Э	
Part or Component	Item No		(Comp				and I			ions)	١		Est. Time	Min. Skill		Thi	reshold	s
Component	140		(COIII)	, , , , , , , , , , , , , , , , , , ,	ar an v	ourro	it our	oty pr	Journ		,		Req (min)	Lev	Run Hours		ieces Fed 000)	Freq.
			FMP0 see th									g to						
		C.	Chec	k the	e FM	PCS	Cin	nplic	ty so	cree	n to							

see if blocked sensor is shown on the

For chutes that have two sensors (the second sensor is located near the middle of the chute).

a. Block the upper sensor and check the

c. Block lower sensor to see if the chute full light illuminates (if this is a container loader the parcel gate should move).

33. **CLEAN UP**. Ensure all tools, lubricants, rags, etc.,

are removed from the work area. Report all

deficiencies to your supervisor.

FMPCS condition report or message log to see that it indicates the chute is full.b. Check the FMPCS Cimplicity screen to see if blocked sensor is shown on the

screen.

screen.

<sup>\* ---</sup> the tasks marked with an asterisk are per unit tasks.

<sup>\*\* ---</sup> the tasks marked with two asterisks are critical tasks.

### ATTACHMENT 3

#### **SSM MASTER CHECKLIST**

09-SSM-OA-001-M

**Operational Maintenance** 

Time Total: 52 minutes

U.S. Postal Service

Maintenance Technical Support Center

U.S. Postal Service  Maintenance Checklist		IDENTIFICA EQUIPMENT							100		NUMBER   -		T) (5.5			
		WORK CODE					MENT NYM				_ASS ODE	N	JMBER		TYPE	
			0 9	S	S	М					0	Α	0	0	1	М
Equipment Nomenclature			Equipme	ent M	odel					tin File		•	Occurr			
Sack Sorting Machine			mm12						mm12	2047a	е	Tourly				
Part or	Tools Obstance of and bestmedies							Fot	Min.	Thresholds						
Component	Task Statement and Instruction  Comply with all current safety precautions)							Est. Time	Skill							
'	. ,				, ,		,		Req	Lev	Run			Freq.		
											(min)		Hours	Fed (000		
										_				,		"
SAFETY		COMPLY										All				Т
STATEMENT:		Disconne required														
		local lock														
		and lock														
		inspect d														
		dust or u														
	substa		bstance is found notify supervisor prior to													
			roceeding with any further action on the													
		equipment.														
	тн			HE USE OF COMPRESSED OR BLOWN AIR IS												
	_	ROHIBITED. /hen cleaning is required, an alternative														
					cleaning method such as a HEPA filtered											
		vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical														
		ipment only when other cleaning methods														
					not be used. Report safety deficiencies to											
		your sup														
	,	WARNING	G FOR	EWF	P/PPF	=-										
					-		tin n	nay r	equire	e the						
			teps contained in this bulletin may require the se of Personal Protective Equipment (PPE). efer to the current Electrical Work Plan (EWP)													
	MMO for			or appropriate PPE requirements.												
	WARNIN				NG: Be cautious when working around											
						quipment when power has been applied.										
FMPCS REPORTS:		GENERA							•		15	10				Т
		data provi														
		if any area attention.														
		FMPCS m								;						
		command		Ston	1 01 10	,quc	3100	at tir	C							
		4 Davida					1. 6									
		1. Revie	w volur rences							per						
			tion Uni							lem						
		or fail		. pic		, 01	_,,00	a. gc	, P. OD	.0,,,						
				i4i	<b></b> -	n4 I	. a l - f	OF								
		2. Revie														
		equip	itional, d ment	Jul 0	n sei\	rice,	ıdılli	ıy, or	uowi	1						
			ew maintenance report. Look for high													
		numb	ber occurrences of problems or failures.							<del>2</del> 5.						
-																

U.S. Postal Service		IDENTIFICATION														
Maintenance Checklist		RK DE	EQUIPMENT ACRONYM								CLASS CODE		NUMBER			TYPE
	0	9	S	S	М						0	Α	0	0	1	M
Equipment Nomenclature Sack Sorting Machine	Equipmer		nt Model					В	Bulletin Filename mm12047ae				Occurr			

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill	Thresholds			
Component	INO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.	
		Review current message log.						
SENSOR: TRACKING (DVS, IVS, LVS)	3	RUN FMPCS MAINTENANCE SENSOR TESTS. Run sensor test for each sorter tracking sensor (observe test results on message log). The location of mail on the trays or tray state must be known to determine correct test results.	5*	10			Т	
DISCHARGE:	4	RUN FMPCS MAINTENANCE DISCHARGE TESTS. Run discharge unit test for any discharge showing a high failure rate in the maintenance report (observe discharge unit tipping tray).	10	10			Т	
INDUCTION UNIT:	5	CHECK INDUCTION UNIT. Observe condition of the induction unit (belting, controls).	1*	09			T	
INDUCTION UNIT:	6	<b>CHECK INDUCTION</b> . Observe induction of sack onto the sorter, ensure sack is hitting the correct tray.	1*	09			Т	
INDUCTION UNIT: SCANNER	7	CHECK SCANNER. Verify scanners ability to read bar code.	1*	09			Т	
CHAIN:	8	CHECK CHAIN. Check chain tension by observing chain slack coming off the driving sprocket (bull wheel). Check chain lubrication (if applicable).	1	09			T	
DRIVE:	9	CHECK DRIVE. Check reducer, drive gear, and coupling. Look for oil leaks, grease seals. Listen for bearing or gear noise.	1	07			Т	
CARRIAGE:		CHECK CARRIAGES. Observe sorter carriages for broken trays, latching plates, or missing wheels.	10	07			Т	
TRAY STRAIGHTENER:	11	CHECK TRAY STRAIGHTENERS. Verify tray straighteners are functional and wear strip is in good condition.	2	07			T	
TRAY STABILIZER:	12	CHECK TRAY STABILIZERS. Verify tray stabilizers are functional and wear strip is in good condition.	2	07			Т	
REPORT:		REPORT DEFICIENCIES. Report all deficiencies to your supervisor.	3	All			Т	