MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE



Maintenance Management Order

SUBJECT: Network Distribution Center (NDC) Mail

Search Guidelines for Singulate Scan

Induction Unit

NO: MMO-077-12

DATE: August 13, 2012

TO: Manager Maintenance, All NDCs FILE CODE: Y9

jsta:mm12035af

Safety Warning added for working around moving conveyors.

This Maintenance Management Order (MMO) provides Network Distribution Center (NDC) Mail Search Guidelines for Singulate Scan Induction Unit (SSIU). The acronym is SSIU. The class codes are AA, BA, CA, DA, EA, FA, GA, and HA.

Actual workhour requirements and the frequency of tasks are dependent on run time and pieces processed. Therefore, mail search workhour requirements will vary day-to-day based on site specific machine utilization. Management may modify task frequencies to address local conditions.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher level employees from performing any of this work.

WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

Web Access: http://mtsc.usps.gov

WARNING

Moving conveyors may expose employees to personal safety hazards. Do not climb, sit or walk on conveyors without first performing local Energy Control Procedure (ECP).

Direct any questions or comments concerning this bulletin to the MTSC HelpDesk, (800) 366-4123 or (405) 573-2123.

Robert E. Albert

Manager

Maintenance Technical Support Center

HQ Maintenance Operations

Attachments 1. Summary Workload Estimate for SSIU

2. Master Checklist: 24-SSIU-**-001-M

ATTACHMENT 1

SUMMARY

WORKLOAD ESTIMATE

FOR SSIU

Attachment 1 1

SUMMARY WORKLOAD ESTIMATE FOR SSIU

MAIL SEARCH TOTAL							
	2	3					
Days/Week	HSIUS	HSIUS					
	Hrs/Yr	Hrs/Yr					
5 Days	132.17	140.83					
6 Days	158.60	169.00					
7 Days	185.03	197.17					

2 Attachment 1

ATTACHMENT 2

SSIU MASTER CHECKLIST

DAILY MAIL SEARCH

24-SSIU-**-001-M

Time Total: 28.5 minutes

** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA

Attachment 2

Maintenance Technical Support Center

** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA Part or Component No (Comply with all current safety precautions) Est. Min. Three Skill Reg Lev Run Pie						
Maintenance Checklist						
Equipment Nomenclature Singulate Scan Induction Unit ** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA Part or Component No Item Task Statement and Instruction Comply with all current safety precautions) SAFETY STATEMENT: COMPLY WITH ALL SAFETY PRECAUTIONS. All Disconnect power and apply lockouts when Di	R TYP					
Singulate Scan Induction Unit Class codes = AA, BA, CA, DA, EA, FA, GA, and HA Part or Component Item No	1 M					
** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA Part or Component No (Comply with all current safety precautions) SAFETY STATEMENT: ** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA Task Statement and Instruction (Comply with all current safety precautions) Est. Time Req (min) Hours Fe (00) All All Disconnect power and apply lockouts when						
Part or Component No (Comply with all current safety precautions) SAFETY STATEMENT: Comply with all current power and apply lockouts when Statement and Instruction Est. Time Skill Req (min) Skill Req (min) Fig. (Or Statement and Instruction Skill Req (mi	aily					
Component No (Comply with all current safety precautions) Time Req (min) Run Hours Fe (OX SAFETY STATEMENT: Disconnect power and apply lockouts when						
SAFETY 1. COMPLY WITH ALL SAFETY PRECAUTIONS. STATEMENT: Disconnect power and apply lockouts when	Thresholds					
SAFETY 1. COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when	ces Fred					
SAFETY 1. COMPLY WITH ALL SAFETY PRECAUTIONS. All STATEMENT: Disconnect power and apply lockouts when	ed					
STATEMENT: Disconnect power and apply lockouts when)0)					
STATEMENT: Disconnect power and apply lockouts when						
I CUUII CU DY LIIIA III ALI UGLIOH. NGIGI LO GUI I GIIL						
local lockout procedures to properly shut						
down and lock out this machine. Open						
equipment and inspect dust conditions. Check						
for suspicious dust or unusual debris. If any						
unusual substance is found notify supervisor						
prior to proceeding with any further action on						
the equipment.						
THE USE OF COMPRESSED OR BLOWN AIR IS						
PROHIBITED.						
When cleaning is required, an alternative						
cleaning method such as a HEPA filtered						
vacuum cleaner or a damp rag must be used in						
place of compressed or blown air. A lint-free						
cloth or brush may be used on optical						
equipment only when other cleaning methods						
cannot be used. Report safety deficiencies to						
your supervisor immediately upon detection.						
WARNING FOR EWP/PPE:						
Steps contained in this bulletin may require the						
use of Personal Protective Equipment (PPE).						
Refer to the current Electrical Work Plan (EWP)						
MMO for appropriate PPE requirements.						

WARNING: Be cautious when working around or on equipment when power has been applied. Do not attempt to retrieve loose mail from guarded locations without locking out equipment.

NOTE: Return loose mail found while performing this checklist to locally designated locations. Do not induct or otherwise place loose mail on sorter.

SYSTEM:

2. POWER DOWN AND LOCK OUT POWER.

Power down the machine and lock out its electrical power as prescribed by the current local lockout instructions providing lockout/restore procedures.

RECIRCULATE TRANSPORT FEED SYSTEM (RTFS): B. MAIL SEARCH. Traverse accessible portions of RTFS checking for loose mail. Check all horizontal surfaces, catwalks, crossovers, screens, and surrounding platforms.

D

ΑII

2 Attachment 2

Maintenance recinical Support Senter												- 11	/11V1V	<u> </u>	1112
U.S. Postal Service	IDENTIFICATION														
Maintenance Checklist	WORK EQUIPMENT CODE ACRONYM						CLASS CODE			NUMBER			TYPE		
	2	4	S	S	Ι	U				*	*	0	0	1	M
Equipment Nomenclature Singulate Scan Induction Unit	Equ	ipmer	nt Mo	del						ename 2035af		Occurr		aily	

** Class codes = AA, BA, CA, DA, EA, FA, GA, and HA

Part or	Item No	Task Statement and Instruction	Est. Time	Min. Skill	Thresholds				
Component	INO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.		
SINGULATOR:	4.	MAIL SEARCH. Check under and around each singulator conveyor and waterfall chute for loose mail.	3	07			D		
DEBRIS REMOVAL SYSTEM:		MAIL SEARCH. Check under and around debris removal system for loose mail.	1	07			D		
BARCODE SCAN TUNNEL:		WARNING: Illumination assemblies may be HOT. Avoid contact with illumination assemblies while performing next step to avoid burns or other personal injury. MAIL SEARCH. Check under and around barcode scan tunnel for loose mail.	1	07			D		
DIMENSIONING SYSTEM:	7.	MAIL SEARCH. Check under and around dimensioning system for loose mail.	0.5	07			D		
WEIGH SYSTEM:	8.	MAIL SEARCH. Check under and around weigh system for loose mail.	0.5	07			D		
SINGULATION VERIFICATION SYSTEM:	9.	MAIL SEARCH. Check under and around singulation verification system for loose mail.	0.5	07			D		
SHOE SORTER:	10.	MAIL SEARCH. Check under and around shoe sorter for loose mail. Check transition points at 180 degree belt and recirculation takeaway / diverter.	3	07			D		
HIGH SPEED INDUCTION UNIT:		WARNING: Be cautious when working near the parcel sorter when power has been applied. Do not attempt to retrieve loose mail in the path of the moving sorter.	2*	07			D		
		MAIL SEARCH. Check under and around each high speed induction unit for loose mail. Check transition points at shoe sorter and parcel sorter.							
SYSTEM:		RESTORE EQUIPMENT TO SERVICE. Restore equipment to service as prescribed by the current local procedure providing lockout/restore procedures.	3	All			D		
REPORT:	13.	REPORT. Report all deficiencies to your supervisor including any unusual amounts of loose mail found or any unretrievable mail requiring equipment lockout.	3	All			D		

^{* ---} the tasks marked with an asterisk are per unit tasks.

Attachment 2 3

^{** ---} the tasks marked with two asterisks are critical tasks.