# MAINTENANCE TECHNICAL SUPPORT CENTER **HEADQUARTERS MAINTENANCE OPERATIONS**





# Maintenance Management Order

**SUBJECT:** Network Distribution Center (NDC)

Operational Maintenance Guidelines for the

Singulate Scan Induction Unit

**TO:** Manager Maintenance, All NDCs

**PUB NO:** MMO-136-19

DATE: September 2, 2021

FILE CODE: Y9

**FILE ID:** mm19050

**REV LEVEL:** ag

This Maintenance Management Order (MMO) provides Network Distribution Center (NDC) Operational Maintenance Guidelines for the Singulate Scan Induction Unit (SSIU). This bulletin **supersedes MMO-076-12.** The acronym is SSIU. The class codes are AA, BA, CA, CB, DA, EA, FA, GA, HA, IA, and JA.

Actual workhour requirements and the frequency of tasks are dependent on site-specific configuration. Therefore, operational maintenance workhour requirements will vary dayto-day based on site specific machine utilization. Management may modify task frequencies to address local conditions.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher-level employees from performing any of this work.

# WARNING

Various products requiring Safety Data Sheets (SDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current SDS for each product used is on file and available to all emplovees. When reordering such a product, it is suggested that current SDS be requested. Refer to SDS for appropriate personal protective equipment.

# WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

Web Access: http://www1.mtsc.usps.gov

#### WARNING

Moving conveyors may expose employees to personal safety hazards. Do not climb, sit, or walk on conveyors without first performing local Energy Control Procedure (ECP).

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Frederick L. Jackson III Executive Manager

Maintenance Technical Support Center

Asset Maintenance Planning, Performance, and Support

Attachments: 1. Summary Workload Estimate for SSIU

2. Master Checklist: 09-SSIU-\*\*-001-M

## **ATTACHMENT 1**

SUMMARY
WORKLOAD ESTIMATE
FOR SSIU

# SUMMARY WORKLOAD ESTIMATE FOR SSIU

		OPERATION	ONAL MAIN	TENANCE		
		2 HSIU			3 HSIU	
Days/Week	1 Tour	2 Tours	3 Tours	1 Tour	2 Tours	3 Tours
	Hrs/Yr	Hrs/Yr	Hrs/Yr	Hrs/Yr	Hrs/Yr	Hrs/Yr
5 Days	450.67	901.34	1,352.01	472.33	944.66	1,416.99
6 Days	540.80	1081.60	1,622.40	566.80	1,133.60	1,700.40
7 Days	630.93	1,261.86	1892.79	661.27	1,322.54	1983.81

## **ATTACHMENT 2**

#### **SSIU MASTER CHECKLIST**

09-SSIU-\*\*-001-M

Time Total: 101 minutes

\*\* Class Codes = AA, BA, CA, CB, DA, EA, FA, GA, HA, IA, & JA

U.S. Postal	Service					IDENTIFICA	TION				
Maintenance	Check	list	WORK CODE		EQUIPMENT ACRONYM			ASS ODE	NL	IMBER	TYPE
			0 9	SS	U		*	*	0	0 1	М
Equipment Nomenclature	)		Equipmer	nt Model		Bulletin File	ename	•	Occurre	ence	
Singulate Scan Ir						mm	19050			Tourly	
** Class Codes = AA		CA, CB, D					I = .				
Part or	Item No			Statement an			Est. Time	Min. Skill	Run	Threshold Pieces	rreq.
Component		(0	Comply wit	h all current s	afety precautio	ins)	Req (min)	Lev	Hours	Fed	- 1
							(111111)			(000)	
SAFETY STATEMENT	1.	Disconnerequired local l	ect power by this incourt pro- d lock of nt and incious du substant proceedit oment.  OF COI TED. teaning is method cleaner of compress orush method cleaner of compr	er and app instruction cedures to ut this ma- nspect dus ust or unu ce is foun ng with ar MPRESSE s required, such as a or a damp ssed or blo ay be used when othe Report sa immediate EWP/PPE: in this bul Protective ent Electri- riate PPE r	ry PRECAU ly lockouts a. Refer to a properly s chine. Ope st condition sual debris d notify sup by further ac an alternat a HEPA filte rag must b bown air. A l d on optical r cleaning r fety deficie ly upon def letin may re Equipment cal Work Pl requirement hen working	when current shut en es. Check If any pervisor ction on en		All			Т
SYSTEM	2.	•		wnen pow ipment Lo	ver has bee	n applied.	3	09			Т
STOTEW	۷.		•	•	y. ed or suspe	acted		03			'
			entries fro	om previou	s tour. Inve						
SYSTEM	3.	or on equestion of or	uipment the follo be runn nair, clot ng caugl a Syster	when powowing task ing. Take thing, tool thing tool to moving the walk Th	•	n applied. nat the s to quipment	30	09			Т
					ulation Tran						

U.S. Postal S	Service		1						ı	DEN	TIFI	ICATI	ION					
Maintenance	Chec	klist		ORK ODE				QUIP ACRO	MENT NYM					ASS ODE	N	UMB	ER	TYPE
			0	9	S	S	1	U					*	*	0	0	1	M
Equipment Nomenclature	)		_	uipme			•			Bul	letin	r Filer	name	1	Occurr	_	) }	
Singulate Scan Ir		n Unit	'	•							n	nm1	9050			т	ourly	
** Class Codes = AA			)A I	FA F	A G	АН	IA I	<u>۸</u> &	.IA				0000				Jany	
Part or	Item	T ., OB, .	, , , , , , , , , , , , , , , , , , ,		Stater								Est.	Min.		Thr	esholo	ls
Component	No		(Com						ecautio	ns)			Time	Skill	Run	Р	ieces	Freq.
Component			(00	p.y	ur an c	, air oi	it our	oty pro	Journal	10)			Req (min)	Lev	Hours		Fed 000)	
																(	000)	
			or/Se ingu rter, Note tion	epara lation and e any and or loo	ator, I n Ver High ano actio	Barc ifica Spe mali n.	ode tion eed I es fo	Tun Syst Induction	nel Sy em (S tion U for fu	rster SVS) Inits rthe	, r							
				ted lo			1 10 1	ne ic	cally									
		2. Ass	ess	cond	ition	of sa	•	_	rding. erly s									
		3. Ens	ure	start-	up a	larm	s an	id au	dio-vi: eratio	sual								
		4. Visi	ally core	insp	ect e	mer	geno	cy sto	op swi I or m	tche		and						
				that a			cal c	abin	et doo	rs a	re							
		con fran	duits	and and	wirir acce	ng, a ess la	nd o	check ers fo	lamag s supp or dam astene	ort s		el,						
		abn	orm		exce	ssive	e no	ises	ny obv comin									
		mad	chine	e as t	hese	ma	y be	indi	dors a cative nical p	of a	n							
									free o									
			Ss)	are c	pera	tiona	al wi	th no	er Sup red e unding	error								
		alig	clea ned lock	n, no (sens	t blo sor L	cked ED s	l by shov	debr vs blo	nd ref is, and ocked nd doe	d pro /	ope							

U.S. Postal S	Service					IDENTI	IFICAT	ION				
Maintenance	Check	list	WORK CODE		EQUIPMENT ACRONYM				ASS ODE	NL	IMBER	TYPE
			0 9	SSI	U			*	*	0	0 1	М
Equipment Nomenclature	)		Equipmer	nt Model		Bullet	tin File	name		Occurre	ence	
Singulate Scan Ir	nductio	n Unit					mm1	9050			Tourly	
** Class Codes = AA	A, BA, (	CA, CB, D	A, EA, F	A, GA, HA,	IA, & JA							
Part or	Item No		Task	Statement and	Instruction			Est. Time	Min. Skill	Run	Threshold Pieces	ls Freq.
Component	110	(0	Comply wit	h all current sa	fety precautio	ns)		Req	Lev	Hours	Fed	rieq.
								(min)			(000)	
		prob (work belts 13. Ensu are f 14. Ensu	lems with n, holes, s, etc.). ure that a ree of ma	veyor belting h tracking, to frayed, torn all chutes an ail and debr chutes are n	ension, or of lacing, mised transition is.	conditions on the second secon	on strip s					
				oving smoo								
SYSTEM: MAIL	4.			ing Process				3	09			Т
		Note type system.	, volume	e, and condit	tion of mail	in the	!					
FIXED	5.	Obtain F	MPCS R	eports.				3	10			Т
MECHANIZATION PROCESS CONTROL SYSTEM (FMPCS)		Controller computer	r or Cent : and prin	ring tasks or ral Control F t VOLUME I	Point (CCP)							
				t VOLUME I	REPORT fo	r the						
SUPERVISORY	6.	Obtain S	PC Repo	orts.				7	10			Т
PERSONAL COMPUTER (SPC):		Perform t	he follow	ing tasks or	the SPC:							
OOM OTER (SI O).				t SUMMAR` the current		ICS						
				t SUMMAR`		JLATI	ON					
		3. Run tour.	•	t FAULT RE	PORT for t	he cu	rrent					
		4. Obta	in fault r	eport for pre	evious runn	ing to	ur.					
			in recirc	ulation repo	rt from prev	vious						
SUPERVISORY	7.	Assess S	System F	Performanc	е.			10	10			Т
PERSONAL COMPUTER (SPC):		metr Optir	ics provi mization	report data ded in eithe or SSIU Op Il machine e	r the SSIU i eration guid	Syster des to	m					

U.S. Postal S	Service								IDEN	TIFIC	ATION					
Maintenance	Chec	klist	WORK CODE				QUIP ACRC	MENT NYM				_ASS ODE	NU	IMBER	1	TYPI
			0 9	S		I	U		LD	La Car E	*	*	0	•	1	M
uipment Nomenclature		. 11.2	Equipmer	IT IVI	odei				Bu		ilename		Occurre			
Singulate Scan In			A	Λ .	<u> </u>	1	Λ 0	1.0		mr	n19050			Tou	rıy	
Class Codes = AA		JA, CB, D									F=+	I N 4:	1	Thurst		
Part or	Item No		Task						,		Est. Time	Min. Skill	Run	Threst		Fred
Component			Comply with	n all	currei	nt sat	ety pre	ecautio	ns)		Req (min)	Lev	Hours	Fed (000		
			rmine ac	tior	ns red	quire	ed to	impro	ve							
			Summary	/ Sta	atistic	s Re	port 7	arget	<u> </u>		1					
		Through			7000						1					
			d to Sorte	r	>70% Proce	of T	otal F		5							
		Inducted	I to Sorter		>65% Proce			Parcels	6							
		Assigned Recircula			<30 % Proce			Parce	S							
			ummary F													
		Not Sing Parcels			<15% Proce	ssec	t									
			d Parcels		<15% Proce	ssec	ł		5							
		Multi-Re Parcels	ad		<5% ( Proce			arcels								
		HSIU Fu	II Parcels		<5% ( Proce			arcels								
		Over We Parcels	eight		<2% ( Proce			arcels								
		No Weig	ht Parcels		<2% ( Proce			arcels								
		Over Siz	e Parcels		<2% ( Proce			arcels								
		Stray Pa	ircels		<5% ( Proce			arcels								
		Unknow	n Parcels		<2% ( Proce			arcels								

U.S. Postal	Service								IDE	NTIFIC	ATION				
Maintenance	Check	list	WORK CODE					MENT NYM	,			LASS ODE	N	JMBER	TYPE
			0 9	S	S	I	U				*	*	0	0 1	М
Equipment Nomenclature	9		Equipme	nt Mo	del			L.	В	ulletin l	ilename	•	Occurr	ence	•
Singulate Scan Ir	nductio	n Unit								m	m19050			Tour	У
** Class Codes = AA	۹, BA, ۱	CA, CB, D	A, EA, F	A, G	iA, H	IA, IA	۸, &	JA							
Part or	Item No		Task	Stater	ment a	and In	struc	tion			Est. Time	Min. Skill	Run	Thresh	-
Component	140	(0	Comply wit	th all c	curren	t safe	ty pr	ecautio	ns)		Req	Lev	Hours	Piece: Fed	s Freq.
											(min)			(000)	
		parti cate secti SSIL	ck the FN cular atte gory in th on. A hi J mail tra lligned on FMPCS	entione "R gh n acking r flick	n to Reject umb g pro kerin	the " et Ma er he oblen g ind	SSII il by ere i n us lucti	J Pro Reas ndicat ually on un	ble son tes cau	m" " an used l	ру				
			1 1/11 00	VOIG				al Parc	oolo						
		SSIU Pro	blem			cesse		ai i aic	2013	1					
		and	mine preverify that ected or a	at ou	tstan	nding					ו				
		repo	nine pre rts. Add still exis	ress							nt				
SUPERVISORY	8.	Monitor S	System	Statu	us.						5	10			Т
PERSONAL COMPUTER (SPC):		Perform t	he follow	ing t	asks	on t	he S	SPC:							
SPC SPC		throu (red rang red)	the OVI ughput (g graph) ra es (gene and no a J system	greer ates erally anom	n gra are v , gre nalies	ph) a withir en sl s are	and n ac hou	recirc cepta d be	ula ble abo	tion	9				
		com Multi Syst	on the I ponents plexer (New em (URS are gree	shov MUX S), Ti	vn (c ), Un ransp	ame nivers port I	ras, sal F maç	deco Recog	dei Initi	rs, Ne ion					
		that the a are o	on the I the read acceptab displayed de OCR 16).	rate le ra d. No	for e nge : ote th	each and t hat th	can that nese	nera is no wa statis	s w arn stic	ithin ings s nov	1				
			on the A						ves	stigate					

U.S. Postal S	Service							I	DEN <sup>-</sup>	ΓIFICA <sup>°</sup>	TION				
Maintenance	Chec	klist	WORK CODE				QUIP ACRC	MENT NYM				ASS ODE	NU	IMBER	TYPE
			0 9	S	S	I	U				*	*	0	0 1	М
Equipment Nomenclature	)		Equipme	nt Mo	del			•	Bull	etin File	ename		Occurre	ence	
Singulate Scan Ir	nductio	n Unit								mm	19050			Tourl	у
** Class Codes = AA	A, BA, (	CA, CB, D	A, EA, F	A, C	A, H	A, I	A, &	JA							
Part or	Item No		Task	State	ment a	and I	nstruc	tion			Est. Time	Min. Skill		Thresho	
Component	NO	(0	Comply wit	th all o	curren	t safe	ety pre	ecautio	ns)		Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.
SEPARATION AND SINGULATION SYSTEM:	9.	Observe Operation			Т										
		Observe o	n and sir	ngula	ation.										
DEBRIS REMOVAL	10.	Check De	ebris Re	mov	al S	yste	em.				2	07			Т
SYSTEM:		Check the excessive found is re	debris i	s rer	nove	d ar	nd th	at any	ma ma	il					
BARCODE SCAN	11.	Check So	can Sys	tem	Indic	ato	rs.				4	10			Т
TUNNEL:			y that Ad												
			dy green TRIG LE						gree	٦,					
		mail, MUX apper came botto astel ???? Each spec to rig Botto for e the Z astel any o most since with posit came inves 3. Verif is on gree	e the system check the content of th	he Li sure sure of the sure of	CD d that top I that top I top	lispladed in a control of the contro	ay or odection odecti	the / ZIP (hat the ters of charmonic	Accu code e n the n. A acte offrom Back on n Back on n ecod ie ar mark The soci othe d be	sort s are e n rs (* n line. n left c, and nark ed nd an c for left- cated er LED					

U.S. Postal	Service					I	DENT	IFICAT	TION				
Maintenance	Check	list	WORK CODE		EQUIPME ACRONY					ASS DDE	NU	MBER	TYPE
			0 9	S S I	U				*	*	0	0 1	М
Equipment Nomenclature	)		Equipmer	nt Model			Bulle	tin File	name		Occurre	ence	
Singulate Scan Ir								mm1	19050			Tourly	<i>'</i>
** Class Codes = AA		CA, CB, D								1			
Part or	Item No			Statement and		-			Est. Time	Min. Skill	Run	Threshol Pieces	ds Freq.
Component		(6	Comply wit	th all current s	afety precau	utior	ns)		Req (min)	Lev	Hours	Fed	
									(111111)			(000)	
		dime LED: LED: the T	ensioning s are on s are flas TACH LE	e Accusort g unit's POV steady gre- shing yellov D appears unning, and	VER and en, PE ar v as pack steady ye	LA nd A age	AUX I es go w wh	N by, iile					
BARCODE SCAN	12.			on System					2	09			Т
TUNNEL: ILLUMINATION		1. Cheo	ck that al ational.	II SI20 sodi Ensure tha st and debi	um lights t they are								
		func	tional (tu	m camera i rns on as p ınd debris.									
BARCODE SCAN	13.	Check O	ptical Co	omponents	<b>S</b> .				2	09			Т
TUNNEL: OPTICAL COMPONENTS			specially	nses, senso bottom ca									
WEIGH SYSTEM:	14.	Verify Sc	ale Ope	ration.					2	09			Т
		scale con	troller di	results are splay and tle packages	nat they s	ee	m	e					
OPTICAL CHARACTER	15.	Verify Op System S		aracter Re	cognitio	n (	OCR)	)	2	10			Т
RECOGNITHION (OCR) SYSTEM:				sport/Imago ing tasks:	e Server (	(T/I	S) an	nd					
		NetN		ll componei ge Capture									
		and wher Anyt indic	says eith e "xxxxx hing else ates UR	ne Universa ner "URS O " represent e, such as " S degradat uires furthe	nline" or " s a token URS Onli ion (acce	'UF nu ine lera	RS xx: imber 90%' ator/s	XXX" 「. "					
				ne numbers re blocks a				een					

U.S. Postal Se	ervice								IDEI	NTIFIC	ATION						
Maintenance (	Chec	klist	WORK CODE				QUIP	MENT NYM					ASS ODE	NU	JMBE	R	TYPE
			0 9	S	S	1	U					*	*	0	0	1	М
Equipment Nomenclature			Equipme	nt Mo	del				Вι	ulletin F	ilenam	е		Occurre	ence	<u> </u>	
Singulate Scan Inc	ductio	n Unit								mr	n190	50			То	urly	
** Class Codes = AA,	, BA, (	CA, CB, D	A, EA, F	A, C	A, H	IA, I	۹, &	JA									
Part or	Item		Task	State	ment	and Ir	nstruc	tion			Es		Min.		7	shold	
Component	No	(0	Comply with	th all o	curren	t safe	ety pre	ecautio	ns)		Tin Re (mi	p	Skill Lev	Run Hours	F	ces ed 00)	Freq.
SINGULATION VERIFICATION SYSTEM:	16.	dust a	re that th and debr	ne Bl ris.	ack I	Refe	renc	e Bar	is	free o		3	09				Т
		the di	h, width mensior seem rea	, heig ning f	ght, e rame	etc.) e dis	are play	displa pane	yin I ar	ig on nd tha	t						
SINGULATION VERIFICATION SYSTEM: OPTICAL COMPONENTS	17.	Check Op Ensure so free of du	anner le	ense	s, se		s, ar	nd ref	lect	tors a	re	•	09				Т
SINGULATION VERIFICATION SYSTEM: DATA COLLECTION SYSTEM (DCS)		2. Monit SingF (unkn Also d	Log.  CTRL-/ ay the tra or the lo Res=N (r own sing check the ayed and	ALT- ackin g an non-s gulat at we I that	2 on g log d no singu ion) eight t they	the (ca te if lated resu resu / see	DCS n be exce d) or lts a	com left ru ssive Singl re pre ire be	puto unn (> Res esei	er to ning). 10%) s=? nt.			10				Т
SHOE SORTER:	19.	Check Ai Ensure su			•		ıge r	eads	80	psi.	1		09				Т
SHOE SORTER: SLATTED SHOE CONVEYOR	20.	shoe slats, 2. On th On light is ade gauge 3. Verify adequates	n. re that no sorter moshoes, or e Orscouth is lit, equate, as reads to the control of the contr	o ma echair oiler that and t 30 ps slat brica	nil or anisn ns, et the c hat th si. carr	debrander  debrander	ris is etween at the vel in the character of the characte	jammen the who the realir pre	ite ese ess e b	Poweervoirure	r	-	09				Т

U.S. Postal	Service						IDENTIFICA	TION					
Maintenance	Check	list	WORK CODE			JIPMENT RONYM			ASS ODE	NU	JMBI	ER	TYPE
			0 9	S S	ΙU	J		*	*	0	0	1	М
Equipment Nomenclature	)		Equipme	nt Model			Bulletin Fil	ename		Occurr	ence		
Singulate Scan II							mm	19050			To	ourly	
** Class Codes = AA		CA, CB, D											
Part or	Item No			Statement				Est. Time	Min. Skill	Run	_	esholo eces	s Freq.
Component		(	Comply wit	th all currer	nt safety	precautio	ns)	Req	Lev	Hours		ed	1 104.
								(min)			(0	000)	
		5. Chece exces 6. Chece or oth 7. Visual chain frame appea (almost) 8. Verify skew	ng during are dam  k that divided in the servise of	I note the damaged of that the wn block one exit of naged and ing chain as slats are any app	ert proomissin re not le prese slats. white s mou the dr nd prop at clo er runni parent	cess and g. banging ence of a plastic on tied on eive-end perly adjusest pointing true a skewing	or  any bent  carrying the inside bullwheel usted nt).  and not						
HIGH SPEED INDUCTION UNIT:	21.	Assess ( Units (HS		n Of Hig	h Spe	ed Indu	ction	5*	10				Т
(HSIU)				veyor bel missing			trip belts)						
				RUN lig			J control						
		appea conve that the	ar to be s eyors sto	sliding ex p and sta	cessiv art. Th	ely whe	ackages n indication ng is worn						
		induc sortin inordi the H	ting pacl g machi inate am SIU and	ount of m	operly ) and t nail on teturn a	onto the hat there the floo any mail							
		* time per	r unit										
REPORT:	22.	Report.						3	All				Т
				ork ordei			that erated for						

U.S. Postal S	Service									IDEI	NTIFICAT	ΓΙΟΝ					
Maintenance	Chec	klist		DRK DDE					MENT			_	LASS ODE	N	UMB	ER	TYPE
			0	9	S	S	I	U				*	*	0	0	1	M
Equipment Nomenclature	)		Equ	ipme	nt Mo	del				Вι	ulletin File	ename		Occur	ence		
Singulate Scan Ir	nductio	n Unit		m											T	ourly	
** Class Codes = AA	A, BA, C	CA, CB, D	Task Statement and Instruction Est. Min. Thresholds														
Part or	Item			Task	State	ment	and	Instru	Est.	Min.		Thre	eshold	ls			
Component	No	((	Comp	oly wit	th all o	curre	nt sa	ety pr	ecauti	ons)		Time Req (min)	Skill Lev	Run Hours	F	eces Fed 000)	Freq.
		Docu action     Inforr outsta	ns ta n ind	ken comi	in th	e ec	quip of an	ment y op	log b en log	oook gs a	ζ.						