MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE



Maintenance Management Order

SUBJECT: PM Guidelines for Ventilation/Filtration System **DATE:** February 12, 2007

(VFS) (Accusort) - 010

NO: MMO-007-07

TO: All Ventilation/Filtration Sites FILE CODE: W2

sban:mm05058ac

		Online Change Record								
Change #	Date	Description of Change								
1 07/07/2022 Updated the skill level numbers to coincide with the current skill level										
		designations for Attch. 2, Item No 2 and 3, Attch.3, Item No 2, and								
Attch. 4, Item No 2, 3, and 4.										

This Maintenance Management Order (MMO) provides Preventive Maintenance (PM) Guidelines for the Accusort VFS. This MMO addresses the VFS associated with the Dual Pass Rough Cull (DPRC) and the Loose Mail System (LMS).

The minimum maintenance skill to perform each task on the VFS guideline is included in the minimum skill level column. However, this does not preclude higher level employees from performing any of these tasks.

The workhours represented in this MMO reflect the maximum workhours required to maintain the equipment. Given local conditions, management may modify task frequencies.

Maintenance Managers are to use these preventive maintenance guidelines when preparing the route sheets for local maintenance personnel. It is the responsibility of each Maintenance Manager to ensure all WARNINGS, CAUTIONS, and NOTES are included with each applicable task as part of the preparation of any local route sheets.

WARNING

Various products, which require Material Safety Data Sheets (MSDS), may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available for reference by all employees. Refer to MSDS for appropriate personal protective equipment.

WARNING

The use of compressed or blown air is prohibited. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or damp rag must be used in place of compressed or blown air. A lint-free cloth or brush

Web Access: https://www1.mtsc.usps.gov

may be used only on optical equipment when other cleaning methods can not be used.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Earl J. Jones Manager Maintenance Technical Support Center Maintenance Policies and Programs

Attachments: 1. Summary Workload Estimate for VFS – 010

2. VFS Master Checklist: 03-VFS-BA-001-M: Daily PM

3. VFS Master Checklist: 03-VFS-BA-002-M: Weekly PM

4. VFS Master Checklist: 03-VFS-BA-003-M: Monthly PM

SUMMARY

WORKLOAD ESTIMATE

FOR

ACCUSORT

 $\label{eq:VENTILATION} \textbf{VENTILATION/FILTRATION SYSTEM (VFS)} - \textbf{010}$

SUMMARY WORKLOAD ESTIMATE FOR VFS

Operation		Repair Time	Total	Non-	Operational	Total Time
	Servicing Per		Servicing		Maintenance	
	Machine	(hrs/yr)*	Time Per	Time Per	Time Per	(hrs/yr)
	(hrs/yr)		Machine	Machine	Machine	
			(hrs/yr)	(hrs/yr)**	(hrs/yr)	
5 day	66.3	3.3	69.7	7.0	0	76.6
6 day	75.9	3.8	79.7	8.0	0	87.6
7 day	85.4	4.3	89.7	9.0	0	98.6

Times presented are for single units. For multiple machines, multiply time by number of units.

- * Repair estimates based on 5% of servicing.
- ** Based on 10% of servicing and repair.

PM CHECKLIST TIME SUMMARY

CHECKLIST	CHECKLIST TIMES
03-VFS-BA-001-M (Daily)	11 min
03-VFS-BA-002-M (Weekly)	16 min
03-VFS-BA-003-M (Monthly)	24 min

VFS MASTER CHECKLIST

03-VFS-BA-001-M

DAILY

Time Total: 11 Minutes

ΑII

9

U.S. Postal Service								IDE	NTIF	ICATI	ON					
Maintenance Checklist	WORK EQUIPMENT CODE ACRONYM											CLASS CODE		UMBE	TYPE	
	0	3	٧	F	S						В	Α	0	0	1	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	ulletir	ı Filer	name	F	reque	ency		
Ventilation/Filtration System								MM05058AC								

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	s
Component	No	(Comply with all current safety precautions)	Time	Skill			
			Req	Lev	Run	Pieces	Weeks
			(min)		Hours	Fed	
						(000)	

SAFETY STATEMENT

Disconnect power and apply lockouts when MIN required by this instruction. Refer to current local lockout procedures to properly shutdown and lockout this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

WARNING

Be cautious when working around or on equipment when power has been applied.

DUAL PASS ROUGH CULL Check DPRC for loose framework. – Check the 2 DPRC for loose or damaged curtains, framing, or MIN ducting. Report any problem found to the maintenance supervisor.

LOOSE MAIL SYSTEM 3. Check LMS for loose framework. – Check the 3 9 LMS for loose or damaged curtains, framing, or MIN ducting. Report any problem found to the maintenance supervisor.

CLEAN UP

 Clean up. – Ensure all tools, lubricants, rags, etc., 3 All are removed from the work area. Report all MIN deficiencies to your supervisor.

VFS MASTER CHECKLIST

03-VFS-BA-002-M WEEKLY

Time Total: 16 Minutes

ΑII

U.S. Postal Service							IDI	ENTIF	ICAT	ION					
Maintenance Checklist	WC CO	RK DE				 MEN ⁻				CLASS CODE		Ν	UMBI	TYPE	
	0	3	٧	F	S					В	Α	0	0	2	M
Equipment Nomenclature Equipment Nomenclature Ventilation/Filtration System		ipmer	nt Mo	del			E	Bulletir M I		name 058AC		reque	,	EKL	Υ

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	s
Component	No	(Comply with all current safety precautions)	Time	Skill			
			Req	Lev	Run	Pieces	Weeks
			(min)		Hours	Fed	
						(000)	

SAFETY STATEMENT

1. COMPLY WITH ALL SAFETY PRECAUTIONS. 3
Disconnect power and apply lockouts when MIN required by this instruction. Refer to current local lockout procedures to properly shutdown and lockout this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

WARNING

Be cautious when working around or on equipment when power has been applied.

ACCUSORT VFS HOUSING

2. Check and clean perforated plate. – Check the 10 9 perforated plate to ensure no damage has MIN occurred. Clean or vacuum the inlet section and perforated plate if necessary. Report any problem found to the maintenance supervisor.

CLEAN UP

3. **Clean up. –** Ensure all tools, lubricants, rags, etc., 3 All are removed from the work area. Report all MIN deficiencies to your supervisor.

VFS MASTER CHECKLIST

03-VFS-BA-003-M

MONTHLY

Time Total: 24 Minutes

ΑII

U.S. Postal Service	IDENTIFICATION															
	WC	ORK			F	QUIF	PMENT	Γ			CLA	ISS	N	UMBE	ΞR	TYPE
Maintenance Checklist	CO	DE				ACR(MYNC		CODE							
	0	3	V	F	S						В	Α	0	0	3	M
Equipment Nomenclature	Equ	Equipment Model						В	Bulletin	ı Filer	name	F	Frequency			
Ventilation/Filtration System									١M	M050	058AC	;		MON	NTHL	∟Y

Co	Part or omponent	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	s
				Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

SAFETY STATEMENT

1. COMPLY WITH ALL SAFETY PRECAUTIONS. 3
Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shutdown and lockout this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

WARNING

Be cautious when working around or on equipment when power has been applied.

ACCUSORT VFS SYSTEM

Check and clean motor. – Visually check motor. 5
 Keep motor clean and the ventilation openings MIN clear. Verify automated oiler is functioning properly. See Accusort/Siemens VFS Maintenance Guide, NSN 7610-08-000-1118. Report any problem found to the maintenance supervisor.

ACCUSORT VFS SYSTEM 12 AND 18K ONLY

3. Check fan V-belt. – Check fan V-belt for wear, 10 9 tension, and pulley alignment. See MIN Accusort/Siemens VFS Maintenance Guide, NSN 7610-08-000-1118. Report any problem found to the maintenance supervisor.

U.S. Postal Service	IDENTIFICATION															
Maintanana Chaaldist	_	RK			_		MEN	-				ASS	N	UMBI	ĒR	TYPE
Maintenance Checklist	CO	DE			ACRONYM						CODE					
	0	3	V	F	S						В	Α	0	0	3	М
Equipment Nomenclature	Equ	Equipment Model					Е	Bulletin	name	ı	Frequency					
Ventilation/Filtration System									MN	M050	058AC	;	MONTHLY			

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill	,	Threshold	S
·			Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

ACCUSORT SYSTEMS Check control panel components. – Check 3 10 visually inside control panel electrical components MIN for signs of over heating. Report any problem found to the maintenance supervisor.

CLEAN UP

5. **Clean up. –** Ensure all tools, lubricants, rags, etc., 3 All are removed from the work area. Report all MIN deficiencies to your supervisor.