

SPECIFICATION

Product Name: Complex air quality measurement module

Model: AM1008W-K

Version: V1.1

Date: May 5, 2020

Writer	Audit	Approved
Kwon		Kwon



Revision

No.	Version	Content	Reviser	Date
1	V1.0	First release	Kwon	2019–07-17
2	V1.1	Correction of temperature and humidity measurement range and accuracy. (See specifications) Corrected the measurement range of temperature and humidity. (Refer to protocol specification)	Kwon	2020-05-05

www.gassensor.com.cn 1/18



Complex air quality measurement module

AM1008W-K



Applications

- Air purifier
- Air quality monitor
- Air conditioner
- Ventilation system
- Consumer electronic products
- Environmental monitoring

Description

AM1008W-K is an indoor complex air quality measurement module with a built-in highly integrated ultra-thin laser particle sensor, NDIR CO2 sensor, semiconductor VOC sensor, temperature, and humidity sensor, and can output digital measurement data in real-time. It is reliable performance, compact structure design, multi-function, and optional connection method that can be widely used in IAQ monitors, air purifiers, ventilation systems, air conditioners, etc.

Features

- Highly integrated with sensors including laser particle, NDIR CO2, VOC, temperature, humidity for option
- The NDIR CO₂ sensor is with high low power consumption, auto-calibration
- Ultra-thin (height is only 12mm) laser particle sensor with four working mode
- Easy to install and debugging simply
- With voltage regulator design and EMC compliant, strong anti-static ability

Working Principle

- The PM sensor integrated adopts laser scattering technology to simultaneously detect PM1.0, PM2.5, PM10 mass concentration
- The CO₂ sensor integrated adopts NDIR technology to detect indoor CO₂ concentration
- The VOC sensor is based on semiconductor principle
- The RH&T sensor integrated adopts capacitance resistance materials to detect indoor RH&T

www.gassensor.com.cn 2/18


Specifications

Integrated Indoor Air Quality Sensor Specification				
Operating principle	CO ₂ : NDIR technology PM: laser scattering technology VOC: semiconductor			
Measurement range	PM: 0 ~ 1,000ug/m³ CO ₂ : 0 ~ 5,000ppm VOC: 0 ~ 3 level Temperature: -40°C ~ 85°C RH: 5 ~ 95%RH			
Maximum consistency error for PM1.0/PM2.5	≤100ug/m³, ±10ug/m³ >100ug/m³, ±10% of reading Condition: 25 ±2°C, 50±10%RH, Reference instrument: GRIMM 11-A Dust Source: Cigarette + Arizona A1			
Maximum consistency error for PM10	0 ~ 100ug/m³, ±25ug/m³ 101 ~ 1,000ug/m³, ±25% reading Condition: 25 ±2°C, 50±10%RH, Reference instrument: GRIMM 11-A Dust Source: Cigarette + Arizona A1			
CO ₂ measurement accuracy	± (50ppm+5% of reading) @25 ±2°C, 50 ±10%RH ± (50ppm+3% of reading) @25 ±2°C, 50 ±10%RH (Option)			
Temperature accuracy	±0.4 °C (max), -10 ~ 85 °C			
Humidity accuracy	± 3% RH (max), 0 ~ 80% RH			
PM preheating time	≤8 sec			
CO ₂ preheating time	≤30 sec			
VOC preheating time	≤120 sec			
Data refresh rate	1 sec			
Working condition	-10 ~ 50°C, 0 ~ 99%RH (Non-condensing)			
Storage condition	-20 ~ 60°C, 0 ~ 99%RH (Non-condensing)			
Working voltage	DC 5V ±0.1V, ripple wave < 50mV			
Average working current	≤300mA			
Signal output	UART TTL (3.3V TTL), I2C			
Dimension	W80mm × H50mm × D13.6mm			
Life span	MTTF of PM sensor= 110,000Hrs (continuous turn on) CO2 ≥10 years VOC ≥10 years			


www.gassensor.com.cn 3/18



1. Dimensions (Unit mm, tolerance ±0.2 mm)



2. I/O Connector Pin map



No.	Pin	Description
1	GND	Power supply input (GND)
2	RX/SDA	UART-RX input (TTL@3.3V) / I2C data
3	TX/SCL	UART-TX output (TTL @3.3V) / I2C Clock
4	+5V	Power supply input (+5V)


3. Connector and Cables

Item	Part Number	Pitch	Recommendation Manufacturer
Connector	12505WR-04	1.25mm	YEONHO ELECTRONICS
Cables	12505HS-04	1.25mm	YEONHO ELECTRONICS


www.gassensor.com.cn 4/18




Application 1: UART TTL 3.3V UART output



Application 2: I2C 3.3V output



Test scenarios 3: 3.3V ~ 5V switching circuit diagram




www.gassensor.com.cn 5/18



Temperature Influence Curve

PM Temperature Influence Curve



Measured error: under 25°C ± 2 °C, 50 $\pm 10\%$ RH, 0 ~ 1,000ug/m³, consistency and accuracy of PM1.0/PM2.5 is $\pm 10\%$ reading or ± 10 ug/m³, take the biggest value

Temperature influence coefficient: 0.5%°C ~ 1%°C or 0.5ug/m³/°C ~ 1ug/m³/°C, take the biggest value.

www.gassensor.com.cn 6/18




Product Installation

When installing the AM1008W-K Module in a system or equipment, ensure the air intake and air outlet are not blocked. And there should be no huge airflow to the air inlet and air outlet.

• In order to avoid dust deposition on the surface of the sensitive component (laser diode and photosensitive diode), which may affect the measurement accuracy of the sensor, the appropriate installation ways are recommended as below.

Recommended

Non-Recommended



www.gassensor.com.cn 7/18



User Attention

- AM1008W sensor module is for household electronics products. For application of medical, mining, disaster preparedness, which needs high security and high dependence, this sensor is not suitable.
- The laser dust sensor adopts non-static adsorption materials such as metal, please avoid to working under the high particle concentration environment.
- When you use the laser dust sensor, please make sure of unobstructed air-inlet and air-outlet. The CO₂, VOC using diffusion for sampling, the gas diffusion hole should be reserved.
- •This sensor module should avoid working outdoors or in the heavy dust environment. Protection against sandstorm, rain, snow and willow floccus should be completed by the user equipment.
- When using the laser dust sensor, it's recommended to add 50 ~ 60 mesh protective filters to the air inlet position, to prevent the pollution of large particles of dust, floccules, hair etc on the detection data.
- When the sensor module is applied to air purifier or detection equipment, the sensor should be installed more than 20cm above the ground, to avoid the fan couldn't work normally due to the pollution of large dust and floccus.

Caution

If "UART Command" is transmitted within 10 seconds after the power is supplied to the AM1008W-K, the sensor module is fixed to "UART Communication Mode".

When using AM1008W-K in I2C communication mode, 10 seconds must elapse after power is supplied.

Or

UART or I2C communication can be selected with a jumper inside the meter.

When shipped from the factory, it is basically set to UART communication.

www.gassensor.com.cn 8/18



UART Communication Protocol

1. General Statement

- 1). The data in this protocol are all hexadecimal data. Such as "46 for decimal [70]"
- 2). [xx] for single-byte data (unsigned, 0 ~ 255); high byte of double byte data is in the front, the low byte in the back
- 3). Baud rate: 9,600, data bits: 8, stopbits:1, parity: No.

2. Format of Serial Communication Protocol

Sending format of software:

Start Symbol	Length	Command	Data 1	 Data n.	Check Sum
HEAD	LEN	CMD	DATA1	 DATAn	cs
11H	XXH	XXH	XXH	 XXH	XXH

Detail description on protocol format:

Protocol Format	Description	
Start	Command sending fixed [11H], the module respond fixed [16H]	
Length	Frame bytes length= data length +1 (including CMD+DATA)	
Command	Command	
Data	Data of writing or reading, unfixed length	
Check sum	Cumulative sum of data= 256 - (HEAD+LEN+CMD+DATA)	

3. Command Table of Serial Protocol

Item No.	Function Description	Command		
1	Read measurement result	0x01 0x01		
2	CO ₂ calibration	0x03		
3	Open / close particle measurement	0x0C		
4	Set up and read particle measurement time	0x0D		
5	Set up and read timing measurement mode	0x05		
6	Set up and read dynamic working mode	0x06		
7	Set up and read particle calibrated coefficient	0x07		
8	Open / close laser diode	0x08		
9	Read software version 0x1E			
10	Read serial number	0x1F		

www.gassensor.com.cn 9/18



4.Protocol Description

4.1 Read Measurement Result

Send: 11 02 01 01 EB (DF0 added)

Response: 16 16 01 DF1 DF2 DF3 DF4 DF5 DF6 DF7 DF8 DF9 DF10 DF11 DF12 DF13 DF14 DF15 DF16 DF17

DF18 DF19 DF20 DF21 [CS]

Function: to read CO₂, VOC, RH, Temp, PM1.0, PM2.5, PM10, VOC Now / Ref. %, VOC Ref. R Value, VOC Now R

Value [CS]
Statement:

Response data bit:

16 16 01 02 C2 00 03 00 32 00 19 00 53 00 63 00 73 00 64 00 FA 00

Item	Data Bit	Decimal Effective Value Range	Corresponding Value	Multiple
CO ₂	[DF1] [DF2]	0 ~ 5,000	0 ~ 5,000 ppm	1
VOC	[DF3] [DF4]	0 ~ 3	0 ~ 3 level	1
Related humidity	[DF5] [DF6]	50 ~ 990	5.0 ~ 99.0 %	10
Temperature	[DF7] [DF8]	100 ~ 1,350	-40 ~ 85°C	10
PM1.0 (GRIMM)	[DF9] [DF10]	0 ~ 1,000	0 ~ 1,000ug/m ³	1
PM2.5 (GRIMM)	[DF11] [DF12]	0 ~ 1,000	0 ~ 1,000ug/m ³	1
PM10 (GRIMM)	[DF13] [DF14]	0 ~ 1,000	0 ~ 1,000ug/m³	1
VOC Now / Ref. %	[DF15] [DF16]	0 ~ 1,000	0 ~ 1,000%	1
VOC Ref. R Value	[DF17] [DF18]	0 ~ 65,000	0 ~ 650,000Ω	0.1
VOC Now R Value	[DF19] [DF20]	0 ~ 65,000	0 ~ 650,000Ω	0.1
PM Sensor State	[DF21]			1

1. Temperature data is added 500 upon practical measurement result.

For example, -20°C is corresponding to value 300. Temperature value= (DF7 * 256 + DF8 - 500) / 10.

2. The measurement result comes out with two data bits, high bit is on the head, and the low bit is after then. Measurement result= DF_n * 256 + DF_{n+1}

3. Status bit: status alarming. (When the working temperature and fan speed of PM2008 is abnormal)

Byte	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0
Alarming	Reserved	Reserved	Reserved	Reserved	1: Working temperature is low	1: Working temperature is high	1: Fan at low revolving speed	1: Fan at high revolving speed

4.2 CO₂ Calibration

Send: 11 03 03 DF1 DF2 [CS]

Response: 16 01 03 E6
Function: CO₂ calibration

www.gassensor.com.cn 10/18



Statement: Format statement:

Item	Data Bit	Decimal Effective Value Range	Corresponding Value	Multiple
Calibration target value	[DF1] [DF2]	400 ~ 1,500	400 ~ 1,500 ppm	1

- 1. Calibration target value= DF1 * 256 + DF2
- 2. Before CO_2 calibration, make sure that the current ambient CO_2 value is the target value you want to calibrate and that the stable time is at least 2 minutes.

4.3 Open and Close Particle Measurement

Send: 11 03 0C DF1 1E [CS] **Response:** 16 02 0C DF1 [CS]

Function: open and close particle measurement

Statement:

- 1. When send command, DF1= 02 is measurement open; DF1= 01 is measurement close;
- 2. When respond command, DF1= 02 is measurement open; DF1= 01 is measurement close;
- 3. When the sensor receives command for measurement open, it will go into continuous measuring mode;

If send: 11 03 0C 02 1E C0 // open particle measurement

Response: 16 02 0C 02 DA // the sensor module is under measurement open status

If send: 11 03 0C 01 1E C1 // close particle measurement

Response: 16 02 0C 01 DB // the sensor module is under measurement close status

4.4 Set up and Read Particle Measuring Time

Send: 11 03 0D DF1 DF2 [CS] // set up particle measuring time **Send:** 11 01 0D E1 // read particle measuring time

Response: 16 03 0D DF1 DF2 [CS] **Function:** Read particle measuring time

Note:

- 1. Particle measuring time= DF1 * 256 + DF2, unit is second. Minimum measuring time is 36 seconds. Time range is 36 ~ 65,535 seconds. After setting up xx seconds particle measuring time, the sensor will stop working first, then you can send "Open / command" to start single xx seconds measuring.
- 2. When measuring time is \geq 65,531, it means module will be in continuous measuring mode once powered on. It will not stop until "stop" command is sent.

Continuously working mode:

When continuously measuring mode is set, sensor situation is 2. When PM1.0 is less than 5ug/m³, then measuring is close (situation changes to 0x80, only the laser diode turns off for 5 seconds) and outputs the last value in standby mode. After 5 seconds, the PM sensor resumes the measurement for 4 seconds, If PM1.0 measuring data within the 4sec is less than 5ug/m³, then measuring is close (situation changes to 0x80, only the laser diode turns off for 5 seconds). Otherwise, the sensor will go ahead testing until the PM1.0 measuring data is less than 5ug/m³.

www.gassensor.com.cn 11/18



Example:

Send: 11 03 0D 00 24 BB // set up single measuring mode; measuring time is 36sec

Response: 16 03 0D 00 24 B6 // measuring time is set up successfully

Send: 11 03 0D FF FF E1 // set up continuously measuring mode (Repowering on means to start measuring status)

Response: 16 03 0D FF FF DC // continuously measuring mode is set up successfully

Send: 11 01 0D E1 // read particle measuring time **Response:** 16 03 0D FF FF DC // read successfully

4.5 Set up Timing Measuring Mode

Send: 11 03 05 DF1 DF2 [CS] // set up particle measuring mode

Send: 11 01 05 E9 // read particle measuring mode

Response: 16 03 05 DF1 DF2 [CS] **Function:** Read particle measuring time

Note:

1. Particle measuring mode value X= DF1 * 256 + DF2, unit is second;

2. When X >=180, it means module is under timing measuring mode. Measurement timing cycle is X seconds.

The sensor module will start measurement every X second. Default measuring time is 36 seconds.

3. Range for X, minimum timing period is 3 minutes

Send: 11 03 05 02 05 E0 // Set up as timing measuring mode, and timing cycle is 517 seconds.

Response: 16 03 05 02 05 DB // Set up successfully

4.6 Set up Dynamic Measuring Mode

Send: 11 02 06 DF1 [CS] // Set up dynamic particle measuring mode **Send:** 11 01 06 E8 // Read dynamic particle measuring mode

Response: 16 02 06 DF1 [CS]


Function: Read / set up particle dynamic measuring mode

Note:

1. Particle dynamic measuring mode result DF1.

2. When DF1= 0, close dynamic measuring mode. When DF1= 1, start dynamic measuring mode.

Dynamic Working Mode:



www.gassensor.com.cn 12/18



After sensors are in dynamic working mode, start measuring every 30sec. The sensor starts the measurement for the first 3 seconds.

After 3 seconds of measurement, the sensor starts measuring again continuously for 16 seconds and outputs the B value

The laser diode turns off for 11 seconds, enters the standby state, and outputs the B value.

After the first 30 second period, the sensor starts a new 3 second measurement and outputs the A value.

① If $|A-B| > 10ug/m^3$ or |A-B| / B > 10%, the sensor selects Dynamic mode 1. The sensor measures continuously for 16 seconds and outputs the C value.

The laser diode turns off for 11 seconds, enters the standby state, and outputs the C value.

② If | A-B | <10ug/m³ or | A-B | / B <10%, the sensor selects Dynamic mode 2 and stores A value, then enters standby state for 27 seconds and outputs A value.

Regardless of the dynamic mode A or B, the sensor starts a new 30 second measurement cycle by starting the initial 3 second measurement. Compare the measured value with the previously stored value for the initial 3 seconds and select Dynamic mode 1 or 2 again.

Send: 11 02 06 01 E6 // Set up opening dynamic particle measuring mode

Response: 16 02 06 01 E1 // Set up successfully

Send: 11 02 06 00 E7 // Set up closing dynamic particle measuring mode

Response: 16 02 06 00 E2 // Set up successfully

The module can support 4 kinds of working mode (Single + Continuous + Timing + Dynamic).

It can be switched between these 4 kinds of working mode.

It is continuous working mode by default after leaving factory.

These 4 kinds of working mode can be switched by sending commands, as following:

- 1. Send: 11 03 0D 00 24 BB // Single measuring mode, time is 36sec
- 2. Send: 11 03 0D FF FF E1 // Continuously measuring mode
- 3. Send: 11 03 05 02 05 E0 $\!\!\!//$ Timing measuring mode, interval time is 517 seconds
- 4. Send: 11 02 06 01 E6 // Dynamic measuring mode

4.7 Set up and Read Particle Calibrated Coefficient

Send: 11 02 07 DF1 [CS] // Set up particle calibrated coefficient. DF1 means calibrated coefficient

Send: 11 01 07 E7 // Read particle calibrated coefficient

Response: 16 02 07 DF1 [CS]

Function: Read / set up particle calibrated coefficient

Note:

1. Range 70 ~ 150. Corresponding coefficient: 0.7 ~ 1.5. [DF1: 64(HEX) → 100(DEC) → 1.0]

Description:

- 1. When there is difference between standard device, calibrated coefficient can be set to correct the final value.
- 2. When calibrated coefficient is set, the value of PM1.0, PM2.5, and PM10 will be all corrected by this coefficient.

www.gassensor.com.cn 13/18



4.8 Close / Open Laser Diode

Send: 11 02 08 04 E1 // Close laser diode

Send: 11 01 08 E6 // Read status **Response:** 16 02 08 04 DC

Note:

When laser diode is closed, the sensor will stop measuring but the FAN will stay working. The measuring data will keep the same with the last time measured data. If to open the laser diode again, you can use "Open/ close particle measurement' command.

4.9 Read Software Version Number

Send: 11 01 1E D0

Response: 16 0B 1E DF1 DF2 DF3 DF4 DF5 DF6 DF7 DF8 DF9 DF10 [CS]

Function: Read software version

Note:

Software version= "DF1 ~ DF10"

Should change the HEX code to ASCII code.

Example:

HEX code: 16 0E 1E 50 4D 20 56 31 2E 32 36 2E 35 2E 32 38 E9

ASCII code: PM V1.26.5.28

4.10 Read Serial Number

Send: 11 01 1F CF

Response: 16 0B DF1 ~ DF10 [CS] **Function:** Read serial number

Note: Serial number= DF1 ~ DF10

Example:

Response: 16 0B 1F 00 00 00 7E 09 07 07 0E 0D 72 9E

Serial number: 126 2311 1806 3442

4.11 VOC sensor baseline adjustment

Send: 11 03 09 00 00 E3

Response: 16 03 09 00 00 CS

Function: To do baseline adjustment of VOC sensor

Note: 00 00 is the reserved byte

www.gassensor.com.cn 14/18



I2C Communication Protocol

1. Brief Introduction

This is an I2C protocol for AM1008W. The sensor module is lower computer, which is not able to initiate communication automatically. Communication is initiated via main controlled board, which reads data and sends control commands.

I2C Communication clock frequency <=30Khz.

2. Communication Common Description

START: start signal, send by main controlled board; STOP: stop signal, send by main controlled board;

ACK: acknowledge signal, send by the sensor module if in bold; otherwise, send by main controlled board;

NACK: non-acknowledge signal, send by the sensor module if in bold; otherwise, send by main controlled board;

Dx: receive and send data; send by the sensor module if in bold; otherwise, send by main controlled board.

3. Protocol Detailed Description

3.1 Send Command Data

Receive by main controlled board:

START+WRITE+ACK+D1+ACK+ D2+ACK...... +D7+ACK+STOP

Data	Byte Content	Description
Device address	Sensor address and read / write command	This byte is 0x 50 when write data
D1	0x16	Frame header
D2	Frame length	Number of bytes, not including the length of device address (From D1 to D7, 7 bytes in total)
D3	Data1	Control command of the PM Sensor: Close measurement: 0x01; Open measurement: 0x02 Set up single measurement: 0x0D Set up continuously measurement: 0x0C Set up timing measurement: 0x05; Set up dynamic measurement: 0x06 Other function: CO ₂ calibration: 0x03; Set up PM calibration coefficient: 0x07
D4	Time data, high byte DF1/CO ₂ Calibration value, high byte / PM Coefficient	Time data: Set the working mode time of PM2.5 sensor Total time= DF1 * 256 + DF2, Unit(s) Details as below: CO ₂ Calibration value= DF1 * 256 + DF2, Unit: ppm;
D5	Time data, low byte DF2/CO ₂ Calibration value, low byte	PM Coefficient: Set the coefficient of Dust sensor
D6	Reserve	
D7	Data check code	Check code= (D1^D2^^D6)

www.gassensor.com.cn 15/18



Description and Setting Working Mode for PM Sensor

- 1. PM Sensor power on default continuously working mode
- 2. PM Sensor have 4 working mode: continuously measure, dynamic measuring, single measurement, timing measurement. It must be in one of working mode when the sensor power on.
- 3. PM Sensor can be switched in all the working modes, when power off, it will not save the working mode. If power on again, it defaults continuously working mode

4. Dynamic Measuring Mode:

After sensors are in dynamic measuring mode, the measuring cycle is 30 seconds.

The sensor starts the measurement for the first 3 seconds. If measuring result within 3 seconds compared with the last time measured result meets situation ① the sensor will go on testing for another 16 sec, then the measurement is closed for 11 sec (only laser diode is off) until next new 30 sec measuring cycle.

Change range is >±10ug/m³ or >±10%

If measuring result within 3 seconds compared with the last time measured result meets situation ②, the measurement is closed for 27 sec until the next new 30 sec measurement cycle starts.

- ② Change range is $<\pm 10$ ug/m³ or $<\pm 10$ %
- 5. Timing mode and single mode need to combine with P4, P5 to set the time. Details as below table:

PM Sensor Mode	D4	D5	Description	Remark
Class	Close		Byte data is no meaning to	
Close			measurement	
Onon			Byte data is no meaning to	After closed then open the
Open	 -	·	measurement	measurement mode like before
			Single measurement range:	
Single measurement	DF1	DF2	36 ~ 65,530 Unit: sec	
			It's invalid if not in this range	
Continuously			Byte data is no meaning to	
measurement			measurement	
			Timing measurement range:	Start the measurement for
Timing measurement	DF1	DF2	180 ~ 65,530 Unit: sec	each cycle, and the
			It's invalid if not in this range	measurement time is 36 sec
Dynamic	Dynamic measurement		Byte data is no meaning to	
measurement			measurement	

Other description:

- 1. Set the PM coefficient, calibration coefficient range: 70 ~ 150, Corresponding calibration coefficient: 0.7 ~ 1.5.
- 2. Set the calibration value of CO_2 , the range is $0 \sim 1,500$ ppm.
- 3. CO_2 measurement range is $0 \sim 5,000$ ppm.

www.gassensor.com.cn 16/18



Read Data Command

Send by main controlled board: START+READ+ACK+D1+ACK+D2+ACK+.....+D25+NACK+STOP

Data	Byte Content	Description		
Device address	Sensor address and read / write command	This byte is 0x 51 when read data		
D1	0x16	Frame header		
D2	Frame length	Number of bytes, not including the length of device address. (From D1 ~ D25, 25 bytes in total)		
D3	PM sensor operation mode	Close: 0x00 / Single measuring mode: 0x0D / Continuous measuring mode: 0x0C / Timing measuring mode: 0x05 / Dynamic measuring mode: 0x06		
D4	Data 1 High byte	COs concentration. Unit: nnm		
D5	Date 1 Low byte	CO ₂ concentration, Unit: ppm		
D6	Data 2 High byte	VOC level output		
D7	Data 2 Low byte	1 00 lotol odiput		
D8	Data 3 High byte	Humidity, Unit: %RH [Humidity= (measure data / 10)]		
D9	Data 3 Low byte	(
D10	Data 4 High byte	Temperature, Unit: °C [Temperature= (measure data - 500) / 10]		
D11	Data 4 Low byte	remperature, ornit. o [remperature= (measure data = 500) / roj		
D12	Data 5 High byte	DNA4 O		
D13	Data 5 Low byte	PM1.0		
D14	Data 6 High byte	DMo 5		
D15	Data 6 Low byte	PM2.5		
D16	Data 7 High byte			
D17	Data 7 Low byte	PM10		
D18	Data 8 High byte			
D19	Data8 Low byte	VOC Now R / Ref. R (%)		
D20	Data 9 High byte	VOC Ref. R Value		
D21	Data 9 Low byte			
D22	Data 10 High byte	VOC Now R Value PM sensor status alarm		
D23	Data 10 Low byte			
D24	State			
D25	Data check code	check code= (D1^D2^ ~ ^D24)		


D24: PM sensor status alarm (Status of PM2008)

Byte	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0
Alarming	Reserved	Reserved	Reserved	Reserved	1: Working temperature is low	1: Working temperature is high	1: Fan at low revolving speed	1: Fan at high revolving speed

www.gassensor.com.cn 17/18



Packing Information



Sensor per Tray	Tray Qty	Sensor per Carton	Carton Dimensions	Packing Material	
16 pcs	10 layers	160pcs	395 * 310 * 330mm	Red anti-static EPE	

After-Sales Services and Consultancy

Cubic Sensor and Instrument Co., Ltd

Tel: +86 (0)27 81628827 / Fax: +86 (0)27 81628821 / South Korea Contact +82 010-5349-8385

Add: Fenghuang No.3 Road, Fenghuang Industrial Park, Eastlake Hi-tech Development Zone, Wuhan 430205, China

Web: www.gassensor.com.cn / E-mail: info@gassensor.com.cn / South Korea Contact malbonair@naver.com

www.gassensor.com.cn 18/18