

WOBD

Scanned 10/2/2026, 5:26:29 PM

2001 Chrysler PT Cruiser

Web On-Board Diagnostics · Scan report

Check engine light: OFF · 6 codes found

Code	Title	Urgency	What it means
P0340	Camshaft Position Sensor A Circuit (Bank 1)	MEDIUM	The computer isn't getting a good signal from the camshaft sensor. The car may be hard to start or run poorly.
P0601	Internal Control Module Memory Check Sum Error	UNKNOWN	The ECU's internal memory checksum does not match the expected value at startup – the firmware/calibration in flash has become corrupt. Often appears after a failed flash, low battery during programming, or genuine module hardware failure.
P0352	Ignition Coil "B" Primary/Secondary Circuit Malfunction (Cylinder 2)	UNKNOWN	An electrical fault has been detected in the ignition coil circuit for cylinder 2 – open primary winding, short to ground, or short to supply. The ECU disables the coil to protect its driver and the cylinder misfires.
P0351	Ignition Coil "A" Primary/Secondary Circuit Malfunction (Cylinder 1)	UNKNOWN	An electrical fault is detected in both the primary and the secondary circuit of ignition coil A (cylinder 1). The ECU cannot drive the coil correctly, so the cylinder served by coil A misfires or does not fire at all. Causes: an open or shorted primary control wire, an internal coil winding fault, a failed igniter/driver, or wiring or connector damage at the coil.
P0551	Power Steering Pressure Sensor Range/Performance	UNKNOWN	The PS pressure sensor signal stays in electrical range but is implausible for the operating state, e.g. high pressure reported with the wheels straight.
P1391	Manufacturer-specific code	UNKNOWN	Hmm, that one's specific to your car's brand, so it isn't in my book. A quick search with your car's details is the fastest way to find out what it means.

P0340 · Camshaft Position Sensor A Circuit (Bank 1)

Urgency: Medium. Drive gently and get it checked soon.

Common causes:

- Failed camshaft position sensor
- Damaged wiring or connector
- Slipped timing belt or chain

DIY or shop: DIY if you're handy

Tell your mechanic: "I have a P0340. Can you check the cam sensor and its wiring, and confirm the timing is right?"

P0601 · Internal Control Module Memory Check Sum Error

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Common causes:

- Failed flash / interrupted programming
- Module hardware failure
- Module software outdated, reflash may resolve

DIY or shop: Shop job

Tell your mechanic: "I have a P0601, Internal Control Module Memory Check Sum Error. Can you diagnose it?"

P0352 · Ignition Coil "B" Primary/Secondary Circuit Malfunction (Cylinder 2)

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Common causes:

- Coil primary winding open or shorted
- Wiring or connector fault

DIY or shop: Easy DIY

Tell your mechanic: "I have a P0352, Ignition Coil "B" Primary/Secondary Circuit Malfunction (Cylinder 2). Can you diagnose it?"

P0351 · Ignition Coil "A" Primary/Secondary Circuit Malfunction (Cylinder 1)

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Common causes:

- Coil primary winding open or shorted
- Wiring or connector fault

DIY or shop: Easy DIY

Tell your mechanic: "I have a P0351, Ignition Coil "A" Primary/Secondary Circuit Malfunction (Cylinder 1). Can you diagnose it?"

P0551 · Power Steering Pressure Sensor Range/Performance

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Common causes:

- Sensor drift or contamination
- Sensor element aged beyond calibration window
- Sensor mounting loose - signal damping

DIY or shop: DIY if you're handy

Tell your mechanic: "I have a P0551, Power Steering Pressure Sensor Range/Performance. Can you diagnose it?"

P1391 · Manufacturer-specific code

Urgency: Unknown. I can't rate this one. If the car drives differently, get it checked.

Tell your mechanic: "I have a P1391. Can you look up what it means for my car?"

WOBD gives general information, not a professional diagnosis. Always confirm a problem before replacing parts.

WOBD is in active testing and development, and its results aren't guaranteed yet.

Free car diagnostics at wobd.app