8 Diffusion solids

- energy solids → solids + solids phenomena
- Microstructure control → Phase transformations
- processed using equilibrium? → Phase diagrams
- not ideal equilibrium → diffusion
- diffusion: atoms migrate in solids → concentration gradients, heat treatments, creep, sintering, oxidation, microelectronic circuits, polymers
- atoms in → material loses performance
- Diffusion controlled transformations → Rate of reaction depends on rate of diffusion
- Fick's 1st law → Steady state diffusion
- Fick's 2nd law → Non-steady state diffusion
- Factors that affect diffusion → Diffusion mechanism, Material structure, Temperature, Concentration of diffusing species

8.1 Introduction

- Atoms in gases and liquids in motion → fast
- Atoms in solids → vibrate about fixed positions
- Sometimes → jump to new positions
- Diffusion → gradual mixing of atoms due to random atomic motion
- Driving force → concentration gradient
- Steady-state diffusion → Flux doesn't change with time
- Non-steady-state diffusion → Flux changes with time

8.2 Diffusion mechanisms

- Model: Atoms in crystalline solid → vibrate about lattice positions
- Vibrate → frequently enough → jump to vacancy
- Diffusion → vacancy diffusion
- Interstitial diffusion → smaller atoms migrate from interstitial position to interstitial position

8.2.1 Vacancy diffusion

- Vacancy diffusion → atoms exchange with vacancies
- Activation energy → energy required for atom to exchange with vacancy
- Activation energy ↑ → fewer exchanges
- Activation energy ↑ → temperature ↑
- Activation energy → Energy to form vacancy + energy to move it

8.2.2 Interstitial diffusion

- Interstitial diffusion → smaller atoms migrate from interstitial position to interstitial position
- Smaller atoms → Fit between matrix atoms
- Smaller atoms → Diffuse more rapidly than vacancy diffusion

8.3 Steady-state diffusion

- Steady-state → rate of diffusion ↓ with time
- Steady-state → concentration profile ↓ with time
- Concentration profile → Plot of concentration of species ↓ with position within solid
- Concentration gradient → Slope at point on concentration profile
- Concentration gradient → $\frac{dC}{dx}$
- Steady-state diffusion → Concentration gradient ↓ with time
- Steady-state diffusion → Concentration gradient → constant

8.3.1 First Fick's law

- First Fick's law → Steady-state diffusion
- $J = -D\frac{dC}{dx}$
- J → Flux
- D → Diffusion coefficient
- $\frac{dC}{dx}$ → Concentration gradient
- Flux → Rate of mass diffuses through surface
- Flux → Mass ÷ (surface × time)
- $J = \frac{M}{At}$
- M → Mass diffusing through surface
- A → Surface area
- t → Time
- Flux → Number of atoms ÷ (surface × time)
- $J = \frac{n}{At}$
- n → Number of atoms diffusing through surface
- Concentration → Mass of diffusing species ÷ volume of solid
- $C = \frac{M}{V}$
- V → Volume of solid
- $C = \frac{n}{V}$
- n → Number of atoms in solid
- $V = Ax$
- x → Diffusion distance
- $C = \frac{n}{Ax}$
- $dC = \frac{dn}{Ax}$
- $dn = dM$
- $dC = \frac{dM}{Ax}$
- $J = \frac{1}{A}\frac{dM}{dt}$
- $J = -\frac{D}{A}\frac{dM}{dx}$
- Negative sign → Diffusion down concentration gradient
- Diffusion down concentration gradient → Negative flux
- Diffusion up concentration gradient → Positive flux
- Concentration gradient → Driving force for diffusion
- Diffusion → Atoms migrate from region of high concentration to region of low concentration
- Diffusion → Atoms migrate down concentration gradient

8.3.2 Second Fick's law

- Second Fick's law → Non-steady-state diffusion
- Non-steady-state diffusion → Concentration gradient ↓ with time
- Non-steady-state diffusion → Concentration gradient ↓ with position
- Non-steady-state diffusion → Flux ↓ with time
- Non-steady-state diffusion → Flux ↓ with position
- Non-steady-state diffusion → Flux ≠ constant
- Non-steady-state diffusion → Flux changes with time
- Non-steady-state diffusion → Flux changes with position
- Non-steady-state diffusion → Concentration gradient changes with time
- Non-steady-state diffusion → Concentration gradient changes with position
- $\frac{\partial C}{\partial t} = D\frac{\partial^2 C}{\partial x^2}$
- $\frac{\partial C}{\partial t}$ → Change in concentration with time
- $\frac{\partial^2 C}{\partial x^2}$ → Change in concentration gradient with position
- D → Diffusion coefficient
- Second Fick's law → Concentration profile changes with time
- Second Fick's law → Concentration profile changes with position
- Second Fick's law → Concentration gradient changes with time
- Second Fick's law → Concentration gradient changes with position
- Second Fick's law → Flux changes with time
- Second Fick's law → Flux changes with position

8.4 Factors that affect diffusion

- Diffusion → Atoms migrate through solid
- Diffusion → Atoms migrate from one position to another position
- Diffusion → Atoms migrate through interstitial positions or vacancies in crystal structure
- Diffusion → Atoms migrate through grain boundaries, dislocations, and external surfaces
- Diffusion → Atoms migrate through microstructural defects
- Diffusion → Atoms migrate through microstructure
- Diffusion → Atoms migrate through crystal structure
- Diffusion → Atoms migrate through grain structure
- Diffusion → Atoms migrate through defect structure