




1 2 3 4 5 6

A



A



B



C

Sheet: /
File: CPR Machine Schematic.kicad_sch


Title:

Size: A4 | Date:

KiCad E.D.A. 9.0.4

Rev:
Id: 1/6

1 2 3 4 5 6




Sheet: /Motor Control/
File: MotorControl.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.4

Rev:
Id: 2/6



Sheet: /Microcontroller/
File: Microcontroller.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.4

Rev:
Id: 3/6

1 2 3 4 5 6

A

B

C

D

UART_TXC
UART_RXD

TBD: Add all of HMI's RasPi stuff

Sheet: /HMI/
File: HMI.kicad_sch



Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.4

Rev:
Id: 4/6

1 2 3 4 5 6

A



B

C

D



Sheet: /Power/
File: Power.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.4

Rev:
Id: 5/6

A



B

C

D

Sheet: /Sensing/
File: Sensing.kicad_sch

Title:

Size: A4 | Date:
KiCad E.D.A. 9.0.4

Rev:
Id: 6/6