

**Anxin-China's ISD System Prevents the Accidents** in Fireworks Production

On the afternoon of Nov. 1<sup>st</sup>, 2013, a bomb accident occurred in a fireworks production factory in

Wuzhou City, Guangxi Province, with 12 dead, reported agsc.cn.

On Oct. 29th, the State's administration of Work Safety revealed the news that another explosion

accident happened in fireworks production factory in Liuyang, Changsha, Hunan, with 4 dead, one

injured, and 26 factory rooms destroyed. On Sep. 28th, a fireworks manufacturing factory met with

a bomb accident casually in Changde, Hunan, with 3 dead, 2 injured.

It is the end of this year presently, which also means a beneficial season for producing and selling

fireworks. Thus, a series of production accidents consistently happened owing to the limitations of

local government's surveillance and regulation level, as well as the insufficient working

environment in the fireworks production sites. Here, Anxin-China has already noticed the

government's surveillance requests and people's requirements in the aspect of safety

production, and then develops ISD into the fireworks manufacturing area. The key is that ISD

system can take the place of traditional artificial surveillance model to monitor the work sites in

real time and check the corporate information, so as to realize the 7/24 surveillance model. Anway,

the basic infrastructure construction is the premise to wipe out all potential risks in the working

process. Anxin-China's ISD system can makes full use of its precaution feature and emergency

rescue coordination to reduce the loss of life and financial properties to the minimum extent.

However, the safety production concerns the social stability, and those above accidents urge the

government and corporate principals to develop solutions, for instance, Anxin-China's ISD system,

to prevent all the safety production accidents.

Add: Units 2001-2005 20th Floor, Harbour Centre,

25 Harbour Road, Wanchai, Hong Kong

Add: 9<sup>th</sup> Floor, Building A, Future Plaza, Qiao Xiang Road,

Nanshan District, ShenZhen

Add: 99 Dongjiu Road, Hongze County, Huaian City,

Jiangsu Province

**Tel:** 00852-23428702 Fax: 00852-23448917

**Tel:** 0755-86612894

Fax: 0755-26430113

**Tel:** 0517-87209111

Fax: 0517-87386999

www.anxin-china.com.hk