

Anxin-China Spares no Efforts to Develop Security Systems for Preventing Fire Hazards

At 8:20 p.m., August 26th, 2013, a fire accident occurred in Wuhan San Zhen Food Co., Ltd located in Fenghuangshan Industrial Park, Caidian District, Wuhan City. Consequently, the factory area of 3000 square meters was almost burnt down, which led to the economic loss at 500 thousand yuan. At receiving the alarm, Wuhan Fire Prevention Station immediately adjusted 170 soldiers to reach the accidents sites to implement emergency rescue mission. Herein, there was no casualty in the rescue case, while several soldiers were drained exhausted.

At noon, the journalist almost saw a lot of while fog rising up while staying a few hundred meters away from the accident site. Multiple fire protection vehicles reached the site and lots of soldiers strived for keeping the fire under control. As a result, the factory's external wall mostly broke down, with numerous windows damaged. Cracked production equipments could also be seen in the factory room, as some flames were still burning in some positions respectively.

Dating back to the big fire hazard in Jilin on June, 3rd, the State Council emphasized the vital importance of security surveillance in the fire hazard area, and furthermore, People's Daily also published the page-one article, to stick to the unbridgeable red line, to highlight the necessity of safety production in the public concern. Anyway, it was worthy of our attention that Anxin-China was always sparing no efforts to develop security systems to build smart cities and safe cities. Actually, the fire hazards were led by many elements, but Anxin-China can provide a perfect ISD system to solve those problems in China's security industry. Specifically, the front-end sensor can accurately monitor the factory's inner temperature in real time. It can timely send alerts as soon as the interior temperature suddenly rose, so that the monitoring personnel can made the response quickly. Thus, as the fire hazard occurs, multiple stages can be kept under control effectively, including fire predication, command coordination and emergency rescue, and then

Add: Units 2001-2005 20th Floor, Harbour Centre,

Tel: 00852-23428702

Fax: 00852-23448917

25 Harbour Road, Wanchai, Hong Kong

Tel: 0755-86612894

Fax: 0755-26430113

Add: 9th Floor, Building A, Future Plaza, Qiao Xiang Road, Nanshan District, ShenZhen

Add: 99 Dongjiu Road, Hongze County, Huaian City,

Tel: 0517-87209111

Fax: 0517-87386999

Jiangsu Province



the safety of people's lives and financial properties can get a best guarantee.

Your safety is always our business! Anxin-China has always been working on it.

Add: Units 2001-2005 20th Floor, Harbour Centre,
25 Harbour Road, Wanchai, Hong Kong
Add: 9th Floor, Building A, Future Plaza, Qiao Xiang Road,
Nanshan District, ShenZhen
Add: 99 Dongjiu Road, Hongze County, Huaian City,
Jiangsu Province

Tel: 00852-23428702
Fax: 00852-23448917
Fax: 0755-26430113
Fax: 0755-26430113
Fax: 0517-87386999