

The Safety Production Surveillance Ability Required to Be

**Strengthened in the Ongoing Security Cases** 

(Shanghai-August 31th)At 11 O'clock a.m., August 31th, 2013, a liquid ammonia leakage case

occurred in one cold storage building in Fengxiang Road, Baoshan District, Shanghai City,

reported china.com.

And then Shanghai Municipal Government Press Office released the news that Weng Brand

Cooling Storage Entity Co., Ltd , located in No. 1258, Fengxiang Road, Baoshan District, ran into

a liquid ammonia leakage security case, with 15 dead, 26 injured. All security departments from

Shanghai Municipal Government appealed related leaders and personnel to reach the site to

implement rescue deployment immediately after the accident. At present, the emergency rescue

mission has been finished. The cause of the accident is still being investigated.

More importantly, this accident simply happened during the period of State's Safety Production

Major Inspection.

Now, we can return back to the previous accident on June 3th that Jilin fire hazard led ammonia

devices and tubes to run into physical bombs, while a great deal of ammonia leakage sped up the

burning with 121 dead, 71 injured.

Two days later, Li Keqiang, the premier of the State Council, host the execute meeting to demand

all security surveillance departments at all levels to implement the State's safety production

major inspection, with the aim at wiping out all potential safety production risks. Anyway, the key

point is to release the true inspect results to the whole public.

Why did this kind of safety production accident happen again as the major inspection had just

Add: Units 2001-2005 20th Floor, Harbour Centre,

**Tel:** 00852-23428702

Fax: 00852-23448917

25 Harbour Road, Wanchai, Hong Kong

**Add:** 9<sup>th</sup> Floor, Building A, Future Plaza, Qiao Xiang Road,

**Tel:** 0755-86612894

Fax: 0755-26430113

Nanshan District, ShenZhen

**Tel:** 0517-87209111

Fax: 0517-87386999

Add: 99 Dongjiu Road, Hongze County, Huaian City, Jiangsu Province



been finished?

In recent years, however, most accidents are led by the ineffective surveillance and supervision of enterprises and related security departments towards the surveillance devices. For instance, old devices, broken tubes and valves, and outdated surveillance methods. Thus, it's very important for enterprises to strengthen the supervision and surveillance towards monitoring devices and methods. Herein, Anxin-China has particularly developed the ISD system to solve this problem. This is a comprehensive real-time safety surveillance system provide a whole emergency rescue solution for AWS and other enterprises to deal with the safety production cases. The front-end sensor of ISD system can immediately detect the gas density in the target environment, including. For instance, the Nitrogen and ammonia leakage can be checked out quickly by Anxin-China's ISD, so as to reduce the losses to the minimum extent. It covers the previous, medium and post stages of the major safety production accident, so as to offer the most effective surveillance service for the AWS and enterprises.

However, Anxin-China has always been striving for carrying out the promise of smart & safe city with advanced technologies, aiming at the prevention of safety production accidents.

Add: Units 2001-2005 20th Floor, Harbour Centre,

25 Harbour Road, Wanchai, Hong Kong

Add: 9<sup>th</sup> Floor, Building A, Future Plaza, Qiao Xiang Road,

Nanshan District, ShenZhen

Add: 99 Dongjiu Road, Hongze County, Huaian City,

Jiangsu Province

**Tel:** 00852-23428702 **Fax:** 00852-23448917

**Tel:** 0755-86612894

**Fax:** 0755-26430113

**Tel:** 0517-87209111

Fax: 0517-87386999