

[PAPE] 100 R23	[PAPE] 100k R22	[PAPE] 100n (x2) C101, C104
[PAPE] 100u (x3) C100, C102-C103	[PAPE] 10k (x4) R7, R12, R16, R104	[PAPE] 10u (x5) C3-C6, C11
[PAPE] 11k R14	[PAPE] 150p C9	[PAPE] 16k R102
[PAPE] 18n (x2) C8, C10	[PAPE] 1N4148 (x2) D1-D2	[PAPE] 1N5817 D100
[PAPE] 1k R3	[PAPE] 1n C2	[PAPE] 1u (x2) C1, C7
[PAPE] 2.2M (x2) R1-R2	[PAPE] 2.7k R15	[PAPE] 22k (x3) R18, R21, R103
[PAPE] 2N3904 (x3) Q1-Q3	[PAPE] 2N5088 Q4	[PAPE] 390 (x4) R8-R9, R13, R17
[PAPE] 4.7k (x3) R19-R20, R101	[PAPE] 430k (x2) R5, R10	[PAPE] 43k (x2) R6, R11
[PAPE] 47 R100	[PAPE] 47k R4	[PAPE] A100K (x2) RIP, VOL
[PAPE] B10K FUZZ	[PAPE] B50K TONE	[PAPE] DIP Socket IC1

[PAPE]

OPA1678

IC1

[PAPE]

Paper Scratcher Fu

PCB