



## Power Supply




Symbols: J2, J3 are header pins to be used for debugging, jumping, and separating sections of the schematic in case errors occur.

## Wheatstone Bridge Light Sensor



Symbols: J4, J5, J6 are header pins to be used for debugging, jumping, and separating sections of the schematic in case errors occur.

## Microcontroller



Symbols: J7, J8, J9, J11, J13, J14 are header pins to be used for debugging, jumping, and separating sections of the schematic in case errors occur.

### Team 201: Light Sensor Subsystem

Sheet: /

File: subsystem\_design.kicad\_sch

### Title: Wheatstone Bridge Light Sensor with Microcontroller Subsystem

Size: A4

Date: 2025-10-27

KiCad E.D.A. 9.0.4

Rev: 3

Id: 1/1