GEMINI
ENGINEERING GROUP

101 Nightlinger Lane
Millsap, TX 76066
(817) 672-7562

November 05, 2026

City of Centennial, CO

Subject: Consumer Cellular
8283 S. Akron St.
Suite #110
Centennial, CO 80112

To whom it may concern,

The following are responses to your comments.

Comment 3: Fire Alarm and Duct Detection (IBC 907.2.7; IMC 606.2.1; IFC 105.6; CMC 18-7-30). A manual fire alarm system is not required by the IBC for this occupant load; the system shown on FA101 is subject to a separate permit from South Metro Fire Rescue. Duct smoke detection is required on RTU-1 (3,000 CFM) independent of the fire alarm decision.

Response: The Fire Alarm system is shown for reference only and will be submitted as a separate permit. Duct smoke detection for RTU-1 is noted on sheet M101 keyed note #2.

Comment 4: Ventilation (IMC 403.3.1.1). The existing rooftop units provide 675 CFM of outdoor air. Provide the outdoor air calculation for the sales area, back-of-house, office and restroom, and the restroom exhaust rate, to confirm the existing units are adequate after rebalancing.

Response: Ventilation Calculations can be found on sheet M102 in the lower right corner of the Rooftop Unit Schedule. Ourdoor air calculation values for the sales area, back-of-house, office and restroom, and the restroom exhaust rate are shown.

Comment 5: Energy (2021 IECC C405, C503.5). No lighting compliance documentation is included. Provide a COMcheck or lighting power allowance calculation for the new lighting and show automatic lighting controls on the electrical sheets.

Response: COMcheck lighting compliance forms are included on sheet E601.

Comment 6: Electrical (NEC 110.9, 110.24, 220.40). Provide the available fault current and panel interrupting ratings downstream of the existing 400-ampere fused disconnect, and a connected and demand load summary for the tenant.

Response: Available fault current calculations have been added to sheet E301 Detail 2. The existing Panels A & B will be replaced with a new panel rated at 42kAIC. The connected and demand load summary can be found on sheet E301 Detail 1.

Comment 7: Plumbing (IPC 416.5, 504.6, 504.7, 1002.4). Show the water heater drain pan where located above finished space, the ASSE 1070 mixing valve at the lavatory, the trap primer at the restroom floor drain as noted, and the drinking fountain or bottle filler backflow protection.

Response: The water heater drain pan can be found on sheet P501 Detail 5.
The ASSE 1070 mixing valve can be found on sheet P101 Details 2, 4, and 5. The mixing valve is also notated by keyed note #6.
The trap primer can be found on sheet P101 Detail 4 and is notated by keyed note #5.
The drinking fountain backflow protection has been notated on sheet P101 Detail 4.

If you have any questions regarding the above, please do not hesitate to call.

Thank you,

Clayton Lucas, PE
Gemini Engineering Group, LLC

COLORADO LICENSED
CLAYTON LUCAS
63118
PROFESSIONAL ENGINEER

11/05/2026