**Invoice #2478** 

Name: Jamie Florence

Address: 310 S 16th ST

Selah WA 98942

**Year:** 1998

**Model:** 355 F1

Page 1 of 3

**Telephone:** 415-297-9958

 Date:
 6/19/2024

 Make:
 Ferrari

 Miles in:
 43,068

Miles out:



166221 10th Avenue NW Arlington WA 98223 360-202-5220

Parts and Labor required		nes out.			300-202-3220				
		abor Cost	Qty	Part Number	Part Description	Parts (	Cost	T	otal Cost
Email: jamie@microforensics.com									
VIN: ZFFXR41A2W0111503 LIC: CAK8137	\$	_						\$	-
Assembly #	\$	-						\$	-
·	\$	_						\$	_
Car towed in after hours by towing company contracted by owner.	\$	-	1	177968	Engine oil pan	\$ 2	2,986.80	\$	2,986.80
	\$	1	1	149318	windage tray	\$	50.44	\$	50.44
	\$	1	1		sealant, oil pan	\$	48.00	\$	48.00
	\$	1	1	133284	Threaded plug	\$	183.26	\$	183.26
	\$	1	1	129322	drain plug	\$	9.79	\$	9.79
			2	64473300/A	undertray gasket	\$	48.59	\$	97.18
	\$	1	1	64841100	Front undertray	\$ 1	,059.23	\$	1,059.23
Owner states they ran over a large rock in the road and lost fluids, oil	\$	-	1	64841200	Center undertray	\$ 1	,898.00	\$	1,898.00
and shut the car down and pulled over.	\$	-	1	64841400	rear undertray	\$ 1	,650.00	\$	1,650.00
Rack vehcile and perform inspection, document with pictures.	\$	-	1	165652	Fuel tank or repair.	\$ 1	,850.00	\$	1,850.00
Remove undertrays for further inspection of damaged areas.	\$	-						\$	-
Remove engine oil pan and inspect for internal engine damage	\$	750.00							
Test gearbox case for cracks/leaks	\$	1	1	138453	tank oring	\$	55.55	\$	55.55
Engine oil pan and windage tray will need replacement. Recommend doing	\$	2,400.00	4	134701	oring	\$	2.29	\$	9.16
this prior to any other repairs and confirm no hidden damge to the engine.	\$	1	4	134705	oring	\$	2.29	\$	9.16
Remove gearbox for access to the rear of the engine, replace rear main	\$	-	4	14456880	gasket	\$	34.23	\$	136.92
cover plate oring that was damaged during engine oil pan removal.	\$	-	2	142106	Gasket	\$	12.02	\$	24.04
	\$	1	1	157927	pipe	\$	172.10	\$	172.10
Recenter and slef learn F1 system.	\$	1	1	157979	pipe	\$	158.60	\$	158.60
	\$	1	1	157928	pipe	\$	43.66	\$	43.66
	\$	-	1	154802	sending unit gasket	\$	61.29	\$	61.29
	\$	-	1	141066	filler neck	\$	429.00	\$	429.00
Fuel tank smashed in on the underside. Install good used fuel tank.	\$	2,400.00	1	141033	Grommet for filler neck	\$	89.00	\$	89.00
New are no longer available. Transfere over pumps, sending unit and hoses.	\$	-	1	170616	PS pressure line	\$	269.55	\$	269.55
Evaporative pipes will crack upon removal and are quoted on the job.	\$	=	1	170617	P/S return line	\$	257.96	\$	257.96
	\$	-	1	63561600	A/C discharge line	\$	326.25	\$	326.25
A/C and P/S lines damaged down center tunnel. Install new steel lines.	\$	1,200.00	1	63561500	A/C suction line	\$	295.98	\$	295.98

Minor repairs needed to mounting studs for lines and undertrays.		\$	-	4	63959800	pipe clip	\$	14.18	\$	56.72
Requires fuel tank removal so must be done in conjunction with above		\$	-	4	64290100	pipe clip	\$	13.64	\$	54.56
Fuel tank repair. Labor reflects overlapping times.		\$	_	2	162769	motor mounts	\$	190.66	\$	381.32
		\$	-	2	163044	Gearbox mounts	\$	191.81	\$	383.62
		\$	-						\$	=
Repair, replace bent mounting tabs for undertrays and pipe brackets		\$	800.00	10	5w-40	engine oil	\$	18.56	\$	185.60
		\$	-	3	Spirax	P/S fluid	\$	38.00	\$	114.00
		\$	-	2	gallons	engine coolant	\$	29.00	\$	58.00
Replace engine mounts and gearbox mounts		\$	1,650.00	30	ounces	R134	\$	8.00	\$	240.00
		\$	-	15	gallons	premium unleaded fuel	\$	5.00	\$	75.00
		\$	_						\$	-
		\$	-						\$	-
Shipping customs and duties		\$	-	1	shipping	and duties anticipated	\$	583.00	\$	583.00
		\$	-						\$	-
		\$	_						\$	-
		\$	-						\$	-
		\$	-						\$	-
Deposit received 6/20/24 \$13,000 mg		\$	_						\$	-
		\$	_						\$	-
		\$	_						\$	-
		\$	_						\$	-
Extendeed road testing to evaluate repairs and gearbox operation.		\$	_						\$	-
Fill ccar withy fuel		\$	_	1	premium fuel	18027 gallons at 4.99	\$	91.34	\$	91.34
Hot oil pressure after 25 mile freeway drive 15 at idle, 65-70 at 4,000 RPM		\$	_						\$	-
Pull oil filter and cut open, inspect for metal.		\$	-	1	197654	oil filter	\$	79.00	\$	79.00
Perform manual oil pressure test		\$	-	1	135940	oil pressure sensor	\$	289.00	\$	289.00
Install new oil fitler and oil pressure sensor.		\$	-						\$	-
		\$	-						\$	-
		\$	-						\$	-
		\$	_						\$	_
Labor Total	0.00	\$9	9,200.00					Parts Total	\$	14,762.08
You are hereby authorized the above repair work to be done along with the necessary labor and materials. You grant us permission to operate your vehicle for the purposes of testing, inspection, or delivery at your own risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs				Parts Total	\$ 14,762.08				·	
			Labor Total Haz Waste, Supplies		\$ 9,200.00	1				
thereto. We will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire theft accident or any other cause having our control. This estimate is valid for 30 days. This is only an estimate. Occasionally, upon commencement of the repair additional worn or damaged parts may be discovered. All additional parts and labor that exceed 10% of this estimate will require further customer					\$ 250.00					
					<b>A</b>	Depos	it		\$13,000	
approval.			Gagionigi	Subtotal		\$ 24,212.08				
					Tax 9.1% Total	\$ 2,203.30 \$ 26,415.38	Balanc	e	9	313,415.38
Customer Signature:	Date:			Т	Thank you!	. ,			4	2,