Maintenance Log Entry

• **Date:** 2025-02-04

• **Technician:** Pat H.

• Machine Type: CNC Lathe (Model: LT-150)

• Failure Type: Excessive Load Condition

• Error Code: OSF-009

Symptoms:

• Increased vibration and occasional spindle stalling during operations.

- Irregular feed rates and a slight drop in machining precision.
- Intermittent error alerts on the control panel.

Diagnostic Steps:

- 1. Reviewed torque and vibration data; observed values exceeding safe limits.
- 2. Inspected drive components and mechanical linkages for signs of stress.
- 3. Verified operational settings (feed rate and spindle speed) against manufacturer recommendations.
- 4. Examined system logs for load-related anomalies.

Final Resolution:

- Adjusted feed rate and reduced spindle speed to lower mechanical stress.
- Tightened mechanical connections and applied lubrication to moving parts.
- Cleared error code OSF-009 and confirmed stable operation with a brief test run.

Recommendations:

- Perform regular checks on load and vibration levels during operations.
- Maintain operational settings within safe parameters.
- Schedule periodic maintenance on drive components and load-bearing parts.

End of Log Entry