# 1. Description


## 1.1. Project

Project Name	Ratatuj_matka
Board Name	32L476GDISCOVERY
Generated with:	STM32CubeMX 4.25.0
Date	05/30/2018

### 1.2. MCU

MCU Series	STM32L4
MCU Line	STM32L4x6
MCU name	STM32L476VGTx
MCU Package	LQFP100
MCU Pin number	100

## 2. Pinout Configuration




# 3. Pins Configuration

Pin Number LQFP100	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
6	VBAT	Power		
10	VSS	Power		
11	VDD	Power		
14	NRST	Reset		
19	VSSA	Power		
20	VREF-	Power		
22	VDDA	Power		
27	VSS	Power		
28	VDD	Power		
30	PA5	I/O	SPI1_SCK	
43	PE12 *	I/O	GPIO_Output	SP1_CE
44	PE13 *	I/O	GPIO_Output	SPI1_CS
45	PE14	I/O	SPI1_MISO	
46	PE15	I/O	SPI1_MOSI	
49	VSS	Power		
50	VDD	Power		
73	VDDUSB	Power		
74	VSS	Power		
75	VDD	Power		
94	BOOT0	Boot		
99	VSS	Power		
100	VDD	Power		

<sup>\*</sup> The pin is affected with an I/O function

## 4. Clock Tree Configuration



Page 4

## 5. IPs and Middleware Configuration

#### 5.1. SPI1

**Mode: Full-Duplex Master** 

### 5.1.1. Parameter Settings:

#### **Basic Parameters:**

Frame Format Motorola

Data Size 8 Bits \*

First Bit MSB First

#### **Clock Parameters:**

Prescaler (for Baud Rate) 4 \*

Baud Rate 5.0 MBits/s \*

Clock Polarity (CPOL) Low
Clock Phase (CPHA) 1 Edge

#### **Advanced Parameters:**

CRC Calculation Disabled

NSSP Mode Enabled

NSS Signal Type Software

#### 5.2. SYS

**Timebase Source: SysTick** 

<sup>\*</sup> User modified value

# 6. System Configuration

## 6.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull	Max	User Label
				down	Speed	
SPI1	PA5	SPI1_SCK	Alternate Function Push Pull	No pull-up and no pull-down	Very High	
	PE14	SPI1_MISO	Alternate Function Push Pull	No pull-up and no pull-down	Very High *	
	PE15	SPI1_MOSI	Alternate Function Push Pull	No pull-up and no pull-down	Very High	
GPIO	PE12	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Low	SP1_CE
	PE13	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Low	SPI1_CS

## 6.2. DMA configuration

nothing configured in DMA service

## 6.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority
Non maskable interrupt	true	0	0
Hard fault interrupt	true	0	0
Memory management fault	true	0	0
Prefetch fault, memory access fault	true	0	0
Undefined instruction or illegal state	true	0	0
System service call via SWI instruction	true	0	0
Debug monitor	true	0	0
Pendable request for system service	true	0	0
System tick timer	true	0	0
PVD/PVM1/PVM2/PVM3/PVM4 interrupts through EXTI lines 16/35/36/37/38	unused		
Flash global interrupt	unused		
RCC global interrupt	unused		
SPI1 global interrupt	unused		
FPU global interrupt	unused		

<sup>\*</sup> User modified value

# 7. Power Consumption Calculator report

#### 7.1. Microcontroller Selection

Series	STM32L4
Line	STM32L4x6
мси	STM32L476VGTx
Datasheet	025976_Rev4

#### 7.2. Parameter Selection

Temperature	25
Vdd	null

## 8. Software Project

### 8.1. Project Settings

Name	Value	
Project Name	Ratatuj_matka	
Project Folder	D:\Ratatuj\Ratatuj_matka	
Toolchain / IDE	TrueSTUDIO	
Firmware Package Name and Version	STM32Cube FW_L4 V1.11.0	

### 8.2. Code Generation Settings

Name	Value
STM32Cube Firmware Library Package	Copy only the necessary library files
Generate peripheral initialization as a pair of '.c/.h' files	Yes
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	No
Set all free pins as analog (to optimize the power	No
consumption)	

<b>9.</b>	Software	Pack	Report
-----------	----------	------	--------