Business Objective to Process Objective Mapping

Improve on- Time Delivery Performance		Improve Quality of the Product	Business Goal
What percentage of projects is delivered on-time?	manutactured?	How many defects are detected in the products being	Information Need
To determine the variance between the estimated and actual schedules.	customer	To reduce the number of defects in the product	Measurement Objective
-Project Planning -Project Monitoring and Control	-Verification -Validation	-Technical Solution -Product	Affected Processes
Delivery		Quality	Category
dates Actual Milestone Dates	month # of quantity produced in the month Planned milestone	# of defects detected in the products being manufactured in the	Base Measures
Variance Schedule Variance measures the difference between scheduled and achieved durations for a project.	failures in a month and the total quantity produced in the month.	Percentage Line rejection percentage is the ratio of total line	Derived Measures
	±20%	5	Tolerance Limits

Talous I