

CT Flow Activated Releasable Overshot

Document No:07

Editor: Jalal Alali



中国石油长城钻探工程公司



CONTENT

- **♦Introduction of CT Flow Activated Releasable Overshot**
- **♦** Disassembly
- **♦**Assembly







Introduction:



- •The Flow Activated Coiled Tubing Releasable Overshot is a variable catch external overshot used to retrieve a lost cylindrical fish from the well bore.
- •A complete range of hardened and double tempered slips are available for each size tool. These tools are available in all sizes from 1" to 4" diameter with slips to suit.

معرفي:

که برای بازار یک آرواره زبرین با دهانهٔ متغیر است که برای بازیابی ابزار استوانه ای بازمانده درون چاه استفاده میگردد.

بازه کاملی از دندانه های های دو بر ابر ناخنک کاری شده و سخت شده بر ای هر اندازه از ابزار موجود است. این ابزار ها در تمامی اندازه ها از قطر 1 تا 4 اینچ به همراه دندانه های مناسب هر یک در دسترس می باشند.





>> Required hand tools

🗘 ابزار مورد نیاز

- Pipe Wrench
- Allen Key
- Rubber Hammer
- Bowl
- Flat Bar
- Screwdriver





Disassembly



Place Body In The Vice





中国石油长城钻探工程公司

Unscrew Top Sub From Body









Unscrew Guide From Bowl

A B



Unscrew Bowl From Body

A B









Δ



 Note: Upper Core will have to be held steadily by using flat bars in slots at either end of core assembly.

А

C



Unload Upper Core From Body

A



Extract Core Spring And Lower Core From Collet

A



Unscrew Choke From Lower Core

A



中国石油长城钻探工程公司

Remove Core Spring And Collet From Lower Core



















Remove Main Spring From Upper Core







Assembly



Place Body In Vise



Make Up Choke Bean Into Lower Core

A



Place Collet And Spring Over Lower Core And Locate Onto Back Of Retainer Sub



Load Upper Core Into Body

A



Insert Top Of Lower Core Into Bottom Of Body And Make Up Lower Core To Upper Core

*Note: Upper Core Will Have To Be Held Steady For Initial Make Up

A



Slide Bowl Over Collet And Make Up It To Body

A



Place Main Spring Into Top Of Body

A B



Make Up Top Sub To Body

A



Make Up Guide To Bowl

В

A