

SGL-T1 Flow Chart (REV06 - 2025_03_18)

Rev.	Date	Change Description	Approved by
02		Redraw from "2024_02_16 - Reza - T1_skillet(REV01)" - The green boxes are edited or added.	Mohsen Saadatfard
03	2024-05-07	A delay has been added to the pan-down process to prevent the spark on the External Direction-relay. No impact for the UI	Mohsen Saadatfard
04	2024-06-07	SousVide Pump has been added	Mohsen Saadatfard
05	2024-08-18	Jacket Limit Temperature is added to the heating loop during product mode. The green boxes have been edited	Mohsen Saadatfard
06	2025-03-18	Some digital feedbacks and alarms have been added. The yellow boxes have been edited.	Mohsen saadatfard

Notes

- -Errors are not self-clear and need to be cleared by UI after the processed
- -PID registers need to be set by UI according to the selected process -RTD sensor reading values lower than 32F and Higher than 500F will trigger sensor error





- During Pan moving Up/Down, UI checks the Up/Down limit Switches and will notice the end of the moving process.

