## Project Logbook: Source control commits

James Glanville (EM)

## 27th May 2013

This document lists the "commits" to version control of the files used by this project. It accompanies the written part of the project logbook.

```
commit be9773fd95359448ba6e1b0b9881eb9a851a26a7
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue May 27 06:15:57 2014 +0100
     added description of project files
commit 28ff3205dc246fd875f4cb3878c7ed79d1afa49c
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue May 27 03:01:59 2014 +0100
commit 476ecbe7e7f1f283968c100f1ee979bc9f67e0e1
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue May 27 02:59:08 2014 +0100
\verb|commit| e32a4bd9ff6db6cf4059d3faa9e53f1b95406e21|
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue May 27 02:56:19 2014 +0100
commit 616ecdbc339f8bf927f12ab760dc1f0b43402ae0
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue May 27 02:46:24 2014 +0100
commit 72672f258b2fcf44f7d100846fd0704006c909e7
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue May 27 02:40:41 2014 +0100
     added extruder pictures
commit e7970595bdd7b260f28a00d4215287a26ea9bf71
Merge: 58bbcb8 0511d8e
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue May 27 02:02:59 2014 +0100
      Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit 58bbcb8d9fd98e9d139f64d4f3de9cd00f90b198
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue May 27 02:01:08 2014 +0100
      added paste extrusion picture
commit 0511d8e939e501d34b8781562124ce1a2bca20e7
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon May 26 08:44:57 2014 +0100
     added automated inspection
commit 8de54763df7afcf1d26e6472f1e15ba3c3143124
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 26 08:05:45 2014 +0100
     moved software up in report
commit 4a7f587850cca424a8524f9275320fc2fe82cb78
Author: James Glanville <james.n.glanville@gmail.com>
```

```
Date: Mon May 26 08:04:32 2014 +0100
    mostly finished rejigging of report
commit a97f863c943e20164e02c5c7e8743267b815f8b2
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 26 06:57:33 2014 +0100
    compiled
commit 203ca830efe49617a1706961417f2e3c89a27517
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 26 06:57:20 2014 +0100
    committed loads of report improvements
commit 3cf259b4cd249746ace46c3ec7bf40359cc838fe
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 26 03:45:46 2014 +0100
    rewrote axis design
commit 66d4e6cdde2fb10fa00ef4ed94bb8608006e49be
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:34:25 2014 +0100
    added fuse comment
commit e3bc0cc851bd645197c29d3c5325652885c1fad7
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:32:45 2014 +0100
    neatened report, added worm extruder reference, explained usb serial choice
commit 1e831b2986c1fd2a3bdcdd91cb48a41b62d96aaa
Merge: a4ad5c4 d3171ec
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:28:03 2014 +0100
    Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit a4ad5c429a81810bf6ad2ead2db8f36edb7dd5a9
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:27:41 2014 +0100
    added worm extruder placeholder
commit d3171ec8936d1d461cfe51ea6031ff6cb2dac292
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:17:27 2014 +0100
     added user interaction section
commit alf12c71f88fea607e8d9774bea5166479b83729
Author: James Glanville (james.n.glanville@gmail.com>
Date: Fri May 23 04:14:20 2014 +0100
    added more evalution comments
commit c1b7b607e3a364a0dccd6bf65bfe79414a4e228f
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 04:05:41 2014 +0100
    compiled handbook
commit e3355d8447857030645731c2350ea6d7b86bafd4
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 04:05:24 2014 +0100
    mentioned handbook
commit b522dc28eaa77633fa11a85b3ac2e91a94aabcd3
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 04:03:17 2014 +0100
     added untracked breakout board files
commit ba433ed3ce99d598b5ac8b4de548c37e96060617
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 04:02:50 2014 +0100
    actually compile the report...
commit 9e93da7c5f4e92970121ae5def530fde1f812e15
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 04:02:31 2014 +0100
     added pronterface section
```

2

```
{\tt commit 85c41c7319bc6a8934fb4cb32eed78d3c5c5ad85}
Merge: f436821 cbd1418
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 03:56:44 2014 +0100
     Merge branch 'master' of github.com:JamesGlanville/solderingmachine
commit cbd14187e11b4bf5369daa967be959ba6e89e8ee
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 03:55:42 2014 +0100
     added spindle photo
commit f43682134f939154fae1c43896d61b38c1136235
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 03:51:09 2014 +0100
\verb|commit| 49 \texttt{f} 3991783 \texttt{d} \texttt{f} \texttt{d} \texttt{e} \texttt{e} \texttt{c} \texttt{b} 39 \texttt{e} \texttt{e} 95 \texttt{a} \texttt{6} \texttt{a} \texttt{4} \texttt{f} 37 \texttt{6} \texttt{8} \texttt{d} \texttt{4} \texttt{b} \texttt{c} \texttt{4} \texttt{d} \texttt{d} 5
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 03:42:07 2014 +0100
      moved heat calculations to appendix
commit 0d07de97507b127832cc0239fdccfd9346fd806e
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 03:36:32 2014 +0100
     added pictures of breakout board
commit 0412bffa3e5bea952975070e7549eac3c1fd925b
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 03:28:24 2014 +0100
     added breakout photos
 \begin{array}{lll} {\tt commit} & {\tt a5dc4798a3e10d7496a0726b3b5f9d2d26393806} \\ {\tt Merge:} & {\tt 7d7e808} & {\tt 35b980e} \end{array} 
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri May 23 03:28:10 2014 +0100
     Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit 7d7e808927a195a16875be549ab1147f070852a0
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 03:27:25 2014 +0100
     added errors.svg
commit 35b980ec1b7423b2353f8e5350f772dd9ce1696a
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 02:08:56 2014 +0100
      technical abstract draft finished
commit 8a1beb511428a30156d1ba1e9aa6f0312bc11391
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri May 23 02:01:36 2014 +0100
      added technical abstract pdf
commit 2f40e8bfa781e01af44ac7bf3dd144642e42f60f
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu May 22 15:49:14 2014 +0100
     added sample technical abstract, added risk assessment to the report and updated compile script
commit d4a779859c2188cc790e3c0d28d26c9f6520c456
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu May 22 13:56:20 2014 +0100
     compiled updated conclusion
commit 006f2bd7823ca2892cd49389e3d8a693e2cb48dd
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu May 22 13:50:16 2014 +0100
      project management section added
{\tt commit} \ \ 079\,{\tt d2832cc88e67b81c26c107b5a8fb8b0b10ee1}
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu May 22 13:38:10 2014 +0100
      added conclusions
commit 6a108d951b5270d891d28bf401e7a40dc0cb3b83
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu May 22 13:21:18 2014 +0100
     added conclusion section, needs work
commit cal3f70176eef75e5390e2d8dd90728513e91dbb
Author: James Glanville (james.n.glanville@gmail.com>
Date: Thu May 22 12:13:28 2014 +0100
```

```
added handbook
commit cf1945bfe2ab65d7c7fad71bd334f011fe0f679c
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu May 22 12:12:38 2014 +0100
     added pictures, and fixed report
commit 2b3fb1fa7d50fe98ad7f8588141b3d3315fd3f7c
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu May 22 11:11:20 2014 +0100
    fixed handbook formatting for compilation
commit 618cfd3c311580fdb87df2ef2e190ec1576721f8
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu May 22 10:43:49 2014 +0100
    added some operating steps
commit fbffecc58c31d3f0134e111f67b9e107517c3bed
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue May 20 05:49:09 2014 +0100
     moved install instructions to handbook
commit 3b4688e24a0eeff2abe04dc419f119ab75937a57
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue May 20 05:48:33 2014 +0100
     Updated compilation script
{\tt commit} \ d79154fd04b495797574b7da922594de38a830a5
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon May 12 15:06:21 2014 +0100
    improved report from feedback comments
commit c76163ba03a5387687effa5b3ee43cf089438768
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon May 12 14:28:26 2014 +0100
     added glossary
\verb|commit|| e89db8e494c88a2e6dee63557bc22b3d07df7af3|
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 14:10:19 2014 +0100
     added compilation script, a lot of spelling errors fixed and a few more citations added
commit a251931ab1762315b1421c3b589faf6221faad96
Author: James Glanville (james.n.glanville@gmail.com>
Date: Mon May 12 02:56:46 2014 +0100
     started tidying up equations
commit eef4a8468600c7bfc24dcb5605e7fdbd6d555516
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:38:02 2014 +0100
    added error testing sketch
commit 304eccce41f63b2bf7874fe243c9382fc79cede0
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:30:57 2014 +0100
     added sketch of errors
commit a613c2290fa402f886735841eedf68a3b67d0be3
Merge: 6d3572c 413baf2
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:10:22 2014 +0100
    Merge branch 'master' of github.com:JamesGlanville/solderingmachine
commit 6d3572cea29c17fd0f7add2b1bd1b51d0da1a29e
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:10:06 2014 +0100
     adding report sections
commit 413baf239f36214d61e3466aee61b93bad3cd797
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:09:29 2014 +0100
     add placeholder dial gauge photo
\verb|commit| ce4ff19cb3719f1cabce3f93bf2f33d76f32f741|\\
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon May 12 01:02:14 2014 +0100
     added terminology section
```

commit 2b606287cb2c345ea5f0a73f5f2bd3110190aeef

```
Author: James Glanville <james.n.glanville@gmail.com>Date: Sun May 11 23:34:39 2014 +0100
    microscope pics
commit 6b9476e21f310840f136928d2a7788ce0b658ccb
Author: James Glanville <james.n.glanville@gmail.com>
Date: Sun Apr 27 12:07:51 2014 +0100
     added microscope pictures for later use in report
commit feaa46bf5add809bbe41f1cd8ef11f675c2ced78
Author: James Glanville <james.n.glanville@gmail.com>Date: Sun Apr 27 12:07:38 2014 +0100
     various boards and part updates
commit 1f6a0fe7b88d24762fab9ebfacc2ddb848be56c5
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri Apr 4 02:55:34 2014 +0100
     added usb isolator stuff
commit c1d7159f5b995da61e6ad6ceaed02d56e41f4b9b
Merge: 2b94900 9cb561c
Netge: 2094900 9000010
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri Apr 4 02:42:43 2014 +0100
     Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit 2b9490062f7ec1a77effa032e1eb1e6ce5f708a3
Author: James Glanville (james.n.glanville@gmail.com>
Date: Fri Apr 4 02:42:13 2014 +0100
     added usbisolator schem
commit 9cb561cf713c94b6086a79830c16756d2c1ffc4b
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 09:08:35 2014 +0100
     added some speed stuff, need more
commit 39a06cd42f4d7dde3f992bbea79089458be64e4b
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 08:36:49 2014 +0100
     added render of machine
commit ca871987b4c4e934171a2da9ce1b135ee693479d
Merge: a2ed30a aecdaf6
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 08:19:46 2014 +0100
    Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
\verb|commit|| a 2 e d 3 0 a 0 d 17 c 2 f 7 c d 7 4 9 2 1 a a c a 8 f f 5 0 9 b c e 146 f d
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 08:19:28 2014 +0100
     added sample render
commit aecdaf619c5698b2cbedcfca2310b85efd06970f
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 08:04:31 2014 +0100
     Rewrote a lot of the decision making part of the report
commit 64e9964a4a49196e9696ccb34e4201480461e552
Author: James Glanville (james.n.glanville@gmail.com>
Date: Thu Apr 3 08:03:56 2014 +0100
     added old breakout picture
commit ba1fb672a9f7494deb1cc488ec78a30a6c4ca82c
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 08:00:31 2014 +0100
     annotated hc-05 breakout
commit 213c948e1befb752ca86b38a3b0fc897f9150d1b
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 07:55:47 2014 +0100
Date:
     added hc-05 breakout
commit 7914d034bc4462fe269a283aafa2ae2959b13bb5
Merge: b03a1bf 7fd0fe6
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 07:12:33 2014 +0100
     Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit b03a1bf40ca6a9156e7c719f71aa5ed686c8211d
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 07:12:29 2014 +0100
```

```
added soldering pictures
commit 7fd0fe6d1dbfbf937102e76e23691b2458226198
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 05:12:00 2014 +0100
     added some figures
commit 85ef3c34d211fac340e8363f88a43efbed0d1702
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 05:11:20 2014 +0100
     added example smd solder
commit 727d97c680497ac6f0ea81b4a4b6b7a8e2f05c86
Merge: 1995c10 0f5404a
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 05:04:19 2014 +0100
     {\tt Merge \ branch \ 'master' \ of \ https://github.com/JamesGlanville/soldering machine}
commit 1995c10c55fc432992f7e25e1d7d63b7479172d0
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 05:02:25 2014 +0100
     added example smd board
commit 0f5404a53d34854adae5df6f32065c38dfcef879
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 04:53:08 2014 +0100
    added i2c 1cd backpack schem
commit 0af3886c2b1c009f7fd3cdeedfceea9076dbe31b
Author: James Glanville (james.n.glanville@gmail.com>
Date: Thu Apr 3 04:45:27 2014 +0100
    redrew servo exceriser
commit 767ad3c8e54a992af75df8db46a9cc6539f3d338
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 04:15:29 2014 +0100
     added electronics folder
commit 212cf5ce064a38eac4a181e1c5b646e6e40f169a
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Apr 3 04:14:56 2014 +0100
    added lcd_backpack schem
commit 37d6f7fb0bf62e9ad469130d11cb6d975c1f55c0
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 03:37:58 2014 +0100
     exported all drawings as pdfs
commit 072841141b5ca9eebe0a47c296fa42e98c8e5e78
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 02:33:07 2014 +0100
     started exporting drawings
commit cc394e398bfef7f910a55c81e5fc8eedc7815aaf
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Apr 3 02:32:57 2014 +0100
     started exporting drawings
commit c465eb2c03f916c359abcbec1561a64029786ac4
Merge: ef57b4b 7ee3419
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Apr 2 23:24:01 2014 +0100
Date:
    Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit 7ee3419902dd162c178f0bbdc626980d09970457
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Apr 2 22:22:56 2014 +0100
     added sample part list to report with instructions
{\tt commit \ ef57b4b872d4856eed4ecb1708bf2d5c8312d34d}
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Apr 2 22:10:23 2014 +0100
commit 4f5018dacff4a62981d91909c9b9601c9a48c1a6
Merge: d3443a3 078eb29
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Apr 2 03:39:04 2014 +0100
     Merge branch 'master' of github.com: James Glanville/solderingmachine
```

```
commit d3443a329b814df63e86c67b972e11d74accac33
Author: James Glanville (james.n.glanville@gmail.com>
Date: Wed Apr 2 03:38:58 2014 +0100
    added milling settings
commit 078eb2937f3ac4105ae0566ceb84c7d7c582deed
Merge: 264199b 6ec9bdb
....ge. 2041990 6ec9bdb
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Apr 2 02:57:54 2014 +0100
     Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
commit 6ec9bdb145909a4640336e932c95728d5be47c50
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Apr 2 00:06:04 2014 +0100
     actually added gear photos
commit c937b8c52d916f70aeeaf111df390344a1c6d670
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Apr 2 00:05:50 2014 +0100
     added milled gear photos
commit 264199bd74c4cb89a0102dab460ce60e21a26fe7
Merge: 1352296 25e94a2
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Apr 1 23:54:10 2014 +0100
     Merge branch 'master' of https://github.com/JamesGlanville/solderingmachine
\verb|commit| 1352f9601abcbaebe65abb4e5cd6cc59548017d3|
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Apr 1 23:40:05 2014 +0100
     added xt60 panelmount and spindle updates
{\tt commit 9c2ed89c48e1be0418d418a591f5e7dfdf1e8c30}
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Apr 1 23:39:54 2014 +0100
     Added milling gcode
commit 25e94a244e91335a4034e2efaadfad5df91625fb
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Apr 1 12:30:18 2014 +0100
     updated report
commit 1a7247ea6d4350585adab43c8ce28b0980be43a3
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon Mar 31 20:44:52 2014 +0100
     added test board
commit 5af473526038cf38707fde57f5b6acada2420617
Author: James Glanville (james.n.glanville@gmail.com>
Date: Sat Mar 29 04:58:22 2014 +0000
     update for backup
commit b03f2fbe5228414ce4c10733fdfd839c95752be2
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Mar 27 07:32:48 2014 +0000
     added pcb2gcode improvements
commit 259ea119b03991260f2e3d9044925353466cb6df
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Mar 27 07:32:44 2014 +0000
     added pcb2gcode improvements
commit 0de7cea95e0a1e5799b0b486c7e35454e71f7387
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Mar 27 01:14:26 2014 +0000
     added hot air tool to report, as well as milling
commit 0b25339b404f890f1fa8c227de0df18592a31fa2
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Mar 26 23:40:44 2014 +0000
     added milling andhotair
commit a60209a842c2cbff807938777e72cc80d0ebf685
Merge: 48d04f9 d7c54e4
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Mar 26 02:26:30 2014 +0000
     Merge branch 'master' of github.com: JamesGlanville/solderingmachine
commit 48d04f9987a086ea6f2a8ff029ca999b55cc0db9
```

```
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Mar 26 02:26:21 2014 +0000
    remembered to track report resources
commit d7c54e4e5a834b1aa3498991676604d33ba61ff1
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Mar 26 02:16:08 2014 +0000
     started adding new improvements
commit 0915a81c481847fed21396b86eed042d216b8d98
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Mar 26 01:27:59 2014 +0000
     started double-sided board thoughts
commit ad9c52f55fa9de11ef6f2c7ce468a20278e7c6d1
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Mar 26 01:00:40 2014 +0000
     added section on hot air tool
commit 5e5aa922f6169703d9ec9c99e752722ba8775e5a
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Mar 24 05:04:42 2014 +0000
     added brief text about newer extruders
commit 136d43fd59ee8eac9eaa1692a2fef18563956856
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Mar 24 04:54:49 2014 +0000
     added zeroing
commit 560ceae18f4e5ac740c1104781b4d8d10957a7e2
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Mar 24 04:44:31 2014 +0000
commit bd54b731dbf1b178aafecaa7e80c6e5a0e64ad2f
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Mar 24 04:10:29 2014 +0000
     added example SMD sizes
commit 5a27fead53d157085e0dd23098bc6634fb8fc7b3
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon Mar 24 03:37:51 2014 +0000
     added servo tester stuff
commit 7244441d2854335681b8af89c23ce5e617f5663b
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon Mar 24 02:43:52 2014 +0000
     redid solder methods
commit ec74cb442cc665ea6ccaec55702b5132bfddc9b2
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon Mar 24 02:00:52 2014 +0000
     added bluetooth module details and usb serial stuff
commit 91d0b75b8d5105e181b609b9e2dd019ff96c9623
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Mar 11 02:18:25 2014 +0000
    lots of creo updates
commit 78b99e37022ec90172d33f83652f04e9852f9aaa
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri Feb 7 05:32:28 2014 +0000
    parts drawing
commit ad10d73a66347ca155ff32fb754a0b8c858a150d
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Feb 6 13:11:26 2014 +0000
     added drawing for meeting
commit 3f9ecf50705048f4fb529493a464ea41a931297e
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Feb 6 11:24:38 2014 +0000
commit 6889c5fd28da512f8e373a499b2822e64ba0551a
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Feb 6 01:59:23 2014 +0000
     Lots of creo updates
```

```
{\tt commit} \  \, {\tt f36dc4aedd5b1acf776d62424101660d98bf7ee2}
Author: James Glanville <james.n.glanville@gmail.com>Date: Sat Dec 21 14:04:21 2013 +0000
     new design
{\tt commit} \ 11 {\tt e46ab9fe18899f90091d495350d12311ef1d2b}
Author: James Glanville <james.n.glanville@gmail.com>Date: Fri Dec 6 03:18:37 2013 +0000
     added mounting z blocks
commit e293275a3b50f3734729fb3946270197da9b7c57
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri Dec 6 02:17:27 2013 +0000
     added dimensioned drawings
commit 1a92d773227dd1d32aa5eea4f738a52e85f69185
Author: James Glanville <james.n.glanville@gmail.com>
Date: Wed Nov 20 20:03:54 2013 +0000
     new design
commit 3863ca0f691c599abbbc39ae92a2541552aca6e4
Author: James Glanville (james.n.glanville@gmail.com>
Date: Wed Nov 13 15:36:19 2013 +0000
     drew z axis
commit db8a031faed4d26dc56d767c6a47c4428376eeca
Author: James Glanville (james.n.glanville@gmail.com>
Date: Tue Nov 12 19:04:57 2013 +0000
     added zip
commit 648e0bb36c235c3b0fc9f06beb646555b59f1da0
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Nov 12 17:23:13 2013 +0000
    added creo parts
commit 5eb41ef7fd0e03b9dafab3e72ca3dbbe1cbdfc3a
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Nov 12 04:11:20 2013 +0000
Date:
     added rules+pdf
commit aedaf89cafdc827e4cf2fa69869580058c834b53
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Nov 12 04:11:14 2013 +0000
commit c4975c9fa71d72f1f46a79c48d0dddfe251375cc
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Nov 12 03:58:46 2013 +0000
     added solder paste extrusion section
commit 966450451b30f18176a93f2584b4d3c14b8938d4
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Nov 12 03:11:12 2013 +0000
     added some new parts
commit 00d08af5d5c47f771799bf693ee3d5379cbdf927
Author: James Glanville <james.n.glanville@gmail.com>
Date: Fri Nov 1 13:57:06 2013 +0000
     improved corner.scad to reduce height
commit 40c1fc93e21f56e2e2cb881131f6b12d90484834
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Nov 4 16:45:11 2013 +0000
     added testing notes
commit e4582495e609ef54304441d01e1b62c521d32966
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Nov 4 16:40:09 2013 +0000
     added section on host software
commit ea528e57aff970bb4940372d6bfa913c05bda992
Merge: a0487f2 5d02d67
Author: James Glanville <james.n.glanville@gmail.com>
Date: Mon Nov 4 16:22:10 2013 +0000
     Merge branch 'master' of github.com:JamesGlanville/solderingmachine
commit a0487f238f614c7c9bc2bd01cae3bb28b988fad0
Author: James Glanville <james.n.glanville@gmail.com>Date: Mon Nov 4 16:21:58 2013 +0000
```

```
added section on heating solder paste
commit 5d02d679339fea788f9c524c9ecf487aaedb8998
Author: James Glanville <james.n.glanville@gmail.com>
Date: Thu Oct 24 20:03:00 2013 +0100
     added a bit more to the new axes design
commit 30c9604535660280b6d38be67deb8addef95d4f7
Author: James Glanville <james.n.glanville@gmail.com>Date: Thu Oct 24 14:48:29 2013 +0100
     added new design
commit 6dc26074ee9204b9d7c7d808612b26897c3579b5
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 22 16:57:07 2013 +0100
     tex->ndf and added line about host no
commit 73314f430c00afda991f0f91ca93c2d8ca4e80c8
Merge: 5eb1dd3 dfbd73d
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 22 16:56:42 2013 +0100
Date:
     Merge branch 'master' of github.com: JamesGlanville/solderingmachine
commit 5eb1dd374b9a21a3422756d3e1cc7c642e398596
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Oct 22 16:52:56 2013 +0100
     added isolation routing to report
\verb|commit|| \texttt{dfbd73d5ce2b40ad09d4ee8b3fbd29ddc2ec3754}|
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Oct 16 16:30:12 2013 +0100
    added design renders
commit 58537b08411651220cd0a6d16b6a5683380b1f9e
Author: James Glanville <james.n.glanville@gmail.com>Date: Wed Oct 16 16:19:43 2013 +0100
     added design sketch
commit bb2eeecc2ec3841b2c8ea8936952e26ccdf8e848
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 15 23:00:46 2013 +0100
     tidied up report.tex
commit fc3708a89d70b917f48943102fd79b574d35ce59
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Oct 15 23:00:42 2013 +0100
     tidied up report.tex
commit 677069188d5c4397c44d98691b1eb2c9a555692b
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 15 23:00:18 2013 +0100
     tidied up report.tex
commit 3077b319bc52e9c2ae9b2a5185e157c3be68eaac
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Oct 15 21:10:20 2013 +0100
     added .gitignore for latex
commit 736c48e145c3b2971ccb5778597896a2c191b241
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 15 20:48:55 2013 +0100
     added photos + requirements
commit ed8ab29ea90f96413ae85cb95efe12673eb7b667
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Oct 15 19:09:48 2013 +0100
    Added photos
commit cc219b5ae430d8bb9c8d63d77a3c5918aaa930fe
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Oct 15 17:53:30 2013 +0100
     Added driven corner stl
commit 0a278f4fea8670b4b886ca9b7fa5f14d42bd8dc4
Author: James Glanville <james.n.glanville@gmail.com>Date: Tue Oct 15 17:52:32 2013 +0100
     Added prototype part designs
commit 21e62bd672b965d0cc58bee7af8a667e70a3de97
Author: James Glanville <james.n.glanville@gmail.com>
```

```
Date: Tue Sep 10 22:45:32 2013 +0100

started adding info about vacuum pump

commit 2a54d57bae07dee31ac218bf5d75b6f36aabdc2d
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Jun 11 16:25:49 2013 +0100

added design subsections

commit 5e8ed99ada07b41216d7b6d73360ba16cb37341f
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Jun 11 15:35:54 2013 +0100

Started report

commit fc72ba47fe29fec48c7edab8aada2aa4b8a57510
Author: James Glanville <james.n.glanville@gmail.com>
Date: Tue Jun 11 06:47:46 2013 -0700

Initial commit
```