Test Form 11/4/15	Notes			The second second	A STATE OF THE PARTY OF THE PAR				o Micerii 8			
	Notes		-	The second	COLUMN TAXABLE DATE OF TAXABLE							
	Notes		The second second	1			T	1				
	Notes	0	And I		160 1	7.03	1-7-16		3 Setup 4 FAIR			
	Notes	Xmx	All His	ck New Letter	_	~ ~	Submitted					
			i ope	Pay lot	Approved Mtri		Date Part	Codes		uctions	Special Notes / Instructions	Specia
N. C.			inspection Record	First Bart								KOOTING.
Z		The same of the sa										POLITING:
?	(	_		Contraction of the								
	2	- / /		-								
	119											
_												
												ı e
							1		1			
												•
						-						
	K					8	'n	Z	アプス	الله عليا	4	lalic
Scrap Code	Sc		Notes		Down Time Code	Down Time Do	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
Scrap		Distriction was opposed.	MANAGEMENT PROPERTY.	· · · · · · · · · · · · · · · · · · ·	The second second second			ALC: NO.				
	144	Thru- put/8hrs	18	Pcs./Hr	3 MIN	Cycle Time	30 MIN	Setup Hrs.	H2	_	Mach. No.	
South Property of the Party	日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	おから 大学士 かんかっとう	をなるできるという		Sydemotral County							
,									Do not require traceability.	Do not requi	L	Caps/Plugs
							t Number."	ed by "Lo	Located on the bag followed by "Lot Number."	Located on t		Snap Rings
						box label.	late on the	per and d	Use their work order number and date on the box label.	Use their wo		Flare Tubes
						tter "M."	with the le	, starting	Located on the spool label, starting with the letter "M."	Located on t		Copper Tubing
						ord "heat."	bove the wo	directly al	Located on the box label, directly above the word "heat."	ocated on th		Brazing Rings
			BRZ00			quantity.	l under box	box labe	Six digit no. located on the box label under box quantity.	Six digit no. l		Flare Nuts
			CASC-11				ers	ity Numb	Distinguishing Traceablity Numbers	Distinguis		
	0.77	V 14 0	ASC-11	,					5	25	Qty	Order Qty
	4 9	200	6644			devices, LLC	d		371	396371	No.	Order No.
	Heat Lot/Traceability	Heat Lot/	Component(s)	Com		ontrol	000		11-7	ASC-11-7	No.	Part No.