BRAZING PRO	special	Specia	ROUTING:		4/22/11	Date		Caps/Plugs	Flare Tubes Snap Rings	Copper Tubing	Flare Nuts Brazing Rings		Order Qty	Order No.	Part No.
BRAZING PRODUCTION RECORD	Special Notes / Instructions				40	Emp. Name	Mach. No.	i i		1,2,000			Qty	r No.	No.
	2 2 3 4 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	ctions			Banco	Prod Hrs.		Do not requ	Use their wo	Located on	Six digit no. Located on	Distingu		40.	S404
	Maintenance Tooling Setup FAIR Training Meeting	Down Time			10	Total Pcs.		Do not require traceability.	ork order nun	the spool lab	located on the	ishing Tracea	10	404591	S404-8-3/16
	Date Part Submitted	Codes			10	Cum. Total	Setup Hrs.	·y.	Use their work order number and date on the box label Located on the bag followed by "Lot Number."	Located on the spool label, starting with the letter "M."	Six digit no. located on the box label under box quantity. Located on the box label, directly above the word "heat."	Distinguishing Traceablity Numbers		1	
	art Time Of Day					Down Time	Cycle Time		the box label.	the letter "M."	er box quantity. he word "heat."			a control devices, LLC	
	Approved Yes / No				,	Down Time Code								LLC	
THE STATE OF THE PROPERTY.	Mtrl Rev Letter					Notes	Pcs./Hr						SF404-8-3/16	Component(s)	3
	er Inspection Record										BRZ23 CP13	CUTU-1-1/2			
			33				Thru- put/8hrs		T					z	Heat Lot/
	Notes		0			Scrap								No(s)	Heat Lot/Traceability
Test Form 11/1/15						Scrap Code									