Part No.	S7-4	S7-4-9-24-C			ontrol			Com	onent(s)	Heat L	Heat Lot/Traceability	
Order No.	39	392123		THE STATE OF THE S	devices, LLC	LLC		com	Component(s)		No(s)	
Order Qty		1							7-4-9	39	39/126	
	Distingu	Distinguishing Traceablity Numbers	lity Numb	ers				CUT	CUTU-0-1/4	_	11/14	
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box label	under bo	x quantity.				BRZ09	29	h10 16e	
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ab	ove the w	ord "heat."			п п	BRZ05	<i>a</i>)	267376	
04	Located on	Located on the spool label, starting with the letter "M."	, starting v	with the le	etter "M."			CUT	CUTU-0-7/8		MA	
	Use their w	Use their work order number and date on the box label	per and da	ate on the	box label.				CP15			
,	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	Number.	=							
4	Do not requ	Do not require traceability.	•									
And the second second second second						The second second						
Mach. No.	2		Setup Hrs.	23	Cycle Time	38		Pcs./Hr		Thru- put/8hrs		
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes		Scrap	Scrap Code
9-3-8-6		/								\	0	
		ŧ							Condy			
								(0			
		100										
											5	
æ												
										->	7	
										V	S	
											>	
											7	
NOO IIWO.												
Special Notes / Instructions	ctions	Down Time C	Codes				F	First Part Ins	Inspection Record			
		 Maintenance Tooling 		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl F	Rev Letter	Inspector		Notes	
				23-15	12/2	YES	1	4	¥	Q. 450	A CONTRACTOR OF THE PARTY OF TH	100 mg
					i	,		1				
		0	L									