Part No.		1104 A DIAW											
Order No.		1104-A-BLNK 401394		Component Heat Lot #			19377/.12.1			CE 2	contr device	ol es uc	
						19					001101	00, 000	
Order Qty		125		W/O # from Box OPERATION 1				AND WEST		- Tubu	B. 12 / 21 / 2		
Mach No.	Data	Frank Name	Dan d Han			Down	Down time			THRU	-PUT/8HRS	104 Scrap	
IVIACII IVO.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	code		Notes		Scrap	Code	
H1	9-29-16	HVD-JS	8	109		0					1	11	
	3-1-16	Pb	5	71	180	0					Ó		
Setup Hrs.	ļ								Johost				
1.5									HVD				
Cycle Time							1		1				
3 MIN 49							1	1_0	1 no	/ 1	Ø		
SEC								46	0.0	011			
Pcs/Hr							U	4	13	6.	/		
13										1			
ROUTING:					_								
WEST AND SEE		Mark Color		OPERATIO	N 2					THRU	PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down	Down time		Notes		Scrap	Scrap	
						time	code				Эсгар	Code	
Setup Hrs.		-			-	<u> </u>	<u> </u>	-					
								-					
Cycle Time													
Pcs/Hr					_								
		_			_								
ROUTING:			V										
				OPERATION 3			E PER LA		The Paris	THRU-PUT/8HRS			
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes			Scrap	Scrap Code	
											а		
Setup Hrs.												- "	
Coole Ti													
Cycle Time													
H	10												
Pcs/Hr								*					
1 03/111		+											
-				III									
ROUTING:								 					
	structions	Down Ti	me Codes			F	irst Part In	spection	Record				
The state of the s		1 Maintenance		Date Part	Date Part Time Of Day Approved			irst Part Inspection Record Mtrl Rev Inspects					
		2 Tooling 3 Setup		Submitted	Time Of Day	Yes / No	Check	Letter	Inspector	Notes			
		3 Setup 4 FAIR		229/16	1:30/	4/2)	~	BB	H	(3)	Maca		
			5 Training		,	r .		TO DE	-0				
SECONDARY	PRODUCTIO	6 Meeting			DACE								
		ILLOOND			PAGE 1						Test Form 1	0/15/15	