Part No.		P1012001-10		Component		P1212001-10			control devices, LLC			
Order No.		4010923		Heat Lot #								
Ord	er Qty	2	25	W/O #	from Box							
				OPERATION 1				700	THRU-PUT/8HRS			
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
HARDING COBRA	2125116	70 PBA	5,5	28	28	2.5	3	7				26
Setup Hrs.	01 010 €		-1/		01			3				
										<u> </u>		
				- Ic-				-	n/A	7		
Cycle Time								/	160			
Cycle Time									OP			
										A 1	0	
Dec/Us									7	11	4	
Pcs/Hr									-	1		
									- (2	A	
DOUTING:												
ROUTING:	THE CHARLES	Secretary and the		OPERATION 2			ST W. GENISO	THRU-PUT/8HRS				
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
				***					VALUE AND			-
Setup Hrs.						Tr.					10	
Cycle Time												
Pcs/Hr										,		
									_			
ROUTING:												
经验证证	NE 集包 表现的			OPERATIO	N 3					THRU-	PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes		Scrap	Scrap Code	
Setup Hrs.			- Hirth - E - H									
			107400	-								
Cycle Time										-		
						_						
Pcs/Hr			-					7				
	_											
ROUTING:												
Notes / I	nstructions	Down T	ime Codes			F	irst Part In	spection	Record			
		 Maintenance Tooling 		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector	pector Notes		
1		3 Setup		2-25-16	3:500	V	1		JC 2nd 00			
		4 FAIR 5 Training						B				
		6 Meeting										
CCONDADA	PRODUCTIO	N DECODD			DACE			THE RESERVE OF THE PERSON NAMED IN				SECOND CONTRACTOR